
Document Type: Index Field: Project Name:

EA-Administrative Record Draft EA Wilson Dam Bridge Deck Refurbishment EA 2019-20

Project Number:

WILSON DAM BRIDGE DECK REFURBISHMENT DRAFT ENVIRONMENTAL ASSESSMENT

Lauderdale and Colbert Counties, Alabama



Prepared by: TENNESSEE VALLEY AUTHORITY Muscle Shoals, Alabama

April 2019

For Information, contact: Elizabeth Smith NEPA Compliance Tennessee Valley Authority 400 West Summit Hill Drive, WT 11B Knoxville, Tennessee 37902-1499 Phone: 865-632-3053 Email: esmith14@tva.gov This page intentionally left blank

Table of Contents

CHAPT	ER 1 – PURPOSE AND NEED FOR ACTION	1
1.3 1.4 1.5 1.6 1.7	Introduction and Background Purpose and Need Decision to Be Made Related Environmental Reviews Scope of the Environmental Assessment and Summary of the Proposed Action Public and Agency Involvement Necessary Permits or Licenses	5 5 6 7
CHAPT	ER 2 – ALTERNATIVES	8
2.2 2.3 2.4 2.5	Alternatives Development Process	9 10 11 11
		40
	CONSEQUENCES	
	Air Quality	
3.1		
	.2 Environmental Consequences	
	3.1.2.1 Alternative A – No Action Alternative	
	B.1.2.2 Alternative E – Repair Scheme D	
	Climate	
3.2		
	.2 Environmental Consequences	
-	3.2.2.1 Alternative A – No Action Alternative	
-	3.2.2.2 Alternative E – Repair Scheme D	
	Surface Water	
3.3		
	.2 Environmental Consequences	
	3.3.2.1 Alternative A – No Action Alternative	
	3.3.2.2 Alternative E – Repair Scheme D	
	Wildlife	
	.1 Affected Environment	
	.2 Environmental Consequences	
	3.4.2.1 Alternative A – No Action Alternative	
	3.4.2.2 Alternative E – Repair Scheme D	
	Threatened and Endangered Species	
3.5		
3.5		
-	3.5.2.1 Alternative A – No Action Alternative	
	3.5.2.2 Alternative E – Repair Scheme D	
	Solid and Hazardous Waste	
3.6	.1 Affected Environment	19

	3.6.2 Environmental Consequences	20
	3.6.2.1 Alternative A – No Action Alternative	20
	3.6.2.2 Alternative E – Repair Scheme D	20
	3.7 Visual Resources	
	3.7.1 Affected Environment	
	3.7.2 Environmental Consequences	
	3.7.2.1 Alternative A – No Action Alternative	
	3.7.2.2 Alternative E – Repair Scheme D	
	3.8 Cultural and Historic Resources	
	3.8.1 Affected Environment	
	3.8.2 Environmental Consequences	
	3.8.2.1 Alternative A – No Action Alternative	
	3.8.2.2 Alternative E – Repair Scheme D	
	3.9 Recreation	
	3.9.1 Affected Environment	
	3.9.2 Environmental Consequences	
	3.9.2.1 Alternative A – No Action Alternative	
	3.9.2.2 Alternative E – Repair Scheme D	
	3.10 Transportation	
	3.10.1 Affected Environment	
	3.10.2 Environmental Consequences	
	3.10.2.1 Alternative A – No Action Alternative	
	3.10.2.2 Alternative E – Repair Scheme D	
	3.11 Noise	
	3.11.1 Affected Environment	
	3.11.2 Environmental Consequences	
	3.11.2.1 Alternative A – No Action Alternative	
	3.11.2.2 Alternative E – Repair Scheme D	
	3.12 Socioeconomics and Environmental Justice	
	3.12.1 Affected Environment	
	3.12.2 Environmental Consequences	
	3.12.2.1 Alternative A – No Action Alternative	
	3.12.2.2 Alternative E – Repair Scheme D	
	3.13 Unavoidable Adverse Impacts	
	3.14 Relationship of Short-Term Uses to Long-Term Productivity	
	3.15 Irreversible and Irretrievable Commitments of Resources	36
	3.16 Cumulative Effects	37
С	HAPTER 4 – LIST OF PREPARERS	39
	4.1 NEPA Project Management	39
	4.2 Other Contributors	
C	HAPTER 5 – ENVIRONMENTAL ASSESSMENT RECIPIENTS	
U		
	5.1 Federal Agencies	41
	5.2 Federally Recognized Tribes	
	5.3 State Agencies	
С	HAPTER 6 – LITERATURE CITED	43

List of Appendices

- Appendix A Wilson Dam Bridge Deck Refurbishment Design
- Appendix B Expansion Joint Installation Details
- Appendix C Wilson Dam Bridge Deck Refurbishment Study
- Appendix D Scoping Study Alternatives Scoring Appendix E Wilson Dam Traffic Volume Data
- Appendix F Consultation Correspondence

List of Tables

Table 2-1.	Summary and Comparison of Alternatives by Resource Area	9
Table 3-1.	Federally Listed Species	18
Table 3-2.	Population and Income	35
Table 3-3.	Cumulative Impacts	38

List of Figures

Figure 1-1.	Project Location	.4
Figure 3-1.	Recreation Areas	27
Figure 3-2.	Road Network Overview	30

This page intentionally left blank

Acronyms and Abbreviations

ADEM AL ALDOT APE BMP CAA CBMPP CEQ CFR CO ₂ CWA	Alabama Department of Environmental Management Alabama Alabama Department of Transportation Area of Potential Effect Best Management Practices Clean Air Act Construction Best Management Practices Plan Council on Environmental Quality Code of Federal Regulations Carbon Dioxide Clean Water Act
dB	Decibel
dBA	A-Weighted Decibel
EA EIS	Environmental Assessment
EO	Environmental Impact Statement Executive Order
EPA	U.S. Environmental Protection Agency
EPCRA	Emergency Planning and Community Right to Know Act
ESA	Endangered Species Act of 1973
FHWA	Federal Highway Administration
GHG	Greenhouse Gas
HUD	U.S. Department of Housing and Urban Development
LBP	Lead-Based Paint
NAAQS	National Ambient Air Quality Standards
NEPA	National Environmental Policy Act
NHL	National Historic Landmark
NHPA NOx	National Historic Preservation Act Nitrous Oxide
NPDES	National Pollutant Discharge Elimination System
NPS	U.S. National Park Service
NRHP	National Register of Historic Places
NWI	National Wetland Inventory
pcf	Per Cubic Foot
RCRA	Resource Conservation and Recovery Act
SHPO	State Historic Preservation Officer
SO ₂	Sulfur Dioxide
TVA	Tennessee Valley Authority
USACE	U.S. Army Corps of Engineers
USC	United States Code
USEPA USFWS	U.S. Environmental Protection Agency U.S. Fish and Wildlife Service

This page intentionally left blank

CHAPTER 1 – PURPOSE AND NEED FOR ACTION

1.1 Introduction and Background

The Tennessee Valley Authority (TVA) proposes to refurbish and repair the Wilson Dam Bridge deck and other concrete surfaces, reseal the fly-over epoxy overlay, remove and replace the fly-over expansion joints, and repaint the fly-over handrails (see Figure 1-1). The repairs would be limited to the concrete arches on the dam above the spring line, bridge deck, fly-over, curbs, parapets, and sidewalks between the control building and the north end of the fly-over. The dam below the spring line, the equipment operating deck on the upstream side of the bridge, and the lock are outside the project scope.

Construction of Wilson Dam began in 1918, and it was dedicated in 1926. At the time that the dam was dedicated, a primary roadway crossing the Tennessee River over the top of the dam, as well as the original lock, was opened between Muscle Shoals and Florence, Alabama. In May 1933, TVA acquired the dam from the U.S. Army Corps of Engineers (USACE). TVA owns the Wilson Dam while the USACE Nashville District operates the Wilson Dam locks for TVA. Both the dam and bridge are listed in the National Register of Historic Places (NRHP) as a National Historic Landmark (NHL).

The original wearing surface of the bridge deck was brick pavers, which were removed in the late 1950s, and replaced with the current concrete deck and the steel superstructure flyover was constructed over the lock. The arches appear to be constructed of mass unreinforced concrete. The bridge deck also appears to be unreinforced concrete.

Over the years, the downstream face where the concrete arches interface with the parapet have developed widespread spalls (areas where chips, splinters or fragments are broken off) with efflorescence (whitish powdery substance due to migration of mineral rich water through the porous concrete where it evaporates) and visible water movement. In addition, the sidewalk, curb, and deck have developed widespread cracking.

The bridge fly-over that crosses over the locks adjacent to the dam consists of 30 steel spans. The epoxy overlay with a flint aggregate wearing surface on the fly-over was installed in the 1980s but is showing signs of wear and tear with areas where the epoxy overlay has been worn down or completely disappeared. In addition, expansion joints on the fly-over installed in the 1950s are deteriorating and the handrails need repainting.




Deterioration of Parapet and Curb



Bridge Deck Cracks



Bridge Deck Cracks



Concrete Arch Showing Spalling and Efflorescence



Failing Epoxy Overlay and Deteriorating Bridge Joint on Fly-over




Figure 1-1. Project Location

1.2 Purpose and Need

The purpose of the proposed action is to refurbish and repair the Wilson Dam Bridge deck and other concrete surfaces, such as the arch faces, and to stop the flow of water through the deck and parapets. The bridge deck and sidewalk are cracking due to water entering the space (void layer) between the original arch concrete and the newer concrete deck. The concrete arches exhibit a large amount of concrete spall near the top surface due to water passing through the existing deck and deteriorating the arch face. Due to age and wear and tear, the epoxy overlay, expansion joints, and handrails on the fly-over section of the bridge are deteriorating.

If the bridge is left unrepaired, deterioration of keyways, arches, fly-over overlay, and expansion joints may worsen over time, which would increase the potential for public safety risks including falling debris.

1.3 Decision to Be Made

TVA must decide whether to refurbish the Wilson Dam Bridge deck, fly-over, and other surfaces. TVA's decision would consider factors such as potential environmental impacts, economics, availability of resources, and TVA's long-term goals. This Environmental Assessment (EA) has been prepared to support the decision-making process and determine whether an Environmental Impact Statement (EIS) should be prepared.

1.4 Related Environmental Reviews

The following environmental reviews have been prepared for actions near the project location:

- *Muscle Shoals Power Service Shop Warehouse EA (TVA 2019a).* The EA evaluated the proposed construction of a new warehouse to support the relocation of spare turbine rotors and other generating components to a central location.
- *Muscle Shoals Outdoor Education and Recreation Area Improvements EA (TVA 2015).* The EA addressed proposed improvements to the trail/recreation system located north of Reservation Road on the Muscle Shoals Reservation, including three trailheads and the Reservation Road Trail.
- Muscle Shoals Reservation Redevelopment Final EIS (TVA 2011). The EIS documented the potential environmental effects of the proposed sale of 1,400 acres of land on the Reservation in Colbert County, Alabama. After the final EIS was published, TVA worked with the local community to develop a comprehensive master plan to guide development of the land. During this process, TVA identified 400 acres of land that should be retained by TVA due to ongoing TVA business needs and limited development opportunities due to prior industrial operations. The TVA Board of Directors subsequently approved the disposal of approximately 1,000 of the 1,400 acres analyzed in the final EIS.
- Wilson Dam Bascule Bridge Replacement EA (USACE 2008). The EA addressed a proposed construction of a fixed bridge over the lower end of the auxiliary lock at Wilson Dam to provide safe, reliable access to the main lock.
- *River Heritage Hotel EA (TVA 2002).* The EA addressed a 12-acre permanent easement for the proposed construction of a 150 to 200-room hotel adjacent to

the Wilson Dam. The TVA Board of Directors approved the easement and the hotel was constructed in 2005.

- *Muscle Shoals/Wilson Dam Reservation Land Use Plan EA (TVA 1996).* TVA prepared this EA to evaluate land on the Reservation needed for TVA program uses and to identify areas that would be made available for external uses.
- Patton Island Bridge and Approaches Crossing the Tennessee River and Connecting the Cities of Florence and Muscle Shoals EIS (FHWA 1991). The Federal Highway Administration prepared this EIS to consider the proposed construction of a multi-lane highway bridge over the Tennessee River downstream of the Wilson Dam. The Patton Island Bridge was opened in 2002 and was renamed the Singing River Bridge in 2010.

The description of the affected environment and the assessment of impacts contained in the documents listed above were used in support of the analyses of environmental resources in Chapter 3.

1.5 Scope of the Environmental Assessment and Summary of the Proposed Action

TVA prepared this EA to comply with the National Environmental Policy Act (NEPA), associated regulations promulgated by the Council on Environmental Quality (CEQ; 40 CFR Parts 15000-1508), and TVA's procedures for implementing NEPA. TVA considered the possible environmental effects of the proposed action and determined that the resources listed below are potentially impacted by the alternatives considered.

- Air Quality
- Climate
- Surface Water
- Wildlife
- Threatened and Endangered
 Species
- Solid and Hazardous Waste

- Visual Resources
- Cultural and Historic Resources
- Recreation
- Transportation
- Noise
- Socioeconomics and Environmental Justice

Given the nature of the project, the following resources are not found in the study area or would not be impacted by any of the project alternatives. These include:

Aquatic Resources – The TVA Natural Heritage Database indicated that there are
federally listed aquatic animals and several state-listed mussels within 10-miles of
Wilson Dam. In addition, the tailwater below Wilson Dam has been designated
nonessential experimental population status by the U.S. Fish and Wildlife Service
(USFWS) for 13 federally listed mussels and one federally listed snail. However, no
work would be performed in the river. Completion of the repairs on the arch faces
would require a work platform of some type to be placed along the bridge by the
Contractor. The Contractor would be required to install appropriate netting to
prevent debris from falling into the water. The Contractor would also be required to
install measures to prevent waste materials such as concrete from washing into
storm drains. Containment measures would be required during replacement fly-over
expansion joint activities and preparation of the fly-over handrails for repainting.

- Dam Safety The bridge refurbishment activities would not have an impact on the water barrier structures or operation of the dam.
- *Navigation* The bridge refurbishment activities would not have an impact on the lock or commercial navigation.
- Additional Resource Areas Potential effects related to land use, vegetation, floodplains, managed areas, prime farmland, aquatic species, and wetlands were considered. However, due to the nature of the action and project footprint, potential effects were found to be absent, and these resources have not been brought forward for further evaluation.

TVA's action would satisfy the requirements of Executive Order (EO) 11988 (Floodplains Management), EO 11990 (Protection of Wetlands), EO 12898 (Environmental Justice), EO 13751 (Invasive Species); and applicable laws including the National Historic Preservation Act (NHPA), Endangered Species Act (ESA), Clean Water Act (CWA), Clean Air Act, and Resource Conservation and Recovery Act (RCRA).

1.6 Public and Agency Involvement

TVA is issuing this draft EA for public review and comment. Its availability was announced in a TVA news release and in an advertisement in the *Florence Times Daily* newspaper. The draft EA was also posted on TVA's website. Notifications of its availability were sent by mail or email to local, state, and federal agencies and to individuals and organizations that had previously expressed an interest in the Wilson Dam or the Muscle Shoals Reservation. TVA has consulted with the Alabama State Historic Preservation Office (SHPO), and federally recognized tribes under Section 106 of the NHPA.

1.7 Necessary Permits or Licenses

The proposed action would be subject to the Alabama Department of Environmental Management (ADEM) General National Pollutant Discharge Elimination System (NPDES) Permit for stormwater discharge associated with construction activity. This permit requires that a Construction Best Management Practices Plan (CBMPP) be implemented. Stormwater discharges would need to comply with ADEM NPDES permit (ALG 36-0012) for the Wilson Dam.

CHAPTER 2 – ALTERNATIVES

2.1 Alternatives Development Process

A total of six alternatives were identified during initial project scoping (see Appendix C) including:

- Alternative A No Action. Under the No Action Alternative, TVA would not refurbish the Wilson Bridge deck or other concrete surfaces, reseal the fly-over epoxy overlay, remove and replace the fly-over expansion joints, or repaint the fly-over handrails.
- Alternative B Repair Scheme A. This alternative would include the following: stabilize and repair the bridge deck by pressure injecting urethane polymer or an equivalent product into the space or void between the arch concrete and the existing concrete overlay. It would repair existing deck cracks by epoxy injection. This alternative also includes performing spot grinding of the deck to improve rideability and patch deteriorated concrete arch faces. Alternative B is the least-cost alternative to meet the minimum needs of the proposed bridge refurbishment.
- Alternative C Repair Scheme B. This alternative would perform the same repairs as Alternative B but would also include the patching of deteriorated concrete surfaces on the rails and sidewalks.
- Alternative D Repair Scheme C. This alternative would include the following: stabilize and repair the bridge deck and construct a new latex modified concrete overlay; and patch deteriorated surfaces of arch face, rails, and sidewalks.
- Alternative E Repair Scheme D. This alternative would include the following: remove and replace existing bridge deck; patch deteriorated surfaces of arches, rails, and sidewalks; reseal the fly-over epoxy overlay; remove and replace the flyover expansion joints; and recoat/repaint the fly-over handrails. Alternative E is the highest cost alternative.
- Alternative F Hybrid Repair Scheme. This alternative would combine Repair Schemes A through D on a span-by-span basis. This alternative may provide cost saving opportunities; however, it could result in a longer schedule for completion of the bridge refurbishment as additional assessment of each bridge span would be needed to assign a repair scheme to each span.

TVA has determined that from the standpoint of NEPA, there are two alternatives that would be carried forward in the EA: Alternative A – No Action Alternative; and Alternative E – Repair Scheme D. The environmental impacts of Alternative A and Alternative E are analyzed in detail in this EA and are summarized in Table 2-1. These summaries are derived from the information and analyses provided in the Affected Environment and Environmental Consequences sections of each resource in Chapter 3.

-	,	,
Issue Area	Alternative A – No Action	Alternative E – Repair Scheme D
Air Quality	No impact.	Temporary, minor increase in local air emissions due to construction activities.
Climate	No impact.	No impact.
Surface Water	Minor impact.	Temporary, minor adverse impacts during removal of bridge deck, deteriorated concrete from arch faces, fly- over expansion joints, and preparation of fly-over handrails.
Wildlife	No impact.	No impact.
Threatened and Endangered Species	No impact.	No impact.
Solid and Hazardous Waste	No impact.	Minor impact due to construction.
Visual	Minor impact.	Temporary, minor adverse impact but long-term visual benefit.
Cultural and Historic Resources	Minor impact.	No adverse effect.
Recreation	No impact.	Minor, short-term impacts on recreation due to temporary construction detour. No long-term impacts.
Transportation	Minor impact.	Temporary, short-term impacts to vehicle and pedestrian traffic due to bridge closure during construction. Long-term beneficial impacts as bridge and fly-over can accommodate current and forecasted traffic.
Noise	No impact.	Temporary, minor impact due to construction noise. No long-term impact.
Socioeconomic and Environmental Justice	No impact.	Short-term, minor, beneficial increases in employment, payroll, and tax payments during construction. Beneficial impacts would extend to environmental justice if workers are hired from minority or low-income populations.

Table 2-1. Summary and Comparison of Alternatives by Resource Area

2.2 Alternative A – No Action Alternative

Under the No Action Alternative, TVA would not refurbish or repair the Wilson Dam Bridge deck and other concrete surfaces, reseal the fly-over epoxy overlay, remove and replace the fly-over expansion joints, or recoat/repaint the fly-over handrails. The spalling, efflorescence, and cracking would not be addressed, and the deterioration of keyways and arches may worsen over time, which would increase the potential for public safety risks associated with falling debris. The epoxy overlay, expansion joints, and handrails would not be resealed, replaced, or repainted which could lead to worsening public safety conditions on the fly-over. Additionally, deterioration of the bridge could lead to additional water infiltration affecting the integrity of the bridge and dam below.

2.3 Alternative E – Repair Scheme D

As described above, this alternative would include the following: remove and replace existing bridge deck; and patch deteriorated surfaces of arches, rails, and sidewalks (see Appendix A). The repairs would be limited to the concrete arches on the dam above the spring line, bridge deck, fly-over, curbs, parapets, and sidewalks between the control building and the north end of the fly-over (see Figure 1). The dam below the spring line, the equipment operating deck on the upstream side of the bridge, and the lock are outside the project scope. The project area includes an approximately 1.6-acre staging area located within the lock operations area. The proposed staging area is an existing gravel and fenced staging area used as part of the Wilson Dam Bascule Bridge Replacement project.

The existing concrete bridge deck and deteriorated material between the arch faces and existing concrete bridge deck would be removed. The method to remove concrete would be hydrodemolition which utilizes high-pressure water to remove the concrete. A skid steer loader would be used to put concrete debris in a dump truck. A new reinforced concrete bridge deck would be constructed, and joints would be sealed. Deteriorated concrete arch faces, bridge rails, and sidewalks would be patched. Construction traffic would include private vehicles for 35 workers along with large delivery or construction trucks including dump trucks and concrete mixer trucks. Project construction would occur over an estimated 8-month period.

During refurbishment activities, existing curbs, deck drain plates, and light fixtures set into the guard rails of the bridge would be removed, retained, and reinstalled as a part of the project. Repair of any damaged lights is not a part of this project, however, the damaged lights or those that are missing globes would be reinstalled for potential future repair or restoration. In places where curbs are missing, in-kind replacements would be installed. Additionally, any concrete or paint applied textural finishes would be matched to Wilson Dam's current appearance.

In addition, the epoxy overlay with a flint aggregate wearing surface on the fly-over would be replaced. As part of the process, a small, surface preparation milling machine would scarify the surface, the surface would be pressure washed, and then the epoxy would be applied using a trailer mounted mixer/applicator. This epoxy resurfacing would take approximately two weeks with the most time involving surface preparation activities. To replace the six expansion joints, a cut would be made in the concrete a few inches behind the joint and then the joint would be chipped out with small pneumatic hammers. A replacement joint would be set from the bottom and concrete would be poured around the new joint (see Appendix B). Each expansion joints would take approximately a week to replace. To remove the paint/coating on the handrails, an abrasive pressure wash would be used. Operations to remove the expansion joints and prepare the handrails would be fully contained to avoid or minimize releases of materials.



Wilson Dam Bridge Fly-over

2.4 Alternatives Eliminated From Further Discussion

TVA carefully considered a range of rehabilitation options for repairing the Wilson Dam Bridge, fly-over, and arches. The alternatives identified above were evaluated based on a set of criteria including: longevity of the repair, efficiency, safety, design, impacts to the public, and environmental impacts (see Appendix D). Apart from the No Action Alternative, all the alternatives partially meet the project purpose and need. TVA determined, however, that the urethane polymer injection proposed under Alternatives B, C, and D may not entirely stabilize the deck of the bridge. Urethane stabilization is also a newer technology, and the longevity of the repair is uncertain. Alternatives D and E scored equally as the highest for safety concerns, and all action alternatives scored equally for environmental concerns. Based on the presumed duration of road closure, Alternative E scored best for limiting inconvenience to the public and extending estimated service life for the bridge. Therefore, Alternatives B, C, D, and F have been eliminated from further consideration.

2.5 TVA's Preferred Alternative

Alternative E is the alternative that has the best potential to fully meet TVA's asset management and structural preservation goals. Alternative E scored highest for achieving the purpose and need of the project and the longevity of the repair.

2.6 Summary of Mitigation Measures

Mitigation measures identified in Chapter 3 to avoid, minimize, or reduce adverse impacts to the environment are summarized below. TVA's analysis of Alternative E includes mitigation, as required, to reduce or avoid, minimize, or reduce adverse effects. Project-specific best management practices (BMPs) are also identified.

- *Cultural Resources.* As specified in the 100% Wilson Dam Bridge Deck Refurbishment Design (see Appendix A), TVA and the contractor would ensure that the character-defining features of the bridge would be retained in accordance with *Secretary of the Interior's Standards for Rehabilitation.*
- Surface Water. TVA would implement BMPs and control measures in a CBMPP to prevent the discharge or loss of potential pollutants into the Wilson or Pickwick Reservoirs and to contain and properly dispose of all wastes, accidental spills, surface runoff, or other potential contaminants. TVA would comply with applicable environmental laws and regulations, including ADEM NPDES permit (ALG 36-0012) for Wilson Dam and ADEM's General Permit for Construction Activities.

This page intentionally left blank

CHAPTER 3 – AFFECTED ENVIRONMENT AND ENVIRONMENTAL CONSEQUENCES

3.1 Air Quality

3.1.1 Affected Environment

The Clean Air Act regulates the emission of air pollutants and, through its implementing regulations, establishes National Ambient Air Quality Standards (NAAQS) for several "criteria" pollutants that are designed to protect the public health and welfare with an ample margin of safety. The criteria pollutants are ozone, particulate matter, carbon monoxide (CO), nitrous oxides (NO_x), sulfur dioxide (SO₂), and lead.

Specified geographic areas are designated as attainment, nonattainment or unclassifiable for specific NAAQS. Areas with ambient concentrations of criteria pollutants exceeding the NAAQS are designated as nonattainment areas and new emissions sources in or near these areas are subject to more stringent air permitting requirements.

Colbert and Lauderdale counties are in attainment with applicable NAAQS (USEPA 2016) and ambient air quality standards referenced in the ADEM Administrative Code, Title 335-3 (ADEM Administrative Code 2016).

The proposed project would be subject to both federal and state regulations that impose permitting requirements and specific standards for expected air emissions. These include ADEM Administrative Code, 335-3-4-.02 Fugitive Dust and Fugitive Emissions.

3.1.2 Environmental Consequences

3.1.2.1 Alternative A – No Action Alternative

Under the No Action Alternative, TVA would not refurbish the Wilson Bridge deck and other concrete surfaces, reseal the fly-over epoxy overlay, remove and replace the fly-over expansion joints, or repaint the fly-over handrails. There would be no changes to the existing air quality conditions and no new impacts on air quality.

3.1.2.2 Alternative E – Repair Scheme D

Transient air pollutant emissions would occur during the 8-month construction phase. Construction-related air quality impacts would primarily result from the staging of construction vehicles, equipment, and supplies and the operation of construction vehicles and equipment and worker personnel vehicles. The daily workforce during construction is expected to be 35 workers. During construction, approximately 3,500 vehicles per day would detour from crossing the Wilson Dam Bridge to the Singing River Bridge, located 1.1 miles downstream. At the same time, worker personnel vehicles (approximately 35) would drive to the project site and park at the staging area.

Combustion of gasoline and diesel fuels by internal combustion engines (e.g., vehicles, generators, construction equipment, etc.) would generate local emissions of particulate matter, NO_x, CO, volatile organic compounds, and SO₂.

Equipment expected to be used include 1-2 truck-mounted cranes, 2 skid steer loaders, 1 forklift, 2-4 dump trucks, concrete trucks and pump trucks during deck pours, hand tools (small pneumatic hammer), generators, air compressors, vacuum cleaners, airless spray equipment, abrasive pressure washer, and other miscellaneous equipment. Emissions

associated with these vehicles and equipment are expected to result in negligible impacts to air quality because there would be relatively few emissions sources (e.g., trucks, private vehicles) used during construction and use would be temporary.

Removal of the bridge deck, milling the fly-over surface, cutting/chipping out the expansion joints, preparing the surface of the fly-over handrails, and vehicular traffic over paved roads at the site also would result in the emission of fugitive dust during active construction periods. Based on analyses conducted at other construction sites, it is expected that the largest fraction (greater than 95 percent by weight) of fugitive dust emissions would be deposited within the construction site boundaries. To minimize air impacts TVA requires all contractors to keep construction equipment properly maintained and to use BMPs (such as covered loads and wet suppression) to minimize fugitive dust.

Air quality impacts from construction activities would be temporary (approximately 8 months) and would depend on both human factors (e.g., intensity of activity, control measures) and natural factors such as wind speed and direction. However, even under unusually adverse conditions, these emissions from construction activities would have, at most, a minor transient impact on air quality and would be well below the applicable ambient air quality standards.

There would be indirect effects caused by the approximately 3,500 vehicles per day using the Wilson Dam Bridge that would shift to crossing the Singing River Bridge nearby. Air emissions generated from these vehicles would continue unchanged but are expected to temporarily shift to the nearby bridge. The slight increase in distance traveled due to the temporary detour may cause a small increase in air emissions.

Overall, the potential impacts to air quality from construction-related activities on local and regional air quality would be temporary and minimal.

3.2 Climate

3.2.1 Affected Environment

Data trends indicate increasing temperatures, decreasing precipitation, declining cloud cover, and increasing solar radiation in the TVA power service area. TVA has taken an active role in preparing for the potential impacts of Climate Change, by developing and maintaining its Climate Change Adaptation Plan (TVA 2016). Also, since 2011, TVA, in coordination with other federal agencies as well as state and local partners, has initiated a Climate Change Sentinel Monitoring program with 18 stations in the TVA power service area designed to assess potential biological, ecological, and hydrological responses of aquatic ecosystems related to climate change. TVA is also monitoring effects of climate change on agriculture, forest resources, and recreation. TVA also participates in the Department of Energy's Partnership for Energy Sector Climate Resilience, the aim of which is to improve the resilience of energy infrastructure to extreme weather and climate change impacts.

Gases that trap heat in the atmosphere are called greenhouse gases. Gases that contribute to the greenhouse effect include: water vabor, carbon dioxide, methane, and nitrous oxides. Global atmospheric concentrations of carbon dioxide, methane, nitrous oxide, and certain manufactured greenhouse gases have all risen significantly over the last few hundred years. Too much of these greenhouse gases can cause Earth's atmosphere to trap more and more heat and affect climate change. TVA power plant carbon dioxide emissions have

dropped by approximately 31 percent between 2011 and 2017 due to a multitude of emission reduction projects instituted by TVA in this period.

3.2.2 Environmental Consequences

3.2.2.1 Alternative A – No Action Alternative

Under the No Action Alternative, TVA would not refurbish the Wilson Bridge deck and other concrete surfaces, reseal the fly-over epoxy overlay, remove and replace the fly-over expansion joints, or repaint the fly-over handrails. Implementing the No Action Alternative would not result in any new emissions of greenhouse gases and therefore, this alternative would not impact climate change.

3.2.2.2 Alternative E – Repair Scheme D

Carbon dioxide emissions would occur during the construction phase. Construction-related carbon dioxide emissions would be primarily related to the combustion of gasoline and diesel fuels by internal combustion engines (vehicles, generators, construction equipment, etc.). The total amount of these greenhouse gas emissions (GHG) would be small and would last for a short time (8 months). These emissions would not adversely affect regional GHG levels with no discernable link or effect to changes in global climate. Therefore, this alternative would not result in noticeable impacts on climate change.

The GHG emissions associated with operation of the bridge would be similar to current conditions and would not create a new impact on climate change.

TVA would continue to monitor climatic effects as they occur and continue to update its plans and policies as evidence of changing climate conditions continues to be gathered and as the forecasting capabilities continue to evolve.

3.3 Surface Water

3.3.1 Affected Environment

The project area drains to the Tennessee River both upstream and downstream of Wilson Dam. Upstream, Wilson Reservoir has been designated by the Alabama Department of Environmental Management for uses including public water supply, fish and wildlife, swimming and other whole-body water-contact recreation. Downstream, Pickwick Reservoir has been designated for uses including public water supply and fish and wildlife.

Water quality monitoring of the main stem reservoirs of the Tennessee River system is conducted by TVA through its Reservoir Ecological Health Monitoring Program. Objectives of the program are to provide basic information on the "health" or integrity of the aquatic ecosystem in each TVA reservoir and to provide screening level information for describing how well each reservoir meets the "fishable" and "swimmable" goals of the Clean Water Act. Sampling activities involve examination of appropriate physical, chemical, and biological indicators in the forebay, midregion, and headwater areas of each reservoir. In the most recent monitoring results, from 2016, Wilson Reservoir received an ecological health rating of "poor" with concerns related to dissolved oxygen, chlorophyll, and bottom life. Pickwick Reservoir's ecological health rating is "fair" with concerns related to chlorophyll (TVA 2019b). The Tennessee River (Wilson Reservoir) is listed by the State of Alabama under Section 303(d) of the Clean Water Act as an impaired waterbody because of excessive nutrients from agriculture (ADEM 2018).

3.3.2 Environmental Consequences

3.3.2.1 Alternative A – No Action Alternative

Under the No Action Alternative, TVA would not refurbish the Wilson Bridge deck and other concrete surfaces, reseal the fly-over epoxy overlay, remove and replace the fly-over expansion joints, or repaint the fly-over handrails. There would be no change in operation of the bridge but minor impacts to water quality would occur due to continuing deterioration of keyways, expansion joints, and arches and the increased potential for falling debris from the structure. Continued aging and degradation of the structure could pose water quality issues over the long term should the existing drainage structure become compromised.

3.3.2.2 Alternative E – Repair Scheme D

Infrastructure disturbances associated with construction and demolition activities could potentially result in water quality impacts. Erosion and sedimentation could increase turbidity (water cloudiness) and threaten aquatic life. Construction activities with the potential to affect surface water include those that generate dust, debris, and stormwater runoff. Specific activities that could affect surface water include using high-pressure water (i.e., hydrodemolition) to remove deteriorated and sound concrete, cutting and chipping out the expansion joints, and using aggregate under high pressure to remove coating/paint on the fly-over handrails. Where possible, preparation activities would be contained (e.g., cutting/chipping out of expansion joints or removing coating/paint from handrails) to avoid/minimize potential impacts to water quality. Water used during cutting operations would be collected using shop vacuums. Even with the use of full containment, the possibility exists of minimal amounts of concrete dust/chipping debris, saw wash water, paint dust from the use of abrasive media on the handrails, and the abrasive media entering the surface water.

Water used during refurbishment preparation activities would help to suppress dust and would drain toward storm drains. TVA would comply with the NPDES permit, including Part 1.A, and would utilize best management and maintenance practices to minimize potential impacts and to prevent the discharge or loss of potential pollutants to the reservoir and to contain and properly dispose of all wastes, accidental spills, surface runoff, or other potential contaminants. TVA would also comply with applicable local, state and federal laws and regulations. The use of the existing graveled area for staging equipment, materials, and vehicles would help minimize potential for erosion and sedimentation. Workers will use portable toilets (porta potties/porta johns) and a crew wash station that will be cleaned on a regular basis and removed after construction is completed.

With implementation of these minimization and control measures, there would be temporary, minor impacts on water quality because these measures would help to prevent and minimize the amount of contaminants entering stormwater drains on the bridge. The potential for impacts would be greatest during removal of the deck, an action that is anticipated to take several months. No long-term water quality impacts are anticipated and the proposed action would not affect the long-term water quality or ecological health of Wilson or Pickwick Reservoirs.

3.4 Wildlife

3.4.1 Affected Environment

The Tennessee River provides diverse habitat features and supports a wide range of wildlife. Habitat along the shoreline near Wilson Dam consists of deciduous-dominated woodlands, fields, maintained parks and open areas, and floodplain areas. These draw a

variety of birds including waterfowl and shorebirds; Alabama Birding Trail Sites 6 and 7 are immediately adjacent to the dam. Based on current eBird records, Lauderdale and Colbert counties are the 3rd and 4th most bird species-rich counties in the state, respectively (eBird 2012).

Bald eagles and golden eagles are both federally protected under the Bald and Golden Eagle Protection Act. Bald eagles utilize the Tennessee River corridor to nest and forage year-round. Golden eagles forage along the Tennessee River throughout the winter. Bald eagles are routinely observed from the dam and in the surrounding area (eBird 2012). Golden eagles are infrequent to the area and have not been documented within 10 miles of the project area in the past decade. A great blue heron (*Ardea herodias*) rookery is present on Jackson Island, just downstream of Wilson Dam. Although bats and birds are known to roost in bridges, buildings, and dams, TVA biologists completed a survey of Wilson Dam in 2018 and found no indications of roost use. Five caves have been documented within three miles of the project area.

Wilson Dam connects the communities of Florence and Muscle Shoals and the predominant land-cover within 10 miles of Wilson Dam is urban development (NLCD 2011). Portions of the natural environment that remain have been impacted by anthropogenic sprawl and are often maintained for recreation, designated natural areas, or other environmental amenities.

3.4.2 Environmental Consequences

3.4.2.1 Alternative A – No Action Alternative

Under the No Action Alternative, TVA would not refurbish the Wilson Bridge deck and other concrete surfaces, reseal the fly-over epoxy overlay, remove and replace the fly-over expansion joints, or repaint the fly-over handrails. As a result, this alternative would not adversely impact wildlife or their habitats.

3.4.2.2 Alternative E – Repair Scheme D

Activities proposed under Alternative E would occur on the bridge deck, fly-over, and arches and would require use of an existing temporary equipment and supply staging area.

Despite the prevalence of birds around Wilson Dam, Alternative E would not directly impact wildlife because work would be confined to the dam bridge, fly-over, arches, and existing gravel-lined staging area. Bridge construction has been shown to have limited influences on bird species groups found on the Tennessee River (Bonnington and Smith 2018) when no activities would be conducted in aquatic or terrestrial wildlife habitat. Construction is not expected to impact species using nearby caves or forested areas, such as Jackson Island (0.15 miles) or the nearest cave (1.1 miles). These habitats are sufficient distance from the Wilson Dam Bridge that construction noise at the habitat areas would be under 60 A weighted decibels (dBA) (a typical conversation occurs at 60 dBA and is not loud enough to cause hearing damage) (see Section 3.11 for information on noise levels associated with typical construction equipment). Implementation of BMPs would minimize indirect impacts from sediment mobilization and introduction of contact water into Wilson Reservoir and the Tennessee River. No indirect impacts are expected to wildlife species or habitat surrounding the project action area because the proposed action is too far removed in distance to affect these species or their habitat.

3.5 Threatened and Endangered Species

3.5.1 Affected Environment

In the United States, species may be federally listed as threatened or endangered under the ESA, which affords broad protections to the listed species. A species' status is critically reviewed prior to listing and, once listed, federal agencies are required to follow structured procedures to conserve endangered and threatened species when taking a federal action that may jeopardize these species. The State of Alabama also requires separate protections for species considered endangered or of special concern within the state. The state species listing is updated by the Alabama Department of Conservation and Natural Resources and these species are identified in the State Wildlife Action Plan.

A review of the USFWS Information for Planning and Consultation (IPaC) tool indicated that 3 mammals, 3 fishes, 10 mussels, and 1 snail could potentially be within 10 miles of the project area (Table 3-1). The wood stork (*Mycteria americana*) us federally listed as threatened and has been observed within 10 miles of Wilson Dam each of the past three years by multiple observers and corroborated with photo evidence (eBird 2012). Impacts to this species are also evaluated. Wood storks are a rookery nesting species with overlapping nesting requirements to great blue heron. Despite this, no wood stork observations near Wilson Dam have occurred during nesting season, nor has any nesting activity near this dam been reported.

Table 5-1. Tederally Listed Opecies			
Scientific Name	Federal Status	Species Group	
Myotis grisescens	Endangered	Mammal	
Myotis sodalis	Endangered	Mammal	
Myotis septentrionalis	Threatened	Mammal	
Mycteria americana	Threatened	Bird	
Speoplatyrhinus	Endangered	Fish	
poulsoni			
Etheostoma boschungi	Threatened	Fish	
Erimonax monachus	Threatened	Fish	
Dromus dromas	Endangered	Mussel	
Cyprogenia stegaria	Endangered	Mussel	
Plethobasus	Endangered	Mussel	
cooperianus			
Lampsilis abrupta	Endangered	Mussel	
Obovaria retusa	Endangered	Mussel	
Pleurobema plenum	Endangered	Mussel	
Plethobasus cyphyus	Endangered	Mussel	
Epioblasma triquetra	Endangered	Mussel	
Cumberlandia	Endangered	Mussel	
monodonta			
Plethobasus	Endangered	Mussel	
cicatricosus			
Compeloma decampi	Endangered	Snail	
	Scientific Name Myotis grisescens Myotis sodalis Myotis septentrionalis Myotis septentrionalis Dromus dromas Cyprogenia stegaria Plethobasus cooperianus Lampsilis abrupta Obovaria retusa Pleurobema plenum Plethobasus cyphyus Epioblasma triquetra Cumberlandia monodonta Plethobasus cicatricosus	Scientific NameFederal StatusMyotis grisescens Myotis sodalisEndangered EndangeredMyotis sodalisEndangered EndangeredMyotis septentrionalisThreatened EndangeredMyotis septentrionalisThreatened EndangeredMyotis septentrionalisThreatened EndangeredMyotis septentrionalisThreatened EndangeredMyotis septentrionalisThreatened EndangeredMyotis septentrionalisThreatened EndangeredMyotis septentrionalisThreatened EndangeredDromus dromasThreatened EndangeredCyprogenia stegariaEndangered EndangeredPlethobasusEndangered EndangeredObovaria retusaEndangered EndangeredPlethobasus cyphyusEndangered EndangeredPlethobasus cyphyusEndangered EndangeredPlethobasus cyphyusEndangered EndangeredPlethobasus cyphyusEndangered EndangeredPlethobasus cyphyusEndangered EndangeredPlethobasus cyphyusEndangered EndangeredPlethobasus cyphyusEndangered EndangeredPlethobasusEndangeredPlethobasusEndangered	

Table 3-1. Federally Listed Species

Federally endangered gray bats (*Myotis grisescens*) and Indiana bats (*Myotis sodalis*) have been recorded in Lauderdale County and gray bats have also been documented in Colbert County. Gray bats reside primarily in caves and Indiana bats hibernate in caves and roost

in trees throughout the summer. There is designated critical habitat for the Indiana bat within 10 miles of Wilson Dam. TVA biologists completed a survey of Wilson Dam in 2018 and found no indications of bat use or potential roosting sites on the deck of the dam, arches, or fly-over. Five caves have been documented within three miles of the dam, the closest of which is approximately 1.1 miles from the dam.

3.5.2 Environmental Consequences

3.5.2.1 Alternative A – No Action Alternative

Under the No Action Alternative, TVA would not refurbish the Wilson Bridge deck and other concrete surfaces, reseal the fly-over epoxy overlay, remove and replace the fly-over expansion joints, or repaint the fly-over handrails. As a result, this alternative would not impact threatened or endangered animals.

3.5.2.2 Alternative E – Repair Scheme D

Federally listed mammals would not be directly impacted by Alternative E because work would be confined to the dam bridge, fly-over, and arches and existing fenced gravel-lined staging area. These areas have no bat use as confirmed by TVA biologists. No activities would be conducted in species habitat and, due to sufficient distance of the proposed actions from known caves, construction is not expected to impact listed bat species using nearby caves or forested areas. There would be no impact on the wood stork because this species has not been observed using the project area during nesting season or for nesting activity. Wood stork occurrence in the project area appears to be limited to migration and the scale and location of the proposed action is not expected to affect migration.

Federally listed fish and mollusks would not be directly impacted by Alternative E because work would be confined to the dam bridge, fly-over, and arches and gravel-lined staging area. No impacts to the watercourse are anticipated and implementation of BMPs would minimize indirect impacts from sediment mobilization and introduction of contact water into Wilson Reservoir and the Tennessee River.

Activities proposed under Alternative E would require use of an existing temporary equipment and supply staging area. No threatened and endangered species habitat occurs in the staging area. Therefore, Alternative E is not anticipated to have an impact on threatened and endangered species.

3.6 Solid and Hazardous Waste

3.6.1 Affected Environment

Solid waste consists of a broad range of materials that include refuse, sanitary wastes, contaminated material, scrap metals, nonhazardous wastewater treatment plant sludge, nonhazardous air pollution control wastes, various nonhazardous industrial waste, and other materials (solid, liquid, or contained gaseous substances). Solid wastes are generally managed through recycling and local landfills.

Hazardous wastes consist of materials that may be harmful to human health or the environment due to their toxicity, reactivity, ignitability, or corrosivity. Hazardous materials and management of these materials are regulated under a variety of federal laws including the Occupational Safety and Health Administration standards; Emergency Planning and Community Right to Know Act; RCRA; the Comprehensive Environmental Response, Compensation, and Liability Act; and the Toxic Substances Control Act. The federal laws regulating hazardous wastes are under RCRA and its implementing regulations codified in

Title 40 CFR Parts 260-280. The regulations define what constitutes a hazardous waste and establishes a "cradle to grave" system for management and disposal of hazardous wastes.

3.6.2 Environmental Consequences

3.6.2.1 Alternative A – No Action Alternative

Under the No Action Alternative, TVA would not refurbish the Wilson Bridge deck and other concrete surfaces, reseal the fly-over epoxy overlay, remove and replace the fly-over expansion joints, or repaint the fly-over handrails. Therefore, no hazardous or solid substances would be generated from construction or operation activities.

3.6.2.2 Alternative E – Repair Scheme D

Under Alternative E, demolition debris, such as concrete, would be generated during bridge deck and expansion joint removal. The concrete deck to be removed is approximately 3,600 tons (3,200' x 20' x 0.75' x 150 per cubic foot (pcf)/2,000 tons/lb.) and the concrete debris generated during expansion joint removal would add several hundred more pounds. The refurbishment action includes a 10% increase in debris due to removal of materials from arches, sidewalks, and guardrail faces for an approximate total of 4,000 tons.

The six steel expansion joints weigh approximately 2,800 pounds in total and are expected to be recycled.

Various hazardous wastes, such as fuels, solvents, paints, adhesives, lead-based paint (LBP) and compressed gases could also be produced during construction. Oily wastes generated during servicing of heavy equipment would be managed by TVA approved offsite vendors who service on-site equipment using appropriate self-contained used oil reservoirs. Appropriate spill prevention, containment and disposal requirements for hazardous wastes would be implemented to protect construction and plant workers, the public, and the environment. A small amount of LBP debris may be generated during the preparation of the fly-over handrails. LBP would be captured as part of the closed abrasive pressure wash system. The amounts of LBP generated are anticipated to be small as most LBP on the handrails would have been removed during previous repainting efforts (repainting efforts have occurred post-1977 when the LBP ban went into effect).

TVA would manage all solid wastes generated from construction activities in accordance with established procedures. Solid wastes would be managed as required by applicable state regulations in conformity with TVA's environmental procedures and BMPs. General municipal solid waste and scrap metal could be incorporated into TVA's existing recycling program. Solid waste construction impacts are expected to be minor.

Nonhazardous waste generated from deck and expansion joint removal as well as preparing areas of sidewalk, guardrails, fly-over, and parts of arches would include concrete and a limited amount of other construction wastes, such as metal, paper, wood, plastic, and other debris. Appropriate disposal of non-recyclable materials generated by this action would be disposed at the Republic Services' Morris Farm Sanitary Landfill located approximately 32 miles to the east in Hillsboro; the Shoals Solid Waste Authority Landfill located less than 10 miles to the south in Tuscumbia; or the Florence Municipal Solid Waste Landfill, a permitted construction and demolition debris management facility located approximately 10 miles northwest in Florence. Overall, sufficient landfill capacity is available to accommodate the additional solid waste generated as a result of the proposed construction activities. Generation of construction wastes would be short-term and

temporary; therefore, with implementation of standard TVA procedures including recycling, direct or indirect effects associated with construction wastes would be minimal.

Hazardous materials used during refurbishment may include limited quantities of fuels, solvents, paints, and other hazardous materials. The deck, fly-over, expansion joint, and arch refurbishment would not require any solvents. Repaired handrails located along the bridge may be repainted to match existing handrails. The fly-over deck would be coated with two layers of epoxy. Appropriate spill prevention, containment, and disposal requirements for hazardous materials would be implemented to protect construction and plant workers, the public, and the environment. All wastes would be characterized for appropriate disposal and a TVA approved permitted third-party waste disposal facility would be used for ultimate disposal of the wastes. Therefore, no significant impacts associated with the use of fuels, oil, lubricants, and the limited quantities of other hazardous materials generated during construction would be expected.

Operation of the refurbished bridge deck and fly-over would be the same as described under Alternative A and no direct or indirect effects related to solid or hazardous wastes are anticipated from use of the refurbished bridge deck and fly-over.

3.7 Visual Resources

3.7.1 Affected Environment

This assessment provides a review of the visual attributes of existing scenery, along with the anticipated impacts resulting from the proposed action. The classification criteria used in this analysis are adapted from a scenic management system developed by the U.S. Forest Service and integrated with planning methods used by TVA. The classification process is also based on the methodology and descriptions adapted from Landscape Aesthetics, A Handbook for Scenery Management, Agriculture Handbook Number 701 (U.S. Forest Service 1995).

Scenic resources within a landscape are evaluated based on several factors that include scenic attractiveness, integrity and visibility. Scenic attractiveness is a measure of scenic quality based on human perceptions of intrinsic beauty as expressed in the forms, colors, textures and visual composition of each landscape. Scenic integrity is a measure of scenic importance based on the degree of visual unity and wholeness of the natural landscape character. The varied combinations of natural features and human alterations both shape landscape character and help define their scenic importance. The subjective perceptions of a landscape's aesthetic quality and sense of place are dependent on where and how it is viewed. For this analysis, the affected environment is the dam, as well as the physical and natural features of the landscape around it.

The Wilson Dam is an National Historic Landmark (NHL) and is listed in the National Register of Historic Places (NRHP). It has been a visual presence in the area since the 1920s. No other historic resources are within direct line of sight to the Wilson Dam. The nearest identified historic resource, the circa 1870 Norfolk Southern Railroad Bridge, is located approximately 2.69 miles west-southwest of the Wilson Dam. No NRHP-eligible resource associated with the TVA Muscle Shoals Reservation is within direct line of sight.

The downstream face of the Wilson Dam, where the concrete arches interface with the parapet have developed widespread spalls with efflorescence and visible water movement.

In addition, the sidewalk, curb, parapet, and deck have developed widespread cracking. Sections of the bridge parapet show previous repairs that do not match the original bridge.

On the north shore of the dam is the Marriott Shoals Hotel and Spa constructed in 2005 and the 26-story Renaissance Tower built in 1991. On the south shore of the dam is the control building, a scenic overlook, and residential development. Upstream of the dam is Wilson Reservoir and downstream is the Tennessee River/ Pickwick Reservoir and the forested Jackson Island. Wilson Reservoir is visually dynamic depending on the time of year (e.g., lower pool levels may result in exposure of reservoir banks, bottoms, and flats). The combination of development and land use patterns along its shore contributes to the overall visual character of the area.

The potential impacts to the visual environment from a given action are assessed by evaluating the potential for changes in the scenic value class ratings based upon landscape scenic attractiveness, integrity, and visibility. Sensitivity of viewing points available to the public, their viewing distances and visibility of the proposed action are also considered during the analysis. These measures help identify changes in visual character based on commonly held perceptions of landscape beauty and the aesthetic sense of place. The extent and magnitude of visual changes that could result from the proposed facility were evaluated based on the process and criteria outlined in the U.S. Forest Service scenic management system.

3.7.2 Environmental Consequences

3.7.2.1 Alternative A – No Action Alternative

Under the No Action Alternative, TVA would not refurbish the Wilson Bridge deck and other concrete surfaces, reseal the fly-over epoxy overlay, remove and replace the fly-over expansion joints, or repaint the fly-over handrails. If the bridge is left unrepaired, deterioration of the deck, fly-over, expansion joints, keyways, and arches may progress over time, increasing the visible spalls and cracks and further degrading the scenic attractiveness of the dam, bridge, and fly-over. A minor visual impact would occur due to continued deterioration of the dam, bridge, an fly-over.

3.7.2.2 Alternative E – Repair Scheme D

Construction activities would temporarily affect the visual environment due to refurbishment activities. Hydrodemolition activities to remove the bridge deck concrete and the deteriorating concrete on the faces of the arches would be visible to visitors and residents viewing the Wilson Dam from the nearby shores. Cutting and chipping expansion joints as well as preparing the fly-over surface would also be visible. In addition, dump trucks removing debris or concrete mixer trucks would be visible entering and leaving the project area. Therefore, temporary, minor impacts to the visual environment are anticipated.

TVA intends to rehabilitate the bridge such that deteriorated features would be repaired to match the original features in design, color, texture, and other visual qualities. The textural finishes of any concrete or paint applied would be matched to the Wilson Dam's current appearance. Existing curbs, deck drain plates, and light fixtures set into the guard rails of the bridge would be removed, retained, and reinstalled as a part of the project. Overall, the project would provide long-term visual benefits as it restores the scenic attractiveness of the dam, bridge, and fly-over by removing spall and the cracks in the roadway, sidewalks, and parapets.

3.8 Cultural and Historic Resources

3.8.1 Affected Environment

Cultural resources include prehistoric and historic archaeological sites, districts, buildings, structures, and objects, as well as locations of important historic events that lack material evidence of those events. Cultural resources that are listed, or considered eligible for listing, in the NRHP are called historic properties. To be considered a historic property, a cultural resource must possess both integrity and significance. A historic property's integrity is based on its location, design, setting, materials, workmanship, feeling, and association. The significance is established when historic properties meet at least one of the following criteria: (a) are associated with important historical events or are associated with the lives of significant historic persons; (b) embody distinctive characteristics of a type, period, or method of construction; (c) represent the work of a master, or have high artistic value; or (d) have yielded or may yield information important in history or prehistory (36 CFR Part 60.4).

Section 106 of the NHPA requires federal agencies to consider the effects of their proposed undertakings on historic properties and provide the Advisory Council on Historic Preservation an opportunity to comment on those effects. TVA determined that the Proposed Action (Alternative E) is an "undertaking" as defined by the regulations under NHPA. Once an action is determined to be an undertaking, the regulations require agencies to consider whether the proposed activity has the potential to impact historic properties. If the undertaking is such an activity, then the agency must follow the following steps: (1) involve the appropriate consulting parties; (2) define the area of potential effects (APE); (3) identify historic properties in the APE; (4) evaluate possible effects of the undertaking on historic properties in the APE; and (5) resolve adverse effects (36 CFR § 800.4 through 800.13.). An APE is defined as the "geographic area or areas within which the undertaking may directly or indirectly cause alterations in the character or use of historic properties, if any such properties exist" (36 CFR § 800.16.).

TVA defined the APE to be the following: the boundary of the Wilson Dam NHL (which includes the foundation lines of Wilson Dam, including the power house and the old and new locks); the planned staging area within the lock operation area on the north shore of the Tennessee River; and any historic properties within 0.5 miles and direct line of sight of Wilson Dam. Given the scale and scope of the project and limited view beyond the bridge itself, the APE accounts for both direct and indirect/visual effects.

The direct APE is limited to the concrete arches on the dam above the spring line, bridge deck, curbs, parapets, fly-over, and sidewalks between the control building at the south end and the fly-over's north end, as well as the existing 1.6-acre staging area located within the lock operations area. The surface of the staging area is covered in gravel and it is enclosed by a chain link fence.

Pietak (2002) investigated the APE as part of Tract I in a cultural resources survey of the Muscle Shoals Reservation. No archaeological sites were discovered and no additional work was recommended. None of the identified resources in the Alabama Register of Landmarks and Heritage web map have direct line of sight to Wilson Dam. The nearest identified resource, the c. 1870 Norfolk-Southern Railroad Bridge, is located approximately 2.69 miles west-southwest of Wilson Dam and does not have a direct line of sight. NRHP data available through the National Park Service (NPS) indicates the only historic property within 1.25 miles of Wilson Dam is the Florence Wagon Works Site, listed in the NRHP by TVA in 1996. The site is not within direct line of sight. TVA records indicate additional

NRHP-eligible resources associated with TVA's Muscle Shoals Reservation (including, but not limited to the Power Service Building and CCC Pavilion) are also not located within direct line of sight.

TVA considers effects to historic properties pursuant to Section 106 of the NHPA. The only historic property within the APE is the Wilson Dam NHL. In 1966, Wilson Dam was designated an NHL by the U. S. Department of the Interior and listed in the NRHP. The NHL was certified in 1977 (Rettig and Sheely 1976).

Section 106 of the NHPA requires federal agencies to consult with the respective State Historic Preservation Officer (SHPO) and Indian tribes when proposed federal actions could affect historic and cultural resources, including archaeological resources, which are also protected under the Archaeological Resources Protection Act, and the Native American Graves Protection and Repatriation Act, in addition to the NHPA. Additionally, federal agencies must consult with the Secretary of the Interior for projects affecting NHLs.

3.8.2 Environmental Consequences

3.8.2.1 Alternative A – No Action Alternative

Under the No Action Alternative, TVA would not refurbish the Wilson Bridge deck and other concrete surfaces, reseal the fly-over epoxy overlay, remove and replace the fly-over expansion joints, or coat/paint the fly-over handrails. As a result, the dam,bridge, and flyover would continue to deteriorate. This alternative would have the potential to diminish the integrity of the NHL Wilson Dam and Bridge and could adversely affect this historic resource.

3.8.2.2 Alternative E – Repair Scheme D

Under Alternative E, there would be a direct and visual effect on the Wilson Bridge NHL from removing and replacing the existing bridge deck; patching deteriorated surfaces of arch face, rails, and sidewalks; resealing the fly-over epoxy overlay; replacing the fly-over expansion joints; and painting the fly-over handrails.

Specifically, existing curbs, deck drain plates, and light fixtures set into the guard rails of the bridge would be removed, retained, and reinstalled as a part of the project. The repair of any damaged lights is not a part of this project, however, the damaged lights or those that are missing globes would be reinstalled for potential future repair or restoration. In places where curbs are missing, in-kind replacements would be installed.

On the fly-over, the steel handrails would be prepared using an abrasive pressure wash to remove the existing coating/paint. This process has been used previously to remove paint on the handrails and has not caused harm to the handrails.

Any concrete or paint applied textural finishes would be matched to Wilson Dam's current appearance. Furthermore, as the plans specify, the contractor would take special care to protect any parts of the structure that are not to be removed specifically and the contractor is not allowed to use a hydraulic ram on a backhoe, mini excavator, or other equipment for concrete removal on portions of the structure to remain in service.

Given that the design of the bridge refurbishment is in keeping with the *Secretary of the Interior's Standards for Rehabilitation,* it is unlikely that the rehabilitation of the bridge, arches, and fly-over at the Wilson Dam would diminish the integrity of the NHL. Therefore, Alternative E would have no adverse effect to historic properties.

TVA completed consultation on a portion of the project excluding work on handrails and the flyover with the Alabama Historical Commission/SHPO, who provided concurrence on TVA's finding of no adverse effect to historic properties. TVA is currently in consultation on the paint removal and repainting of the handrails and flyover portion of the project.TVA is currently in consultation with the following federally-recognized tribes: Absentee Shawnee Tribe of Oklahoma, Alabama-Coushatta Tribe of Texas, Alabama-Quassarte Tribal Town, Cherokee Nation, The Chickasaw Nation, Coushatta Tribe of Louisiana, Eastern Band of Cherokee Indians, Eastern Shawnee Tribe of Oklahoma, Jena Band of Choctaw Indians, Kialegee Tribal Town, The Muscogee (Creek) Nation, Poarch Band of Creek Indians, The Seminole Nation of Oklahoma, Shawnee Tribe, Thlopthlocco Tribal Town of Oklahoma, and the United Keetoowah Band of Cherokee Indians in Oklahoma.

TVA also notified the Secretary of the Interior, via the Southeast Regional Office of the NPS, regarding the SHPO's concurrence on the finding of no adverse effects, as required for projects affecting NHLs (see Appendix F). TVA will send additional consultation once the SHPO concurrence on the remainder of the project is received.

3.9 Recreation

3.9.1 Affected Environment

Nearby recreation opportunities include boating and fishing on Wilson Reservoir. Common fish species include catfish, smallmouth bass, and largemouth bass. Fishing is also popular on the tail waters below the dam, both from the bank or by boat.

The closest boat access facilities are the TVA-owned public boat ramp and associated parking lot at the south end of the dam and the privately-operated Steenson Hollow Marina approximately 0.5 miles east of the dam.

The Wilson Dam Visitors Center is located on Reservation Road at the south end of the dam and includes display panels and interpretive materials. A visitor overlook and ADA-accessible fishing pier are located across the road to the east, while the 1-mile Energy Trail runs along the bluffs above the Tennessee River to the west.

The Muscle Shoals Waterfall Walk, 0.18 miles in length, is located along the southern shore below the dam. This paved trail provides views of Wilson Dam, limestone bluffs, and a waterfall. The trail is popular for bird watching, as many bird species congregate along the tail waters and at Jackson Island.



View of Muscle Shoals Waterfall Walk from Wilson Dam Bridge

The City of Florence operates two city parks on the north shore of the river and reservoir. Veteran's Memorial Park, located northeast of the dam, provides a variety of recreation amenities including baseball fields, tennis courts, a disc golf course, picnic areas, and a playground. River Heritage Park, northwest of the dam, features picnic shelters, a playground, and an interactive water fountain that is open seasonally. The park also has several river overlooks and is the starting point for the future River Walk Heritage Trail, a planned 2-mile walking path along the Tennessee River. Figure 3-1 provides an overview of local recreation areas and facilities.



Bird Watching from Muscle Shoals Waterfall Walk



Figure 3-1. Recreation Areas

Environmental Assessment

3.9.2 Environmental Consequences

3.9.2.1 Alternative A – No Action Alternative

Under the No Action Alternative, TVA would not refurbish the Wilson Bridge deck and other concrete surfaces, reseal the fly-over epoxy overlay, remove and replace the fly-over expansion joints, or repaint the fly-over handrails. There would be no temporary closures or other adverse impacts on recreation over the short- or long-term.

3.9.2.2 Alternative E – Repair Scheme D

Implementation of the proposed action would result in minor, short-term, indirect impacts on recreation similar to those described for transportation below. There would be no direct impacts because all recreation facilities would remain open during refurbishment and no recreation activities would be unavailable.

The closure of Reservation Road would require users to use Singing River Bridge on State Highway 133/157 as an alternate route when accessing recreation facilities and activities on the opposite side of the dam. For example, access to the visitors' center from the north end of the dam would require a 5-minute detour on the Singing River Bridge. These impacts would only occur while Reservation Road is closed.

Activities such as fishing, boating, hiking, and bird watching would be unaffected.

3.10 Transportation

3.10.1 Affected Environment

The Muscle Shoals Reservation is served by highway and railway modes of transportation. The transportation network surrounding the Reservation contains roads, bridges, rail lines, and navigable waterways. Reservation Road crosses the Wilson Dam. Based on a 2017 traffic study, approximately 3,500 vehicles per day travel across the Wilson Dam (Volkert 2017). Wilson Dam Traffic Data is provided in Appendix E.

To the west of the dam is Alabama State Highway 133 (AL 133) or Wilson Dam Road, a multi-lane divided highway, which runs north-south between Muscle Shoals and Florence and carries traffic over the Tennessee River (see Figure 3-2). AL 133 crosses the Tennessee River via the Singing River Bridge (formerly known as the Patton Island Bridge) and carries over 34,710 vehicles per day (ALDOT 2017). On the south side of the Wilson Dam, Reservation Road, a minor arterial, continues until it intersects with AL 133/Wilson Dam Road. On the north side of the Wilson Dam, Reservation Road intersects with Veterans Drive, which are both principal arterials.

The Alabama Department of Transportation (ALDOT) is finishing up work on a section of AL 133 south of the Singing River Bridge in 2019. Additional roadway projects are planned in Florence over the next few years.


A pedestrian sidewalk is on the west side of the bridge crossing the dam. No dedicated bicycle facilities are in the project area. Trail systems are near the project area on both sides of the dam/ bridge but are not within the project area.

There is an extensive intermodal system in the Muscle Shoals area. Included in this system are two railways, Norfolk-Southern Railroad and the Tennessee Southern Rail Company. Norfolk-Southern serves Colbert County with connections to markets to the east, west and south of the Shoals Area. The Tennessee Southern Rail Company is a short line railroad

that serves Lauderdale County with connections into middle Tennessee. The rail service in the Muscle Shoals area is freight based with no passenger rail service.



AL 133 and Singing River Bridge





The Tennessee River provides opportunities for commercial and industrial transportation in the Muscle Shoals Area. The navigable waterway has created the opportunity for thousands of industrial and service jobs at businesses and industries that utilize the river for transportation. The Wilson Dam has a navigation lock, which is operated by the USACE. Port facilities are available on both sides of the waterway for use by commercial and industrial interests. Public and private docks are located along the Tennessee River providing an intermodal transportation connection. The Florence – Lauderdale County Port Authority is a public, not-for-profit organization chartered by the Lauderdale County Commission and the City of Florence. The Authority owns the Port of Florence. The Port Authority leases land and equipment to private operators and manages the public dock.

The Port of Florence is a multi-modal port located at mile 256 on the Tennessee River. Tennessee Southern Railroad provides rail access to the port and operator services at the public dock. The railway connects to CSX north of Columbia, Tennessee. The Tennessee Southern Railroad also operates the Port Authority's 40-ton overhead bridge crane. Fleeting is provided by Muscle Shoals Marine Service.

The Northwest Alabama Regional Airport is located north of U.S. Highway 72 Alternate approximately 3 miles south of the Wilson Dam. The airport has 14 "T" hangers, 12 aerial ports and tie-downs for over 75 general aviation aircraft. The airport hosts approximately three passenger flights per day and 15 freight/mail flights per day (Northwest Alabama Regional Airport 2019). Commercial passenger air service is provided by Mesaba Airlines operating as a Delta Connection with daily connections to Atlanta, Georgia.

3.10.2 Environmental Consequences

3.10.2.1 Alternative A – No Action Alternative

Under the No Action Alternative, TVA would not refurbish the Wilson Bridge deck and other concrete surfaces, reseal the fly-over epoxy overlay, remove and replace the fly-over expansion joints, or repaint the fly-over handrails. Reservation Road would remain open and traffic would continue to use Wilson Dam Bridge. A potential minor impact to transportation would occur if deterioration of the bridge and fly-over continues to the point where it can no longer accommodate current or forecasted traffic volumes.

3.10.2.2 Alternative E – Repair Scheme D

As discussed in the Purpose and Need section, the concrete bridge deck and sidewalks have deficiencies in the form of cracks and evidence of previous repairs. The overlay and expansion joints on the fly-over are showing signs of wear and tear. To repair the bridge deck, fly-over, and sidewalks, Reservation Road over the Wilson Dam Bridge would be closed for approximately 8 months. Detoured traffic would use existing arterial roads and cross the Tennessee River using the nearby Singing River Bridge on AL 133. The detour would add approximately 5 minutes to an average crossing. The small volume of traffic, approximately 3,500 vehicles per day, is not anticipated to negatively affect existing traffic on nearby roads or the Singing River Bridge, where traffic volumes would temporarily increase by approximately 10 percent during repairs. Currently, during bad weather, such as when water freezes on the dam, the bridge is closed and traffic is detoured. Similarly, during dam safety maintenance or inspections, the bridge is closed. Bridge closures occur on a semi-regular basis and travelers using the Wilson Dam Bridge have become accustomed to these closures.

The daily workforce during construction/renovation is expected to be approximately 35 workers. Construction traffic is expected to predominantly consist of a mix of passenger

cars and pickup trucks, along with less frequent large delivery or construction trucks including dump trucks and concrete mixer trucks. For this analysis, the bounding value of the construction workforce (35 workers) is used to assess potential effects on traffic operations. Traffic is assumed to be distributed during a peak morning period (to the site) and during a peak evening period (away from the site). Therefore, a daily traffic volume of 35 vehicles per day (worker vehicles, material delivery trucks, and construction trucks (dump and cement) is assumed to be generated by Alternative E. It is assumed that construction-related traffic would utilize interstate highways or major arterial roadways as much as possible and therefore would only generate a minor increase in traffic on local roads.

Pedestrians using the bridge and fly-over, primarily guests of the Muscle Shoals Hotel and Spa or visitors, would not be able to cross the bridge during repairs but other pedestrian facilities (trails) located on both sides of the Tennessee River near the Wilson Dam would continue to provide for pedestrian access.

Temporary bridge closure would have no impact on boat or barge traffic as the Wilson Dam locks would not be affected by the bridge closure. Passenger and freight air and freight travel would not be affected by the temporary bridge closure.

The temporary bridge closure is not expected to affect local emergency, fire, and law enforcement agencies and would not jeopardize their capacity to respond to other emergencies. These services occur on both sides of the Tennessee River and in case of a large emergency, access would continue through use of the Singing River Bridge.

After repair work is completed, no change in vehicle traffic volume is anticipated and traffic patterns should return to current levels. Therefore, the Project is expected to have a temporary, minor adverse impact on transportation during repairs and have a long-term transportation benefit as the bridge and fly-over would be able to continue to accommodate current or forecasted traffic volumes.

3.11 Noise

3.11.1 Affected Environment

Noise is defined as unwanted or unwelcome sound usually caused by human activity and added to the natural acoustic setting of a locale. It is further defined as sound that disrupts normal activities or diminishes the quality of the environment. Community response to noise is dependent on the intensity of the sound source, its duration, the proximity of noise-sensitive land uses and the time of day the noise occurs (i.e., higher sensitivities would be expected during the quieter overnight periods).

Sound is measured in units of decibels (dB) on a logarithmic scale. Therefore, increasing the noise level by 5 dB results in a noise level perceived by the human ear to be twice as loud as the original source. Given that the human ear cannot perceive all pitches or frequencies in the sound range, sound level measurements are typically weighted to correspond to the limits of human hearing, as measured in dBA. A noise change of 3 dBA or less are not normally detectable by the average human ear. An increase of 5 dBA is generally not readily noticeable and a 10-dBA increase is usually felt to be "twice as loud" as before.

The Noise Control Act of 1972, along with its subsequent amendments (Quiet Communities Act of 1978, USC 42 4901-4918), delegates authority to the states to regulate environmental noise and directs government agencies to comply with local community noise statutes and regulations. Although there are no federal, state, or local regulations for community noise in Colbert or Lauderdale counties, USEPA guidelines (1974) recommend that Ldn (day-night average sound level) not exceed 55 dBA for outdoor residential areas. The USEPA noise guideline recommends an Ldn of 55 dBA, which is sufficient to protect the public from the effect of broadband environmental noise in typical outdoor and residential areas. These levels are not regulatory goals but are "intentionally conservative to protect the most sensitive portion of the American population" with "an additional margin of safety" (USEPA 1974). The U.S. Department of Housing and Urban Development (HUD) considers an Ldn of 65 dBA or less to be compatible with residential areas (HUD 1985).

Sound from a source spreads out as it travels from the source and the sound pressure level diminishes with distance. In addition to distance attenuation, the air absorbs sound energy. Atmospheric effects (wind, temperature, precipitation) and terrain/vegetation effects also influence sound propagation and attenuation over distance from the source. An individual's sound exposure is determined by measurement of the noise that the individual experiences over a specified time interval.

Community noise refers to outdoor noise near a community. A continuous source of noise is rare for long periods and is typically not a characteristic of community noise. Typical background day/night noise levels for rural areas range between 35 and 50 dB whereas higher-density residential and urban areas background noise levels range from 43 dB to 72 dB (USEPA 1974). Background noise levels greater than 65 dBA can interfere with normal conversation, watching television, using a telephone, listening to the radio and sleeping.

At the Wilson Dam, ambient noise sources include regular operations at the dam (water releases from the reservoir), lock (opening and closing lock), barges, and daily vehicle traffic crossing the bridge. Noise levels increase when cranes and machinery are used during lock outages. Birds also frequent the areas below the dam and generate noise from their calls and activity and have a roost on Jackson Island.

The Northwest Alabama Regional Airport at Muscle Shoals is 3 miles south of the Wilson Dam. The airport can accommodate small to medium size airplanes. The airport hosts approximately three passenger flights per day and 15 freight/mail flights per day (Northwest Alabama Regional Airport 2019). Approaching and departing planes regularly pass over the nearby Muscles Shoals Reservation and are an external source of noise.

Sensitive noise receptors (residences, hotels, parks, etc.) are located near the proposed project. On the north side, the Muscle Shoals Hotel and Spa is 0.36 miles; and Veterans Park is 0.2 mi away from the project area. The nearest residence is located approximately 0.36 miles to the southeast of the dam. A parking lot and overlook of the dam is approximately 0.1 miles from the dam.

Construction noise associated with the proposed action would include the use of vehicles such as dump trucks, delivery trucks, concrete mixers, pavers, pickup trucks, and skid steer loaders, and generators and hand-held pneumatic tools. These types of equipment emit 55 to 85 dBA at a distance of 50 feet (FHWA 2017).

3.11.2 Environmental Consequences

3.11.2.1 Alternative A – No Action Alternative

Under the No Action Alternative, TVA would not refurbish the Wilson Bridge deck and other concrete surfaces, reseal the fly-over epoxy overlay, remove and replace the fly-over expansion joints, or repaint the fly-over handrails. Therefore, there would be no changes to the existing noise environment and no new impacts on sensitive receptors.

3.11.2.2 Alternative E – Repair Scheme D

Repairs at the Wilson Dam are anticipated to take up to 8 months. During this time, vehicle traffic would detour to the Singing River Bridge and traffic noise would decrease. At the same time, worker personnel vehicles (approximately 35) would park at the staging area. Equipment expected to be used to rehabilitate the dam and bridge include 1-2 truck-mounted cranes, 2 skid steer loaders, 2-4 dump trucks, concrete trucks and pump trucks during deck pours, hand tools, generators, compressors and other miscellaneous equipment. Construction activities would primarily occur during the day on weekdays; however, construction activities could occur at night or on weekends, if necessary. Typical noise levels from construction equipment are expected to be 85 dBA or less at 50 feet.

Based on a simplified analysis of straight-line noise attenuation from the project boundary, it is estimated that construction phase noise levels would attenuate to below the USEPA guidelines. For example, the sound level of construction tools and equipment emitting 55 to 85 dBA at 50 feet would be approximately 28.5 to 58.5 dBA at Veteran's Park (0.2 miles away) and approximately 27.3 to 57.3 dBA at the Muscle Shoals Hotel and Spa and at the nearest residence (approximately 0.23 miles away). These construction noise impacts would be partially offset by the absence of noise from the 3,500 vehicles which normally travel over the bridge.

Given the temporary and intermittent nature of construction noise, the impact of noise generated from construction activities is expected to be minor. There may be minor indirect noise impacts from the detour of traffic (approximately 3,500 vehicles per day) onto the nearby Singing River Bridge. This would temporarily increase the vehicle noise on the detour routes used. The detour traffic noise would only occur during the 8-month construction period.

3.12 Socioeconomics and Environmental Justice

3.12.1 Affected Environment

The northern shore of Wilson Reservoir is the boundary between Lauderdale County (to the north) and Colbert County (to the south). The largest population center near the project is the City of Florence, which is in Lauderdale County directly north of the dam. The City of Muscle Shoals, in Colbert County, is approximately two miles southwest of the dam.

Population and income estimates were derived from the most recent US Census data and are provided in Table 3-2 below. This includes information on low-income and minority populations. EO 12898 (Federal Actions to Address Environmental Justice in Minority Populations and Low-Income Populations) mandates federal agencies to consider potentially disproportionate health or environmental impacts that their activities may have on minority or low-income populations. Although TVA is not subject to this EO, it routinely evaluates the impacts of its actions on low-income and minority populations.

Table 3-2. Fopulation and income								
Metric	State of Alabama	Colbert County	Lauderdale County	City of Florence	City of Muscle Shoals			
Population	4,874,747	54,500	92,538	39,852	14,022			
Per Capita Income	\$25,746	\$23,675	\$25,803	\$23,311	\$26,227			
Median Household Income	\$46,472	\$45,477	\$44,888	\$37,843	\$52,201			
Persons in Poverty (Percent)	16.9	15.4	13.7	22.2	10.2			
Minority Population (Percent)	34.4	21.5	15.4	24.7	17.3			
Source: US Census 201	9							

Table 3-2.Population and Income

During refurbishment, a temporary workforce of approximately 35 workers would utilize services and likely commute from their homes in Colbert and Lauderdale counties.

3.12.2 Environmental Consequences

3.12.2.1 Alternative A – No Action Alternative

Under the No Action Alternative, TVA would not refurbish the Wilson Bridge deck and other concrete surfaces, reseal the fly-over epoxy overlay, remove and replace the fly-over expansion joints, or repaint the fly-over handrails. There would be no temporary workforce needed to conduct refurbishment and therefore no impacts on socioeconomics or environmental justice.

3.12.2.2 Alternative E – Repair Scheme D

Implementation of the proposed action would result in minor, short-term beneficial impacts on socioeconomics, primarily through the temporary use of 35 workers to conduct refurbishment activities. Because workers would likely be local to Colbert and Lauderdale counties, there would be no anticipated increase in sales or lodging taxes. However, the proposed action would provide employment for these workers for the duration of refurbishment activities. Beneficial impacts would extend to environmental justice if workers are hired from minority or low-income populations. Indirect effects would be minor and include spending by workers in the local economy.

3.13 Unavoidable Adverse Impacts

Unavoidable adverse impacts are the effects of the proposed action on natural and human resources that would remain after mitigation measures or BMPs have been applied. Mitigation measures and BMPs are typically implemented to reduce a potential impact to a level that would be below the threshold of significance as defined by the CEQ and the courts. Impacts associated with refurbishment and repair of the Wilson Dam Bridge deck, fly-over, and other concrete surfaces have the potential to cause unavoidable adverse effects to several environmental resources.

Impacts associated with construction have the potential to cause unavoidable adverse effects to existing open water habitats. Use of high-pressure water and aggregate to remove deteriorated and sound concrete and old paint could cause temporary impacts to water quality in receiving water bodies from runoff/drainage. BMPs to filter and minimize runoff would be implemented, and water released by construction activities would meet established ADEM permit limits.

Other impacts associated with Alternative E would primarily be related to activities associated with the use of construction equipment. Equipment use may result in varying amounts of air emissions, noise and vibration that may potentially impact onsite workers. Potential noise impacts also include traffic noise associated with the construction workforce traveling to and from the site. Emissions from construction activities and equipment are minimized through implementation of BMPs, including proper maintenance of construction equipment and vehicles.

3.14 Relationship of Short-Term Uses to Long-Term Productivity

NEPA requires a discussion of the relationship between short-term uses of the environment and the maintenance and enhancement of long-term productivity. This EA focuses on the analyses of environmental impacts associated with the refurbishment or repair of the Wilson Dam Bridge deck, fly-over, and concrete surfaces. These refurbishment activities are considered short-term uses of the environment as they would occur during the 8 months of construction and the long-term use is considered to be initiated upon the completion of the refurbishment and reopening of the bridge to traffic. This section includes an evaluation of the extent that the short-term uses preclude any options for future long-term use of either the bridge or dam.

Construction activities would have a negative effect on a limited amount of short-term uses of the environment such as air, noise and transportation resources as described above. Most environmental impacts during construction activities would be relatively short term and would be addressed by BMPs and mitigation measures. Construction activities would have a limited, yet favorable short-term impact to the local economy through the creation of construction and support jobs and revenue.

Use of an existing solid waste landfill would have a minor impact on capacity and, therefore, have an impact on the users of the landfill. This project is not anticipated to have any significant impact on solid waste management capacities due to the small volume of waste to be managed.

In the long-term, refurbishing or repair of the bridge deck, fly-over, and other concrete surfaces is not expected to alter long-term uses of the bridge or dam.

3.15 Irreversible and Irretrievable Commitments of Resources

This section describes the expected irreversible and irretrievable environmental resource commitments used in the refurbishment of the Wilson Dam bridge deck, fly-over epoxy overlay, expansion joints, and handrails. The term irreversible commitments of resources describe environmental resources that are potentially changed by construction or operation and that could not be restored at some later time to the resource's state prior to construction or operation. For example, the construction of a road through a forest would be an irretrievable commitment of the productivity of timber within the road right of way if the road remains. Irretrievable commitments of resources are generally materials that are used for the refurbished bridge in such a way that they could not, by practical means, be recycled or restored for other uses. For example, mining of ore is an irreversible commitment of a resource; once the ore is removed and used, it cannot be restored. Under Alternative A, no irreversible or irretrievable commitments would occur as the existing bridge would remain unchanged. Under Alternative E, the bridge refurbishment would involve irreversible commitment of fuel, energy, and concrete, overlay, and painting material resources.

3.16 Cumulative Effects

CEQ regulations for implementing the procedural provisions of the NEPA of 1969, as amended (42 USC § 321 et seq.) define cumulative impact as: "...the impact on the environment which results from the incremental impact of the action when added to other past, present and reasonably foreseeable future actions regardless of what agency (federal or nonfederal) or person undertakes such other actions" (40 CFR § 1508.7).

The proposed action identified under Alternative E would occur on land that was previously disturbed and is used for transportation, water storage, and energy generating purposes. Consequently, the potential for direct and indirect effects from project activities is generally low. For resources where no direct or indirect effects were identified, there would be no cumulative effects.

Unless otherwise stated, the geographic scope of analysis is assumed to include a 5-mile radius around the Wilson Dam. This is the area in which indirect and cumulative effects are expected to occur. This area is largely defined by urban and suburban land use, water features including Wilson Reservoir, and agricultural and forested lands in unincorporated areas.

Past, present and reasonably foreseeable future actions were identified within the 5-mile radius and include the following:

- Commercial, and industrial development in Florence (e.g., Underwood Baptist Church student building, Florence; University of North Alabama renovations to historic Strickland Building).
- American Paper & Twine started construction in 2019 of a 30,000 square foot facility in Shoals Research Airpark in Muscle Shoals.
- The Alabama Department of Transportation (ALDOT) is finishing up work on a section of AL 133 south of the Singing River Bridge in 2019.
- In 2019, ALDOT will widen a section of U.S. 43 to four lanes and add a turning lane. The work is from AL 64 north to the Tennessee state line (Lauderdale County).
- In 2019, ALDOT will replace two bridges at the Ash Boulevard overpass on Hatch Boulevard in Sheffield.
- In 2020, ALDOT will replace the overpass on Mitchell Boulevard at Coffee Road in Florence.

As shown in Table 3-3, the cumulative impacts associated with the proposed action in combination with the above identified actions would be insignificant.

	Table 5-5. Cumulative impacts
Resource Area	Alternative E – Repair Scheme D
Air Quality	Minor, short-term cumulative impacts. The temporary construction-related air emissions are not expected to result in any changes to NAAQS attainment.
Climate	Minor, short-term cumulative impacts.
Surface Water	Minor, short-term cumulative impacts due to the confined scale of the construction activities and the BMP minimization measures that would be implemented to minimize impacts to water quality. No long-term water quality or ecological health impacts are anticipated.
Wildlife	No cumulative impacts.
Threatened and Endangered Species	No cumulative impacts.
Solid and Hazardous Waste	Minor short- and long-term cumulative impacts due to the small waste volumes generated and the regional solid waste management capacity. The capability of regional waste management facilities to continue accepting waste would not be compromised.
Visual	Short- and long-term beneficial cumulative impacts on the visual landscape as it restores the visual qualities of the current Wilson Dam and bridge. This would result in long-term cumulative effects if other nearby restoration or preservation actions are undertaken.
Cultural and Historic Resources	No cumulative impacts.
Recreation	Minor, short-term cumulative impacts on recreation due to temporary construction detour. No long-term cumulative impacts to nearby recreation facilities are anticipated.
Transportation	Minor, short-term cumulative impacts to vehicle traffic due to temporary construction detour that would occur simultaneously with other transportation improvement and development projects and their traffic impacts. No cumulative impacts anticipated on air, railroad, or barge transportation.
Noise	Minor, short-term cumulative noise impacts.
Socioeconomic and Environmental Justice	Minor, short-term, beneficial cumulative impacts from the temporary employment of a construction workforce. The proposed action is not expected to contribute to cumulative impacts on environmental justice.

CHAPTER 4 – LIST OF PREPARERS

4.1 NEPA Project Management

Name: Education: Project Role:	Ashley Pilakowski B.S., Environmental Management NEPA compliance, document preparation and project management
Experience:	8 years in environmental planning and policy and NEPA compliance.
Name:	Lori Whitehorse
Education:	B.S., Plant and Soil Science
Project Role:	TVA Environmental Program Manager
Experience:	15 years of environmental regulatory compliance
Name:	Marty Marchaterre (Copperhead)
Education:	J.D., Law; B.A., History and Political Science
Project Role:	Project Manager, NEPA Coordinator
Experience:	28 years of experience in NEPA document preparation.

4.2 Other Contributors

Name: Education: Project Role: Experience:	Michael Bradley M.S., Communications Strategic Communications Partner 20 years involved in engineering, science, environmental, and energy communications
Name:	Ben Byard
Education:	B.S., M.S, and PhD. Civil Engineering
Project Role:	FAM Bridge Program Manager
Experience:	12 years of structural engineering experience
Name:	John Day
	•
Education:	B.A., Business
Education: Project Role:	B.A., Business Facilities Program Manager
Education:	B.A., Business
Education: Project Role:	B.A., Business Facilities Program Manager
Education: Project Role: Experience:	B.A., Business Facilities Program Manager 20 years of project management experience
Education: Project Role: Experience: Name:	 B.A., Business Facilities Program Manager 20 years of project management experience Elizabeth B. Hamrick
Education: Project Role: Experience: Name: Education:	 B.A., Business Facilities Program Manager 20 years of project management experience Elizabeth B. Hamrick M.S., Wildlife and B.S. Biology Terrestrial Ecology (Animals), Terrestrial Threatened and

Name: Education:	Hailie A. Hearnes M.A., Public History (Historic Preservation) and B.S., Historic Preservation
Project Role: Experience:	Architectural Historian, Cultural Compliance 11 years performing historic architectural surveys, NRHP assessments, condition assessments, and documentation for NHPA compliance
Name: Education: Project Role: Experience:	Venita Perkins B.S., Chemical Engineering Environmental Scientist 17 years of environmental work
Name: Education: Project Role: Experience:	 A. Chevales Williams B.S., Environmental Engineering Surface Water 13 years of experience in water quality monitoring and compliance; 10 years of NEPA planning and environmental services
Name: Education:	Richard Borthwick (Copperhead) PhD, Biology (Candidate); M.S., Biology and Ecology; B.S., Natural Resource and Environmental Management and Wildlife and Fisheries
Project Role: Experience:	Wildlife, Threatened and Endangered Species 10 years of experience performing environmental assessments and field surveys.
Name: Education: Project Role: Experience:	Kelsie Eshler (Copperhead) B.A., Environmental Earth Science Solid and Hazardous Waste; Transportation 3 years of experience performing environmental assessments and field surveys.
Name: Education: Project Role: Experience:	Chris McNees (Copperhead) B.S., Environmental Studies Geographic Information Systems 15 years of experience in restoration, remediation, spatial analysis, sample collection, lab analysis, and habitat assessments.
Name: Education:	Drew Vankat (Copperhead) M.S., Environmental Policy and Planning and B.Phil., Urban and Environmental Planning
Project Role:	Socioeconomics and Environmental Justice, Recreation, Surface Water, QA/QC
Experience:	12 years of experience with environmental policy including NEPA document preparation.

CHAPTER 5 – ENVIRONMENTAL ASSESSMENT RECIPIENTS

5.1 Federal Agencies

National Park Service, Secretary of the Interior

5.2 Federally Recognized Tribes

Absentee Shawnee Tribe of Oklahoma

Alabama-Coushatta Tribe of Texas

Alabama-Quassarte Tribal Town

Cherokee Nation

The Chickasaw Nation

Coushatta Tribe of Louisiana

Eastern Band of Cherokee Indians

Eastern Shawnee Tribe of Oklahoma

Jena Band of Choctaw Indians

Kialegee Tribal Town

The Muscogee (Creek) Nation

Poarch Band of Creek Indians

The Seminole Nation of Oklahoma

Shawnee Tribe

Thlopthlocco Tribal Town of Oklahoma

United Keetoowah Band of Cherokee Indians in Oklahoma

5.3 State Agencies

Alabama Historical Commission, State Historic Preservation Officer

Alabama Department of Environmental Management

Alabama Department of Transportation

This page intentionally left blank

CHAPTER 6 – LITERATURE CITED

- Alabama Department of Environmental Management (ADEM). 2018. Final 2018 303(d) List. Available online at <u>http://www.adem.state.al.us/programs/water/wquality/2018AL303dList.pdf</u>. Accessed March 2019.
- Alabama Department of Transportation. 2017. Traffic Data AL 133 just north of Singing Bridge. 2017. Internet website: <u>https://aldotgis.dot.state.al.us/atd/default.aspx</u>. Accessed in February 2019.
- Bonnington, C., and D. Smith. 2018. Do bridge construction activities influence birds using the River Mersey, in northwest England. Bird Study, 65(3), published online.
- eBird. 2012. eBird: An online database of bird distribution and abundance. Ithaca, New York. Available online at <u>https://ebird.org/home</u>. Accessed on February 14, 2019.
- Federal Highway Administration. 1991. Patton Island Bridge and Approaches Crossing the Tennessee River and Connecting the Cities of Florence and Muscle Shoals Environmental Impact Statement.
- _____. 2017. Construction Noise Handbook. Chapter 9.0 Construction Equipment Noise Levels and Ranges. Updated August 24, 2017. Available at <u>https://www.fhwa.dot.gov/Environment/noise/construction_noise/handbook/handbobk/handbook/handbobk/handbook/handbok</u>
- National Land Cover Dataset. 2011. Multi-Resolution Land Characteristics Consortium. Research Triangle Park, NC. Internet website: <u>https://catalog.data.gov/dataset/national-land-cover-database-nlcd-land-covercollection</u>. Accessed in February 2019.
- Pietak, Lynn Marie, Aaron Deter-Wolf, Ruth Nichols, Jim D'Angelo, and Kristin Wilson. 2002 Cultural Resources Survey for the Muscle Shoals Reservation, Lauderdale and Colbert Counties, Alabama. Submitted to the Tennessee Valley Authority by TRC, Atlanta, Georgia.
- Rettig, Polly M. and Horace J. Sheely, Jr. 1976 Wilson Dam, National Register of Historic Places Inventory – Nomination Form, United States Department of the Interior, National Park Service, Washington, D.C.
- Shoals Area Metropolitan Planning Organizations. 2010. 2035 Long Range Transportation Plan. May 2010. Available at: <u>https://www.nacolg.org/images/pdf/Shoals_LRTP.pdf</u>. Accessed in February 2019.

Shoals Economic Development Authority. 2019. The Shoals March 2019 E-Bulletin.

- TVA. 1996. Muscle Shoals/Wilson Dam Reservation Land Use Plan EA. Muscle Shoals, AL.
- _____. 2002. River Heritage Hotel Environmental Assessment.

- _____. 2011. Muscle Shoals Reservation Redevelopment Final Environmental Impact Statement.
- _____. 2015. Muscle Shoals Outdoor Education and Recreation Area Improvements Environmental Assessment.
- _____. 2019a. Muscle Shoals Power Service Shop Warehouse EA. Muscle Shoals, AL.
- _____. 2019b. 2019 Integrated Resource Plan Environmental Impact Statement. Knoxville, TN.
- _____. 2019c.Letter to National Historic Landmarks Program, National Park Service Concerning Wilson Dam Bridge Rehabilitation.
- US Army Corps of Engineers. 2008. Wilson Dam Bascule Bridge Replacement Environmental Assessment.


US Census. 2019. QuickFacts. Internet website: <u>https://www.census.gov/quickfacts/fact/table/US/PST045218</u>. Accessed on February 6, 2019. Appendix A – Wilson Dam Bridge Deck Refurbishment Design

This page intentionally left blank

TENNESSEE VALLEY AUTHORITY WILSON DAM BRIDGE DECK REPLACEMENT

INDEX OF SHEETS

DESCRIPTION	SHEE	ΞT	Ν
TITLE GENERAL NOTES ESTIMATED QUANTITIES	_ 2 - _ 3	- 2	2 A
STAGING AREA TRAFFIC CONTROL LAYOUT DECK REPAIR TYPICAL SECTION	_ 4A _ 5 -	- 8	3
DECK REPAIR DETAILS DECK REPLACEMENT TYPICAL SECTION DECK REPLACEMENT DETAILS	10	_	13
SIDEWALK ¢ CURB REPAIR DETAILS RAIL REPAIR DETAILS	14		
ARCH REPAIR DETAILS GENERAL REPAIR DETAILS DRAINAGE REPAIR DETAILS	19	-	18



LOCATION MAP

GENERAL NOTES

DESCRIPTION OF THE WORK:

THE SCOPE OF WORK SHALL INCLUDE THE FOLLOWING:

- 1. INSTALL BRIDGE CLOSURE SIGNS AS SHOWN ON SHEET NO. 4A.
- 2. REMOVE THE EXISTING CONCRETE BRIDGE DECK WITHIN THE LMITS SHOWN IN THE PLANS.
- CONSTRUCT NEW REINFORCED CONCRETE BRIDGE DECK.
- 4. REPLACE OR RESEAL BRIDGE DECK JOINTS AT LOCATIONS NOTED 5. SEAL LONGITUDINAL CONSTRUCTION JOINT BETWEEN EXISTING
- CONCRETE CURBS AND NEW CONCRETE BRIDGE DECK.
- 6. PATCH DETERIORATED ARCH FACES.
- 7. REMOVE AND REPLACE DEFECTIVE AREAS OF EXISTING BRIDGE RAILS AND SIDEWALKS.
- 8. REPAIR DETACHED DRAIN PIPE AT ONE LOCATION.
- REMOVE TOP 1.5" OF DECK CONCRETE AND PERFORM FULL DEPTH DECK REPAIRS AT LOCATIONS NOTED IN THE PLANS OR AS DIRECTED BY THE ENGINEER.
- 10. CONSTRUCT A POLYMER MODIFIED CONCRETE OVERLAY AT LOCATIONS NOTED IN THE PLANS.
- REPLACE MISSING OR DAMAGED CURB IRONS AS DIRECTED BY THE ENGINEER.

DEFINITIONS:

WHENEVER THE FOLLOWING TERMS ARE USED IN THE PLANS, IT IS UNDERSTOOD THAT THEY REPRESENT THE FOLLOWING:

- A. CONTRACTOR: ENTITY RESPONSIBLE FOR CONSTRUCTION
- B. ENGINEER/ENGINEER OF RECORD DESIGN ENGINEER, TVA BRIDGE MANAGER, OR THEIR DESIGNATED REPRESENTATIVE
- C. OWNER: TENNESSEE VALLEY AUTHORITY (TVA)
- D. TVA CONSTRUCTION MANAGER: REFERS TO AN INDIVIDUAL EMPLOYED BY TVA FOR COORDINATION OF CONSTRUCTION ACTIVITIES
- E. CONSTRUCTION QUALITY ASSURANCE (CQA) MANAGER: THE CQA MANAGER IS A QUALIFIED PROFESSIONAL ENGINEER RESPONSELE FOR EXECUTION OF THE CQA AND RELATED DOCUMENTATION AS OUTLINED IN THE CMP.

SPECIFICATIONS:

03:34

- ALL WORK ON THIS PROJECT SHALL BE DONE IN ACCORDANCE WITH THE CONTRACT DOCUMENTS AND THE 2018 EDITION OF THE ALABAMA DEPARTMENT OF TRANSPORTATION STANDARD SPECIFICATIONS FOR HIGHWAY CONSTRUCTION APPLICABLE SPECIAL PROVISIONS, AND TECHNICAL SPECIFICATIONS.
- ADDITIONAL NOTES MAY BE FOUND ON THE SUBSEQUENT SHEETS OF THE CONTRACT PLANS, AND SUCH NOTES SUPPLEMENT THE GENERAL NOTES GIVEN ON THIS SHEET.

CONTRACTOR ACTIVITIES:

- THE CONTRACTOR SHALL ADHERE TO THESE PLANS FOR CONSTRUCTION, ALONG WITH THE OMP, COC PLAN, AND OTHER REFERENCED SPECIFICATIONS, STANDARDS, AND APPLICABLE ENVIRONMENTAL AND SAFETY REGULATIONS DURING THE PROJECT ENVIRONMENTAL AND SAFETY REGULATIONS DURING THE PROJECT ENVIRONMENTAL AND SAFETY REGULATIONS DURING THE PROJECT
- ACCESS TO THE SITE, STORAGE, AND STAGING AREAS, SHALL EE DETERMINED BY TVA. CONTRACTOR SHALL COORDINATE CONSTRUCTION ACCESS AND STAGING AREAS PRIOR TO THE START OF WORK.
- THE CONTRACTOR'S MOBILIZATION SHALL INCLUDE, BUT IS NOT LIMITED TO, THE PURCHASE OF INSURANCE: PREPARATION OF REQUIRED SUBMITTALS FOR APPROVAL, TRANSPORTATION OF PERSONNEL, EQUIPMENT, AND SUPPLIES TO THE STE, IAID PROCURING BADGES, BACKGROUND CHECKS, AND ORIENTATION TRAINING FOR WORKERS AS REQUIRED BY TVA.
- THE CONTRACTOR SHALL BID WITH THE UNDERSTANDING THAT CONSTRUCTION ACTIVITIES MAY BE HALTED IF DEEMED NECESSARY TO ENSURE PLANT OPERATIONS, REPAR PLANT EQUIPMENT ETC.
- 5. THE CONTRACTOR SHALL COORDINATE WORK ACTIVITIES AS NEEDED WITH THE SPILLWAY OPERATIONS. THE CONTRACTOR IS ALERTED TO THE POSSIBILITY THAT SPILLWAY OPERATIONS MAY CAUSE ADDITIONAL MOISTURE ON THE CONCRETE SURFACES THAT MAY AFFECT CONCRETE POURS. THE CONTRACTOR IS SOLELY RESPONSIBLE FOR ENSURING THAT ALL MATERIALS ARE PLAGED IN & MARNER WHCH CONFORMS WITH THE MATERIAL SARE PLAGED IN & MARNER WHCH CONFORMS WITH THE MATERIAL MANUFACTURER'S RECOMMENDATIONS.

- 6. THE CONTRACTOR SHALL BE RESPONSIBLE FOR THE MINITENANCE OF ALL ACCESS ROADS, STAGING AREAS, AND STORAGE AREAS USED DURING CONSTRUCTION AND SHALL RESTORE SAID AREAS TO THEIR ORIGINAL CONDITION OR BETTER ONCE CONSTRUCTION ON IS COMPLETE UNLESS THE TVA CONSTRUCTION MANAGER PROVIDES WRITTEN PERMISSION TO THE CONTRACTOR TO LEAVE THE AREA "AS-IS" UPON COMPLETION OF THE PROJECT. THE CONTRACTOR SHALL REMOVE ALL PERSONNEL AND EQUIPMENT FROM THE CONTRACTOR DURING ANY TEMPORARY (TEMS) INSTALLED BY THE CONTRACTOR DURING THE COURSE OF THEIR WORK. THE SITE SHALL BE LEFT IN A CONDITION ACCEPTABLE TO THE OWNER WITH ALL TRASH AND DEBRIS REMOVED.
- THE WORK LIMITS ARE SHOWN ON THE CONSTRUCTION PLANS. THE CONTRACTOR SHALL NOT WORK OR USE AREAS OUTSIDE THE WORK LIMITS. AREAS WIT-IIN THE WORK LIMITS SHALL BE MAINTAINED BY THE CONTRACTOR DURING CONSTRUCTION. THE CONTRACTOR SHALL BE RESPONSIBLE FOR SITE SECURITY AND PROTECTION OF THE WORK AREA.
- SITE WORK SHALL BE ACCOMPLISHED IN A MANNER THAT WILL NOT RESULT IN DAMAGE TO EXISTING STRUCTURES, PAVEMENTS, SURVEY MONUMENTS, INSTRUMENTATION, TREES, OR LANDSCAPING THAT IS NOT DESIGNATED FOR REMOVAL. SITE USAGE: ACCESS IMPROVEMENTS, TEMPORARY DRAINAGE, AND EROSION CONTROL MEASURES SHALL BE SUBMITTED TO THE ENGINEER FOR ACCEPTANCE.
- MATERIALS DELIVERED FOR INCORPORATION NTO THE WORK SHALL BE TEMPORARILY STORED IN THE STAGING AREA NOTED ON SHEET 4. MATERIALS CHALL BE STORED IN ACCORDANCE WITH THE MANUFACTURER'S RECOMMENDATIONS.
- 10. BLASTING IS NOT FERMITTED ON THE PROJECT SITE
- 11. THE CONTRACTOR SHALL BE RESPONSIBLE FCR THE HEALTH AND SAFETY CF ITS PERSONNEL AND SHALL MEET NDUSTRY STANDARD REQUIREMENTS. THE CONTRACTOR SHALL ADHERE TO THE OWNER'S REQUIREMENTS FOR SAFETY DURING CONSTRUCTION, UNLESS SUCH STANDARDS ARE SUPPRECEDED BY REQUILTORY REQUIREMENTS. OPERATIONS SHALL BE PERFORMED BY THE CONTRACTOR IN STRICT ACCORDANCE WITH TWA SAFETY STANDARDS AND OCUPATIONAL SAFETY AND HEACHT ADMINISTRATION (OSHA) REQUIREMENTS.
- 12. THE CONTRACTOR SHALL COMMUNICATE CONSTRUCT/BULTY ISSUES OR DISCREPANCIES IN THE CONSTRUCTION DOCUMENTS TO THE COA MANAGER AND TVA CONSTRUCTION MANAGER IMMEDIATELY UPON BECOMING AWARE THE CONTRACTOR SHALL USE THE OWNER'S REQUESTFOR INFORMATION (RF) FOR THAT ISS CONTAINED IN THE OMP TO COMMUNICATE AND ESTABLISH WRITTEN DOCUMENTATION OF THE ISSUE AND ITS RESOLUTION.
- 13 CONSTRUCTION ACTIVITIES SHALL BE OBSERVED BY THE COA MANAGER DR A DESIGNATED REPRESENTATIVE ON THE COA TEAM. THE CONTRACTOR SHALL COORDINATE WITH THE COA REPRESENTATIVE AND INFORM THE REPRESENTATIVE OF THE COATRACTOR'S SCHEDULED WORK SHIFTS TO ENSURE THAT COA REPRESENTATION OCCURS AS RECURED. THE COA TEAM WILL OBSERVE CONSTRUCTION ACTIVITIES AS RECURED. THE COA TEAM WILL OBSERVE CONSTRUCTION ACTIVITIES AS RECURED.
- 14. VERIFY ALL DIMENSIONS AND GEOMETRY OF THE EXISTING STRUCTURE IN THE FIELD AS NECESSARY FOR PROPER FIT OF PROPOSED CONSTRUCTION PRIOR TO THE FABRICATION OF ANY COMPONENT.
- THE CONTRACTOR SHALL COORDINATE WITH THE TVA CONSTRUCTION MANAGER AND ALABAMA 811 TO LOCATE AND VERIEV ALL UTILITIES PRIOR TO CONSTRUCTION TO ENSURE THERE IS NO CONFLICT WITH THE WORK.
- 16. ONSITE UTILITIES AND UNDERGROUND FACILITIES, WHETHER SHOWN ON THE PLANS OR NOT, SHALL BE PROTECTED BY THE CONTRACTOR FROM DAMAGE BY THE CONTRACTOR'S OPERATIONS, IF DAMAGE OCCURS, THE CONTRACTOR SHALL COORDINATE REPARS WITH THE TVA CONSTRUCTION MANAGER. THE CONTRACTOR SHALL BE RESPONSIBLE FOR ANY DAMAGE ATTRIBUTED TO THE CONTRACTOR'S OPERATIONS.
- PROPOSED MODIFICATIONS TO DESIGN FEATURES AS SHOWN (OR DESCRIBED) IN THE ISSUED FOR CONSTRUCTION DESIGN DOCUMENTS SHALL BE APPROVID BY THE LANSIMER OF RECORD TEMPORARY FEATURES IMPLEMENTED TO FACILITATE CONSTRUCTION SHALL BE DESCRIBED IN APPROVED PROJECT DOCUMENTS.
- VEHICULAR ACCESS TO THE SITE SHALL BE DETERMINED BY TVA. BRIDGE CLOSED SIGNS SHALL BE PLACED AS SHOWN IN THE PLANS. THE BRIDGE WILL BE CLOSED BY TVA UTILIZING EXISTING GATES.
- 19. THE CONTRACTOR IS RESPONSIBLE FOR PROTECTION OF THE WORKSITE FROM UNAUTHORIZED PERSONNEL AT ALL TIMES DURING CONSTRUCTION
- 20. A PERMITSHALL BE OBTAINED FROM TVA PRIOR TO ANY WORK REQUIRING DRILLING OR CHIPPING INTO CONCRETE MORE THAN 5 INCHES.

- ADDITIONAL REPAIR WORK MAY BE REQUIRED AS THE CONTRACT PROGRESSES WHICH IS NOT SHOWN ON THESE PLANS, WORK WILL BE AS DIRECTED BY THE ENGINEER, PAYMENT WILL BE MADE AT AN AGREED UPON PRICE.
- CONCRETE TO BE CLASS "A" IN ADDORDANCE WITH THE STANDARD SPECIFICATIONS, EXCEPT BRDGE DECK CONCRETE SHALL BE IN ACCORDANCE WITH TECHNICAL SPECIFICATION 1.
- 23. CONCRETE SURFACE FINISH: CLASS 3 FINISH SHALL APPLY TO THIS SITE.
- 24. ALL CONCRETE IN REPAIR AREAS SHALL BE CURED IN ACCORDANCE WITH THE STANDARD SPECIFICATIONS.
- BRIDGE DECK SURFACE FINISH SHALL CONFORM TO THE REQUIREMENTS IN THE STANDARD SPECIFICATIONS.
- THE CONTRACTOR SHALL PROVIDE 100% CONVENTIONAL FALL PROTECTION FOR WORKERS WHERE REQUIRED BY OSHA REQUIREMENTS.
- 27. HORIZONTALLY ORILLED HOLES SHALL BE DRILLED %' IN DIAMETER LARGER THAN THE BAR, CLEAVED, PACKED WITH NON-SHRINK GROUT, AND THE BAR ROTATED (NOT SRIVEN) TO ITS SEAT. VERTICALLY DRILLED HOLES SHALL BE DRILLED %' IN DIAMETER LARGER THAN THE BAR, CLEANED, PACKED WITHEPOXY GROUT, NOT THE BAR SHALL BE DRIVEN TO ITS SEAT. ALL GROUTING MATERIAL SHALL BE APPROVED BY THE ENGINEER.
- 28. CONCRETE FORM WORK, FALSEWORK, AND TEMPORARY SUPPORTS SHALL BE REMOVED FROM THE JOB SITE AFTER WORK IS COMPLETED. COST OF FORMS, FALSEWORK, AND TEMPORARY SUPPORT SHALL BE INCLUDED IN ITEMS BID ON. THIS WORK SHALL BE COMPLETED BEFORE FINAL PAYMENT IS APPROVEC.
- STRUCTURAL STEEL SHALL CONFORM TO AASHTO M270 GRADE 36 (ASTM A709 GRADE 36) UNLESS OTHERWISE NOTED.
- CARE SHALL BE TAKEN WHILE REMOVING AND REPAIRING BRIDGE COMPONENTS SO AS NOT TO DISTURB OR DAMAGE ANY UTILITIES.
- 31. CONTRACTOR SHALL TAKE PFECALITION TO NOT DAMAGE OR BLOCK EXISTING DECK DRAINS. ANY DAMAGE OR BLOCKAGE TO EXISTING DECK DRAINS SHALL BE REPARED AT THE CONTRACTOR'S EXPENSE. DURING DECK POURS, DRAINS SHALL BE PROTECTED TO PREVENT WET CONCRUE F REVIN BUT REURING THE DRAIN.
- 32. THE CONTRACTOR SHALL TAKE SPECIAL CARE TO PROTECT ANY PARTS OF THE STRUCTURE THAT ARE NOT TO BE REMOVED SPECIFICALLY. THE CONTRACTOR IS NOT ALLOWED TO USE A HYDRAULIC RAM MOUNTED ON A BACKHOE (COMMONLY CALLED A HOE RAM), MINI EXCAVATOR, OR OTHER EQUIVALENT FOR CONCRETE REMOVAL ON PORTIONS OF THE STRUCTURE TO REMAIN IN SERVICE. ALL DEVICES PROPOSED FOR CONCRETE DEMOLITION SHALL MEET THE APPROVAL OF THE ENGINEER.
- 33. THE CONTRACTOR IS RESPONSIBLE FOR AND SHOULD TAKE ALL PRECAUTIONS TO ENSURE THE STABILITY OF THE STRUCTURE DURING THE REPAIRS. THE CONTRACTOR SHALL BE SOLELY RESPONSIBLE FOR THE STABILITY OF THE STRUCTURE DURING REPAIR AND CONSTRUCTION.
- ALCONTRAVERSING AND ADDRESS AN
- 35. THE CONTRACTOR SHALL FIELD VERIFY ALL DIMENSIONS AND QUANTITIES BEFORE ORDERING ANY MATERIALS.
- 36 NOTHING IN THE GENERAL NCTES OR SPECIAL PROVISIONS SHALL RELIEVE THE CONTRACTOR FROM HIS RESPONSIBILITIES TOWARD THE SAFETY AND CONVENIENCE OF THE GENERAL PUBLIC AND TVA STAFF.
- 37. ALL REPAIR MATERIALS SHALL MATCH THE CURRENT APPEARANCE OF THE STRUCTURE. THE CONTRACTOR SHALL CONSTRUCT 4% MOCC-UPS TO DEMONSTRATE THE APPEARANCE OF THE PROPOSED MATERIALS FOR APPROVAL BY TAX'S FILD REPRESENTATIVE. ALL WORK SHALL MEET THE FULL APPROVAL OF THE FIELD REPRESENTATIVE. THE COST OF CONSTRUCTION MOCK-UPS AND OBTAINING APPROVALS WILL NOT RE PAID DIRECTLY AND SHOULD BE INCLUDED IN THE COST OF CONSTRUCTION MOCK-UPS AND SHALL DIRECT OF OTHER TERMS.



JOB NO. 1012500.17 DATE 11-30-2018 TITLE GENERAL NOTES (1) SHEET NO. 2

GENERAL NOTES CONT.

CONFORMITY WITH PLANS AND CONSTRUCTION TOLERANCES

- ALL WORK PERFORMED AND MATERIALS SUPPLIED SHALL CONFORM TO THE LINES, GRADES, CROSS-SECTIONS, DIMENSIONS, AND MATERIAL REQUIREMENTS, AS SHOWN ON THE PLANS FOR CONSTRUCTION.
- 2. THE CONTRACTOR SHALL BE RESPONSIBLE FOR CONSTRUCTION SURVEYING AND FIELD MEASUREMENTS TO VERIFY CONFORMANCE WITH LINES, GRADES, CRGSS-SECTIONS, DIMENSIONS, AND TOLERANCES SHOWN ON THESE PLANS FOR CONSTRUCTION. SURVEYING AND FIELD MEASUREMENTS SHALL BE PERFORMED AT APPROPRIMET TIMES THROUGHOUT CONSTRUCTION TO VERIFY PLAN CONFORMANCE AND TO PROVIDE THE NECESSARY DATA FOR PREPARATION OF RECORD DRAWINGS. THE CONTRACTOR SHALL PROVIDE AS-BUILT RECORDS OF THE CONSTRUCTED PROJECT TO THE ENGINEER UPON COMPLETION OF CONSTRUCTED PROJECT TO BE VERIFIED AND/OR MEASURED BY SURVEYING SHALL INCLUDE, EUT NOT BE LIMITE TO., THE FOLLOWING:
 - a. ALIGNMENT DIMENSIONS AND ELEVATIONS OF STRUCTURES AT ONE FOOT INTERVALS.
 - OTHER ITEMS DEEMED NECESSARY BY THE COA TEAM AND/OR CONTRACTOR TO VERIFY PLAN CONFORMANCE AND CONSTRUCTION TOLERANCES.
- ACCEPTABLE CONSTRUCTION TOLERANCES FROM PLAN DIMENSIONS, ELEVATIONS, AND GRADES SHALL BE AS FOLLOWS:
 - a. HORIZONTAL: +/- 1/8 INCH
 - b. VERTICAL: +/- 1/8 NGH

QUALITY CONTROL:

- 1. QUALITY CONTROL REQUIREMENTS SHALL BE DETAILED IN THE QUALITY MANAGEMENT PLAN (OMP) AND CONSTRUCTION QUAL TY MANAGEMENT PLAN (COMP)
- 2. CERTIFICATIONS OF MATERIAL QUALITY AND CONFORMANCE TO PROJECT REQUIREMENTS SHALL BE SUBMITTED TO THE ENGINEER

SPECIAL ENVIRONMENTAL NOTES TO CONTRACTOR:

- CONTRACTOR SHALL USE SKTREME CARE AND TAKE ANY MEASURE NECESSARY TO ENSURE THAT NO DEBRIS IS DROPPED INTO THE RIVER BELOW. THIS SHALL BE ACCOMPLISHED BY THE USE OF BASKETS, NEITING, WEAPPING, WORK PLATFORMS, OR OTHER SIMILARLY EFFECTIVE MEANS. ANY DEBRIS WHICH IS ALLOWED TO DROP ON THE BANKS BELOW THE BRIDGE SHALL NOT BE ALLOWED TO DROP ON THE WATER AND SHALL BE REMOVED AND DISPOSING OF BY THE CONTRACTOR. COST OF REMOVING AND DISPOSING OF DEBRIS SHALL BE INCLUBED IN OTHER ITEMS BIO ON.
- ALL GLEANING MATERIALS SUPFACTANTS, CHEMICALS, AND FINSATE WATER SHALL BE COLLECTED AND PROPERLY DISCOSED AND NOT DISCHARGED TO THE TENNESSEE RIVER. ANY PAINT SCRAPINGS AND/OR OTHER SOLID MATERIAL SHOULD ALSO BE COLLECTED AND PROPERLY DISPOSED.
- ALL WASH, DEBRIS, AND PAINT WILL HAVE A CONTAINMENT SYSTEM IN PLACE WHILE REPARTING THE BRIDGE. NO DUST, SPRAY, OR PANT MAY ENTER THE STREAM.
- CONCRETE AND FUGITIVE CONCRETE DUST SHOULD BE PREVENTED FROM ENTERING THE RECEIVING WATERS BENEATH THE PROJECT AREA.
- FRESHLY POURED CONCRETE SHALL NOT BE ALLOWED TO COME IN CONTACT WITH THE RIVER WATER.
- ANY AREA THAT IS DISTURBED OUTSIDE LIMITS OF CONSTRUCTION DURING THE LIFE OF THIS PROJECT SHALL BE REPAIRED BY THE CONTRACTOR AT HIS EXPENSE.

SEDIMENT CONTROL:

03:34

-NA jec

- 1. TEMPORARY EPSC MEASURES MAY BE REMOVED AT THE BEGINNING OF THE WORKDAY BUT MUST BE REINSTALLED AT THE END OF THE WORKDAY OR BEFORE/DURING A PRECIPITATION EVENT.
- 2. THE CONTRACTOR SHALL ESTABLISH AND MAINTAIN A PROACTIVE METHOD TO PREVENT THE OFFSITE MIGRATION OR DEPOSIT OF SEDIMENT OFF THE PROJECT LIMITS (E.G. R.O.W., EASEMENTS, ETC.), INTO WATERS OF THE STATEULS. OR ONTO ROADWAYS USED BY THE GENERAL PUBLIC. IF SEDIMENT ESCAPES THE CONSTRUCTION SITE, OFFSITE ACCUMULATIONS OF SEDIMENT THAT HAVE NOT REACHED A STREAM MUST BE REMOVED AT A FREQUENCY SUFFICIENT TO MINIMIZE OFFSITE IMPACTS (E.G., FUDITY ESCIMENT THAT HAVE NOT REACHED A STREAM MUST BE REMOVED AT A FREQUENCY SUFFICIENT TO MINIMIZE OFFSITE IMPACTS (E.G., FUDITY ESCIMENT THAT HAS ESCAPED THE CONSTRUCTION SITE AND HAS COLLECTED IN A STREET MUST BE REMOVED SO THAT IT IS NOT SUBSEQUENTLY WASHED INTO STORM SEWERS AND STREAMS BY THE NEXT RAIN ANDOR SO THATI TO DOES NOT POSE A SAFETY HAZARD TO USERS OF FUBLIC STREETS). ARRANGEMENTS CONCERNING REMOVAL OF SEDIMENT ON AUDINING PROPERTY MUST BE NEGOTIATED WITH THE ADJOINING PROPERTY OWNER BEFORE REMOVAL OF SEDIMENT.

 OFFSITE VENICLE "TRACKING OF SEDIMENTS AND THE GENERATION OF DUST SHALL BE MINIMIZED. A STABILIZED CONSTRUCTION EXIT (A POINT OF ENTRANGE/EXIT TO THE CONSTRUCTION PROJECT) SHALL BE PROVIDED TO REDUCE THE TRACKING OF MUD AND DIRT ONTO PUBLIC ROADS BY CONSTRUCTION VEHICLES.

GOOD HOUSEKEEPING MEASURES & WASTE DISPOSAL

- THE CONTRACTOR SHALL ESTABLISH AND MAINTAIN A PROACTIVE METHOD TO PREVENT LITTER AND CONSTRUCTION WATERS FROM ENTERING WATERS OF THE TENDESSEE RIVER. THESE MATERIALS SHALL RE FEMOLED FROM STORMWATER EXPOSIBLE PRIOR TO ANTICIPATED STORM EVENTS OR BEFORE BEING CARRIED OFFSITE BY WIND, OR OTHERWISE PREVENTED FROM BECOMING A POLLUTANT SOURCE FOR STORMWATER DISCHARGES. AFTER USE, MATERIALS USED FOR ESPC SHALL BE REMOVED FROM THE SITE.
- THE CONTRACTOR SHALL TAKE APPROPRIATE STEPS TO ENSURE THAT PETROLEUM PRODUCTS OR OTHER CHEMICAL POLLUTATS ARE PREVENTED FROM ENTERING WHERS OF THE STATEJUS. ALL EQUIPMENT REFUELING, SERVICING, MACHINERY, AND STAGING AREAS SHALL COMPLY WITH ALL LOCAL, STATE, FEDERAL, AND TVA LAWS, RULES, REGULATIONS, AND ORDINANCES, INCLUDING THOSE OF THE NATIONAL FIRE PROTECTION ASSOCIATION. AFPROPRIATE CONTAINMENT MEASURES FOR THESE AREAS SHALL BE USED.
- CONTRACTORS SHALL PROVIDE DESIGNATED TRUCK WASHOUT AREAS ON THE STE. THESE AREAS MUST BE SELF CONTAINED. NOT CONNECTED TO ANY STORMWATER OUTLET OF THE SITE, AND PROPERLY SIGNEY. WASH DOWN OR WASTE DISCHARGE OF CONCRETE TRUCKS SHALL NOT BE PERMITTED ONSITE UNLESS PROPER SETTLEMENT AREAS HAVE BEEN PROVIDED IN ACCORDANCE WITH BOTH LOCAL, STATE, FEDERAL, AND TVA REGULATIONS.
- WHEEL WASH WATER SHALL BE COLLECTED AND ALLOWED TO SETTLE OUT SUSPENDED SOLIDS PRIOR TO DISCHARGE. WHEEL WASH WATER SHALL NOT BE DISCHARGED DIRECTLY INTO ANY STORMWATER SYSTEM OR STORMWATER TREATMENT SYSTEM.
- PORTABLE SANITARY FACILITIES SHALL BE PROVIDED ONSITE BY THE CONTRACTOR, SMITLARY WASTE SHALL BE COLLECTED FROM THE PORTABLE UNITS IN A TIMELY MANNER BY A LICENSED WASTE MANAGEMENT CONTRACTOR OR AS REQUIRED BY ANY REGULATIONS. THE CONTRACTOR SHALL OBTAIN ANY AND ALL NECESSARY PERMITS TO DISPOSE OF EMITLARY WASTE.
- 6. ONLY CONSTRUCTON PRODUCTS NEEDED SHALL BE STORED ONSITE BY THE CONTRACTOR. THE CONTRACTOR SHALL STORE ALL MATERIALS UNDER COVER AND IN APPROPRIATE CONTAINERS. PRODUCTS MUST BE STORED IN ORIGINAL CONTAINERS AND LABELED. MATERIAL MIXING SHALL BE CONDUCTED IN ACCORDANCE WITH THE MANUFACTURER'S RECOMMENDATIONS. THE CONTRACTOR'S RESPONSIBLE PARTY SHALL INSPECT MATERIAL STORAGE AREAS REGULARLY TO ENSURE PROPER USE AND DISPOSAL.
- WHEN POSSIBLE, ALL PRODUCTS SHALL BE USED COMPLETELY BEFORE PROPERLY DISPOSING OF THE CONTAINER OFFSITE. THE MANUFACTURER'S DIRECTIONS FOR DISPOSAL OF MATERIALS AND CONTAINERS SHALL BE FOLLOWED.
- ALL HAZARDOUS WASTE MATERIALS SHALL BE DISPOSED OF IN A MAINIER WHICH IS COMPLIANT WITH LOCAL, STATE, FEERAL, OR TYA REGULATONS. SITE PERSONNEL SHALL BE INSTRUCTED IN THESE PRACTICES, AND THE INDIVIDUAL DESIGNATED AS THE CONTRACTOR'S RESPONSIBLE PARTY SHALL BE RESPONSIBLE FOR SEEING THAT THESE PRACTICES ARE FOLLOWED. THE CONTRACTOR SHALL OBTAIN ANY AND ALL NECESSARY PERMITS TO DISPOSE OF HAZARDOUS MATERIAL.



JOB NO. 1012500.17

SHEET NO

11-30-2018

GENERAL NOTES (2)

2A

F	ITEM NO.	UNIT	DESCRIPTION	TOTAL
F	206C001	SQ YD	REMOVING CONCRETE PAVEMENT	5,950
	206C012	SQ YD	REMOVING BRIDGE DECK (PARTIAL ONLY)	961
	502A001	LB	STEEL REIMFORCEMENT (GRADE 60)	74,370
	510B001	CU YD	BRIDGE DECK DONCRETE	1,530
	520A100	CU YD	REPAIRS TO EXISTING BRIDGE (PMC OVERLAY)	40
	520A101	SQ YD	REPAIRS TO EXISTING BRIDGE (FULL DEPTH DECK REPAIR)	120
	520A102	LF	REPAIRS TO EXISTING BRIDGE (BRIDGE JOINT SEALING)	3,020
	520A103	SQ FT	REPAIRS TO EXISTING BRIDGE (UNREINFORCED CONCRETE REPAIR AREAS)	3,900
	520A104	SQ FT	REPAIRS TO EXISTING BRIDGE (REINFORCED CONCRETE REPAIR AREAS)	510
	520A105	LS	REPAIRS TO EXISTING BRIDGE (REMOVE AND RESET SIGN)	1
	520A106	LS	REPAIRS TO EXISTING BRIDGE (DRAIN REPAIRS)	1
	520A107	LS	REPAIRS TO EXISTING BRIDGE (TEMPORARY WORK PLATFORM)	1
	520A108	LF	REPAIRS TO EXISTING BRIDGE (CURE IRON REPAIR)	75
	522A000	LF	BRIDGE JOINT SEAL (TYPE "A")	1,060
	522B000	LF	BRIDGE JOINT SEAL (TYPE "B")	45
	522H000	LF	REPLACEMENT OF EXISTING BRIDGE JOINT SEAL	199
	600A000	LS	MOBILIZATION	1
	603A000	EACH	FURNISHING FIELD OFFICE	1
	701A230	MILE	SOLID YELLOW, GLASS 2, TYPE A TRAFFIC STRIPE (5" WIDE)	2
	740B000	SQ FT	CONSTRUCTION SIGNS	50

- FOOTNOTES: (1) INCLUDES ALL COSTS FOR REMOVAL AND DISPOSAL OF BRIDGE DECK CONCRETE FROM MAIN SPANS AND HYDRODEMOLITION REMOVAL OF DETERIORATED MATERIAL BETWEEN ORIGINAL ARCH CONCRETE AND EXISTING BRIDGE DECK.
- (2) INCLUDES ALL COSTS FOR HYDRODEMOLITION OF APPROACH SPANS.
- (3) INCLUDES ALL COSTS FOR PLACEMENT OF REINFORCEMENT IN NEW BRIDGE DECK. ALL BARS SHALL BE EPOXY COATED.
- (4) INCLUDES ALL COSTS FOR PLACEMENT OF NEW BRIDGE DECK CONCRETE CONCRETE SHALL MEET THE REQUIREMENTS OF TECHNICAL BPECIFICATION 1. (5) INCLUDES ALL COSTS FOR PLACEMENT OF NEW POLYMER MODIFIED CONCRETE (PMC) OVERLAY IN
- APPROACH SPANS.
- (6) INCLUDES ALL COSTS FOR REMOVAL AND REPLACEMENT OF BRIDGE DECK CONCRETE IN APPROACH SPANS.
- (7) INCLUDES ALL COSTS FOR PLACEMENT OF A HIGH MOLECULAR WEIGHT METHACRYLATE JOINT SEALANT ALONG CONSTRUCTION JOINT BETWEEN NEW BRIDGE DECK OR PMC OVERLAY AND EXISTING CURBS. (8) INCLUDES COSTS OF REMOVAL AND DISPOSAL OF DETERIORATED CONCRETE, PROVIDING AND INSTALLING
- CONCRETE ANCHORS, PROVIDING AND INSTALLING WELDED WIRE REINFORCEMENT, AND PLACEMENT OF NEW CONCRETE IN ARCH AND SIDEWALK REPAIR AREAS.
- (9) INCLUDES COSTS OF REMOVAL, DISPOSAL, AND REPLACEMENT OF CONCRETE IN REINFORCED CONCRETE REPAIR AREAS, ALSO INCLUDES THE COSTS OF CLEANING EXISTING REINFORCING STEEL. (10) INCLUDES ALL COSTS FOR TEMPORARY REMOVAL AND REPLACEMENT OF WARNING SIGNS AND LIGHTS IN
- AREAS IN CONFLICT WITH ARCH REPAIR AREAS AS SHOWN ON SHEET 18.
- (11) INCLUDES ALL COSTS FOR THE REATTACHMENT OF DRAIN PIPE AS SHOWN ON SHEET 20. (12) INCLUDES ALL COSTS FOR DESIGNING, ERECTING, MAINTAINING, AND REMOVAL OF TEMPORARY WORK.
- PLATFORM(S) DEEMED NECESSARY BY THE CONTRACTOR TO COMPLETE THE WORK. SHOP DRAWINGS FOR WORK PLATFORMS SHALL BE PREPARED BY A PROFESSIONAL ENGINEER AND REVIEWED BY THE ENGINEER PRIOR TO INSTALLATION, ALL WORK PLATFORMS SHALL MEET THE FULL SATISFACTION OF THE ENGINEER AND THE TVA CONSTRUCTION MANAGER.
- (13) INCLUDES ALL COSTS FOR CONCRETE REMOVAL, STEEL REMOVAL, CONCRETE PLACEMENT, AND NEW CURB IRON PLACEMENT AS SHOWN ON SHEET 15.
- (14) INCLUDES ALL COSTS FOR REMOVAL AND REPLACEMENT OF EXISTING JOINTS AS DEPICTED IN THE PLANS.
- (15) INCLUDES ALL MOBILIZATION COSTS AS DESCRIBED IN THE GENERAL NOTES.
 (16) INCLUDES ALL COSTS FOR PROVIDING, MAINTAINING, AND REMOVING CONTRACTOR'S FIELD OFFICE AT THE SITE. SHALL ALSO INCLUDE ALL COSTS FOR TEMPORARY SANITARY FACILITIES AND HOUSEKEEPING MEASURES AT THE SITE. CONTRACTOR SHALL SUBMIT FIELD OFFICE SPECIFICATIONS TO TVA FOR APPROVAL

(17) INCLUDES ALL COSTS FOR PLACEMENT OF NEW DOUBLE YELLOW LINE ALONG CENTERLINE OF BRIDGE IN REPAIR AREAS.

(18) INCLUDES ALL COSTS FOR PLACING, MAINTAINING, AND REMOVING TEMPORARY CONSTRUCTION SIGNS.

ARCH NUMBER	TOTAL, SF	ARCH NUMBER	TOTAL, SE
ARCH NO. 0	40	ARCH NO. 40	37
ARCH NO. 1	61	ARCH NO. 41	57
ARCH NO. 2	72	ARCH NO. 42	56
ARCH NO. 3	68	ARCH NO. 43	72
ARCH NO. 4	50	ARCH NO. 44	53
ARCH NO. 5	60	ARCH NO. 45	53
ARCH NO. 6	38	ARCH NO. 46	58
ARCH NO. 7	28	ARCH NO. 47	48
ARCH NO. 8	18	ARCH NO. 48	80
ARCH NO. 9	14	ARCH NO: 49	70
ARCH NO. 10	48	ARCH NO. 50	76
ARCH NO. 11	38	ARCH NO. 51	93
ARCH NO. 12	44	ARCH NO. 52	52
ARCH NO. 13	65	ARCH NO. 53	93
ARCH NO. 14	18	ARCH NO. 54	126
ARCH NO. 15	63	ARCH NO. 55	10
ARCH NO. 16	26	ARCH NO. 56	11
ARCH NO. 17	53	ARCH NO. 57	127
ARCH NO. 18	34	ARCH NO. 58	50
ARCH NO. 19	66	ARCH NO. 59	56
ARCH NO. 20	0	ARCH NO. 60	56
ARCH NO. 21	16	ARCH NO. 61	56
ARCH NO. 22	76	ARCH NO. 62	56
ARCH NO. 23	65	ARCH NO. 63	56
ARCH NO. 24	66	ARCH NO. 64	56
ARCH NO. 25	54	ARCH NO. 65	56
ARCH NO. 26	55	ARCH NO. 66	56
ARCH NO. 27	91	ARCH NO. 67	50
ARCH NO. 28	72	ARCH NO. 68	56
ARCH NO. 29	79	ARCH NO. 69	56
ARCH NO. 30	53	ARCH NO. 70	56
ARCH NO. 31	78	ARCH NO. 71	56
ARCH NO. 32	83	ARCH NO. 72	56
ARCH NO. 33	62	ARCH NO. 73	56
ARCH NO. 34	50	ARCH NO. 74	56
ARCH NO. 35	74	ARCH NO. 75	56
ARCH NO. 36	48	ARCH NO. 76	56
ARCH NO. 37	50	ARCH NO. 77	56
ARCH NO. 38	28	ARCH NO. 78	56
ARCH NO. 39	59		

NOTE: ARCH REPAIR QUANTITIES FOR ARCH NOS.0-58 ARE BASED ON MEASUREMENTS TAKEN FROM AUGUST 2018 INSPECTION. QUANTITIES FOR ARCH NOS.59-78 ARE ESTIMATES.





03:33

JAN-2019 (Djectsvið

10

NOTES:

THE CONTRACTOR SHALL DEMONSTRATE PROPER HOUSEKEEPING MEASURES AT ALL TIMES WITHIN THE STAGING AREA.

ANY DAMAGE TO THE AREA AS A RESULT OF THE CONTRACTOR'S ACTIONS SHALL BE REPAIRED IMMEDIATELY AT THE CONTRACTOR'S EXPENSE.

AT THE CONCLUSION OF CONSTRUCTION, THE AREA SHALL BE RETURNED TO ITS PRECONSTRUCTION CONDITION TO THE SATISFACTION OF THE BENGINEER. IT IS RECOMMENDED THAT A PRECONSTRUCTION STE INSPECTION BE PERFORMED INCLUDING PHOTO LOGS OF THE AREA ALL COSTS FOR STAGING AREA RESTORATION TO PRECONSTRUCTION CONDITION WILL BE CONSIDERED INCLIDENTAL TO THE WORK AND WILL NOT BE PAID DIRECTLY.

THE CONTRACTOR SHALL, AT ALL TIMES, PROVIDE AND KEEP UPDATED CONTACT INFORMATION FOR THEIR ONSITE REPRESENTATIVE WITH THE ENGINEER, PLANT MANAGER, AND LOCK MASTER.

THE CONTRACTOR SHALL ABIDE BY ALL SECURITY REQUIREMENTS DICTATED BY TVA.

THE CONTRACTOR SHALL COORDINATE GATE ACCESS WITH TVA PLANT MANAGEMENT.



SIG.








SHEET NO. 4A

----- END OF BRIDGE



BRIDGE CLOSURE SIGN LOCATIONS - AREA 2



BRIDGE CLOSURE SIGN LOCATIONS - AREA 1



NOTES:

BRIDGE WILL BE CLOSED DURING CONSTRUCTION.EXISTING GATES WILL BE USED TO CLOSE STRUCTURE TO TRAFFIC.


CLOSURE SIGNS SHALL NOT BE DISPLAYED MORE THAN FORTY-EIGHT (48) HOURS BEFORE PHYSICAL CONSTRUCTION BEGINS, SIGN MAY BE ERECTED UP TO ONE WEEK BEFORE NEEDDE. IF THE SIGN FACE IS FULLY COVERED.


ALL SIGNS SHALL BE IN STRICT ACCORDANCE WITH THE MANUAL ON UNIFORM TRAFFIC CONTROL DEVICES.


CLOSURE SIGNS SHALL REMAIN IN PLACE UNTIL THE COMPLETION OF THE PROJECT. THE LOCATION OF THE CLOSURE SIGNS ARE TO BE APPROVED BY TVA PRIOR TO INSTALLATION.


A TOTAL OF FOUR (4) SIGNS ARE REQUIRED. ADDITIONAL MAY BE REQUESTED BY TVA.


SIGNS INCLUDING ALL SUPPORTS SHALL BE PAID UNDER ITEM NO.740B000. CONTRACTOR SHALL COORDINATE AND COMMUNICATE BRIDGE CLOSURE WITH ALDOT, LOCAL GOVERNMENT PERSONNEL, AND LOCAL EMERGENCY MANAGEMENT AS NECESSARY.











1


AUTHORITY REFURBISHMENT # TENNESSEE VALLEY CONTRACT DAM BRIDGE DECK WILSON

N.T.S.

11-30-2018

DECK REPAIR TYPICAL

SECTION SHEET NO. 9





	DATE									
	REVISION									
	N0.									
	SCALE DRAWN DESIGN			1	N.T.S A. ALLSBROOM					
				,						
				A. ALLSBROOK						
	CHECKED				J. ECKEL					
	VOLKERT									

SIG.



NOTES:

PRIOR TO FREMOVAL OF ANY PORTION OF THE CONCRETE DECK.CONTRACTOR SHAL MARK ALL EXISTING CONDITIS.LIGHT FUTURES, AND ANY OTHER VITILTES SHAL WILL BE ENCOUNTERED DURING DECK REMOVA AND REPLACEMENT, CURB AND SIDEWALK REPART, AND RAIL REPART PROCESS.IN ADDITION, CONTRACTOR SHALL COORDINATE WITH TVA TO MOVE CONDUIT OR UTILITIES AS NEEDED TO COMPLETE WORK.

CONTRACTOR SHALL TAKE SPECIAL CARE WHEN REMOVING EXISTING CONCRETE DECK TO PRESERVE EXISTING CONCRETE CURE ON BOTH SIDES OF THE SLAB.THE CONTRACTOR SHALL VERIFY WITH TVA CONDUIT LOCATIONS IN THE AREAS OF CONCRETE CURB REMOVAL AND REPLACEMENT.


AFTER REMOVAL OF THE EXISTING CONCRETE SLAB, THE LAYER OF THE FILL MATERIAL SHALL BE REMOVED VIA HYDRODEMOLTION.

AFTER THE HYDRODEMOLITION OPERATION IS COMPLETED. THE ENGINEER WILL DETERMINE IF THE EXPOSED ARCH CONCRETE AND CONCRETE CURB JOINT IS SUFFICIENTLY CLEANED OR IF ADDITIONAL BLASTING IS REQUIRED. ALL LOSSE MATERIAL SHALL BE REMOVED FROM THE DECK PRIOR TO POURING CONCRETE.AREAS OF THE DECK.NOT ACCESSIBLE OR OTHERWISE ADATABLE TO HYDRODEMOLITION.SHALL BE REMOVED BY CONVENTIONAL POWER CHIPPING OR HAND TOOLS. PNEUMATIC HAMMERS HEAVIER THAN THE 30 POUND CLASS SHALL NOT BE USED.


PRIOR TO PLACEMENT OF NEW SLAB, CONTRACTOR SHALL PLACE 2-LAYERS OF TAR PAPER BETWEEN THE CURB AND NEW SLAB CONCRETE. THE LONGITUDINAL JOINT BETWEEN THE DECK AND CURB SHALL BE SEALED WITH A METHACPYLATE SEALANT ALONG THE ENTIRE LENGTH OF THE BRIDGE AFTER THE NEW SLAB CONCRETE HAS BEEN CURED.

THE COST OF THE METHACRYLATE SEALANT TO BE PAID UNDER ITEM NO. 520A102.


THE CONTRACTOR SHALL TAKE PRECAUTIONS (PLUGGING DRAINS, PLUGGING EXISTING JOINTS, ETC.) TO ENSUME HYDRODEMOLITION WASTEWATER DOES NOT ENTER THE TENNESSEE RIVER.





TYPCIAL SECTION - DECK REMOVAL




TYPICAL SECTION - DECK REPLACEMENT









DEFICIENCIES DEF. DESCRIPTION REPAIR DESCRIPTION DEF.NO. LOCATION/COMPONENT РНОТО AUTHORITY 1 LIGHT TO BE REMOVED 7777 VARIOUS SPALLS AROUND LIGHT/PLATE. MOST ARE FAILED AND DETERIORATED PRIOR TO CONCRETE REMOVAL AND REPAIR. TYPICAL AT LIGHT/PLATE LOCATIONS ON BOTH SIDES (LEFT AND 1 THEN RESET. SEE DETAIL "B" ON SHEET NO. 19 FOR REPAIR DETAILS. 1 RIGHT) OF RAIL EXISTING PATCHES. # TENNESSEE VALLEY CONTRACT TOP OF CURB OR TO OF SIDEWALK CONCRETE REPAIR TO MATCH EXISTING LINES, SEE DETAIL "B" ON SHEET NO.19 FOR SPALL OR DELAM. OF CONCRETE RAIL TYPICAL AT RAIL POSTS ON BOTH SIDES (LEFT AND TYPICAL RAIL ELEVATION 2 ACROSS CENTER POST, REBAR USUALLY (TYPICAL RAIL AT DECK JOINTS) (SHOWING DEFICIENCIES ON RAIL) RIGHT) OF RAIL EXPOSED. SIZE VARIES. REPAIR DETAILS. 2 SIG. CONCRETE REPAIR TO MATCH EXISITNG LOCATIONS VARY SPALL OR DELAM. THROUGHOUT RAIL ON BOTH SIDES CONCRETE ON RAIL, REBAR USUALLY 3 LINES, SEE DETAIL "B" ON SHEET NO. 19 FOR -3 (LEFT AND RIGHT) EXPOSED. SIZE VARIES. REPAIR DETAILS. TOP OF CURB OR TO OF SIDEWALK NOTES: DEFICIENCIES SHOWN IN TABLE AND ELEVATION SKETCH MAY OR MAY NOT BE FOUND IN EACH SLAB SECTION, BUT ARE MEANT TO REPRESENT THE TYPICAL LOCATION, DESCRIPTION, AND APPEARANCE OF THE DEFICIENCIES FOUND THROUGHOUT THE ENTIRE STRUCTURE. AREAS TO BE REPAIRED WILL BE DELINEATED BY THE ENGINEER. TYPICAL RAIL ELEVATION . N (TYPICAL RAIL BETWEEN DECK JOINTS) (SHOWING DEFICIENCIES ON RAIL) SCALE N.T.S. DRAWN A. ALLSBROOK DESIGN A. ALLSBROOK CHECKED J. ECKEL VOLKERT

5

DETAILS

DAM BRIDGE DECK REFURBISHMENT


WILSON


JOB NO. 1012500.17 DATE 11-30-2018


RAIL REPAIR DETAILS

TITLE

SHEET NO. 16












NOTES:

7


JAN-2019 03:35 0jects/1012500 -

5

EXISTING DRAIN HOLE DRAIN PLATE, AND ANY CONCRETE THAT IS IN CONTACT WITH MOUNTED DRAIN PLATE SHALL BE THOROUGHLY CLEANED BEFORE DRAIN IS REATLACHED. A MINIMUM OF FOUR (4)1° DIAMETER BOLTS SHALL BE EMBEDDED INTO THE TOP OF THE CONCRETE ARCH USING EXISTING BOLT HOLES. BOLTS SHALL BE EMBEDDED A MINIMUM OF 6° INTO THE ARCH AND GROUTED INTO PLACE.



drain repair detail



TENNESSEE VALLEY AUTHORITY CONTRACT # WILSON DAM BRIDGE DECK REFURBISHMENT

SIG.

. N

SCALE N.T.S. DRAWN A. ALLSBROOK DESIGN A. ALLSBROOK CHECKED J. ECKEL VOLKERT

JOB NO. 1012500.17

DATE 11-30-2018

> DRAINAGE REPAIR DETAILS


TITLE

SHEET NO. 20

SECTION A-A

Appendix B – Expansion Joint Installation Details

This page intentionally left blank




Wabo®Modular


MODEL: "D" Series

Information provided herein, including but not limited to, any drawing, design, photograph, graphic, or statement(s) ("Materials") are proprietary and the property of Watson Bowman Acme Corporation ("Company"). Reproduction, translation, or reduction to any electronic medium or machine readable form, in whole or part, is strictly prohibited, except for the express purpose for which it has been furnished, without prior written consent of Company. All Materials contained herein are provided by Company for information purposes only. Company reserves the right to amend or withdraw any information contained in the Materials without notice. All technical or other advice by Company, whether verbal or written, concerning products, or the use of products in specific situations ("Advice") is given by Company and is used at the Users own risk.

DRAWING NO: C-20518

DATE: 5/19/10





	+ "A" +			
	neric seal D shown)	Type "P" Steel St	nape	
ل Field install seal u ∠ Wabo⊛PrimaLub Adhe ∠		1/2" dia. c anchors	concrete	
	"A"			
	Wabo [®] StripSeal	Type "P"	"EF	E"
Design Features • Rugged design accodating HS-20 loading • Extrusion cavity mechanically locks all seal profile application • Accommodates multi-directional movements	Cast In Place Condition	DN Model Number SE-300 SE-400 SE-500 EFE-400	Seal Dimension Table Joint Width "A" Movement Monormal Min. Max. inches mm inches mm 3.000 76 0 0 3.000 76 4.000 102 0 0 4.000 102 5.000 127 0 0 5.000 127 4.000 102 0.500 13 4.500 114	Min. Install Width inches mm 1.500 38 1.500 38 2.000 51 2.500 64 tal changes,
PROJECT NAME:		Watson Bowman Acme Corp. 95 Pineview Drive Amherst, NY 14228	Watson Bowman	REVISION NO:
PROJECT LOCATION:	We create chemistry	phone: (716) 691-7566 fax: (716) 691-9239 www.wbacorp.com	Acme	SHEET NO:
Wabo®StripSeal	Watson Bowman Acme Corporation ("Company"). strictly prohibited, except for the express purpose provided by Company for information purposes only.	d to, any drawing, design, photograph, graphic, or statement(s) (' Reproduction, translation, or reduction to any electronic medium for which it has been furnished, without prior written consent of (Company reserves the right to amend or withdraw any informati I or written, concerning products, or the use of products in specif is used at the Users own risk.	or machine readable form, in whole or part, is Company. All Materials contained herein are on contained in the Materials without notice. All	3 DRAWING NO: C-20519
- DRAWING DESCRIPTION: Wabo®StripSeal DATE: 5/19/10 MODEL: Type "P"	Information provided herein, including but not limite Watson Bowman Acme Corporation ("Company"). strictly prohibited, except for the express purpose provided by Company for information purposes only.	WWW.Wbacorp.com d to, any drawing, design, photograph, graphic, or statement(s) (' Reproduction, translation, or reduction to any electronic medium for which it has been furnished, without prior written consent of C Company reserves the right to amend or withdraw any informati	Materials") are proprietary and the property of or machine readable form, in whole or part, is Company. All Materials contained herein are on contained in the Materials without notice. All	3 DRAWING NO:







Image: Steel Shape Image: Steel Shape Image: Steel Shape Image: Steel Shape <td>. √.</td>	. √.
	22
Wabo [®] StripSeal Type "R"	EFE"
	Min, Install
Design relatives Movement Min. Max. • Rugged design accodating HS-20 loading • Rugged design accodating HS-20 loading	Width inches mm 76 1.500 38 102 1.500 38 127 2.000 51 114 2.500 64
PROJECT NAME: - - BASF Watson Bowman Acme Corp. 95 Pineview Drive Amherst, NY 14228 phone: (716) 691-7566 fax: (716) 691-9239 Watson Bowman Acme Corp. www.wbacorp.com Watson Bowman Acme Corp.	REVISION NO:
DRAWING DESCRIPTION: Information provided herein, including but not limited to, any drawing, design, photograph, graphic, or statement(s) ("Materials") are proprietary and the property of	SHEET NO: 5
Watson Bowman Acme Corporation ("Company"). Reproduction, translation, or reduction to any electronic medium or machine readable form, in whole or part, is strictly prohibited, except for the express purpose for which it has been furnished, without prior written consent of Company. All Materials contained herein are provided by Company for information purposes only. Company reserves the right to amend or withdraw any information contained in the Materials without notice. All technical or other advice by Company, whether verbal or written, concerning products, or the use of products in specific situations ("Advice") is given by Company and is used at the Users own risk.	DRAWING NO: C-20519







Appendix C – Wilson Dam Bridge Deck Refurbishment Study

This page intentionally left blank



Volkert, Inc.

302 Innovation Dr., Suite 100 Franklin, Tennessee 37067 Tel: (615) 656-1845 Fax: (615) 656-1870 Volkert.com

Wilson Dam Bridge Deck Refurbishment Study

TVA Contract Number PO3021131

Wilson Dam Bridge over Tennessee River

TVA Wilson Dam and Hydro Plant Florence, Alabama

Prepared for: Tennessee Valley Authority



Report Date: October 10, 2017

Preparer: Justin Eckel, PE

Reviewer: Tony Montiel, PE

WILS	ON DAM BRIDGE DECK REFURBISHMENT STUDY Wilson Dam Bridge over Tennessee River TVA Wilson Dam and Hydro Plant Florence, Alabama
Section	Page No.
1.0 EXEC	UTIVE SUMMARY 1
2.0 PROJE	ECT DESCRIPTION
3.0 FIELD	INVESTIGATION
3.1	Traffic Analysis
3.2	2 Concrete Sampling and Testing Results
3.3	³ Field Observations and Measurements
3.4	Field Survey and Deck Drainage12
4.0 REPA	IR TECHNIQUES13
4.1	Bridge Deck
4.2	2 Concrete Arches
4.3	B Miscellaneous Concrete Repairs
4.4	Deck Drainage
5.0 PRELI	MINARY COST ESTIMATES
5.1	Repair Scheme A
5.2	2 Repair Scheme B
5.3	³ Repair Scheme C
5.4	Repair Scheme D
5.5	5 Hybrid Repair Scheme
6.0 ASSUN	APTIONS, RISKS, AND UNKNOWNS
Appendix B Appendix C Appendix D	: Existing Plans : Traffic Analysis : GPR Report : Concrete Testing Report : Deck Drainage Calculations

Appendix F: Manufacturer Information Appendix G: Preliminary Estimated Quantities



1.0 Executive Summary

The purpose of this study is to develop repair options and cost estimates for the repair of the bridge deck and other concrete surfaces for the Wilson Dam Bridge over the Tennessee River. The primary goal is to present viable conceptual repair options for stopping the flow of water through the deck and parapets and removing and replacing deteriorated concrete on the arch faces. The project limits for this study include the concrete arches on the dam above the spring line, bridge deck, curbs, parapets, and sidewalks between the control building and the beginning of the main bridge over the lock.

The conceptual repair details and techniques provided served as a basis for the development of four repair schemes and their associated preliminary cost estimates. The objective in the development of the different repair schemes was to identify a range of total project costs and each scheme's relative risk to allow for the Tennessee Valley Authority (TVA) to arrive at their preferred alternate. The schemes identified are denoted as:

- Repair Scheme A stabilize and repair the bridge deck and perform spot grinding of the deck to improve rideability and patch deteriorated concrete arch faces
- Repair Scheme B perform the same repairs as Repair Scheme A, but also patch deteriorated concrete surfaces of the rails and sidewalks and retrofit deck drainage
- Repair Scheme C stabilize and repair the bridge deck and construct a new latex modified concrete overlay; patch deteriorated surfaces of arch face, rails, and sidewalks; and retrofit deck drainage
- Repair Scheme D remove and replace existing bridge deck; patch deteriorated surfaces of arch face, rails, and sidewalks; and retrofit deck drainage

The total preliminary estimated cost for the repair schemes ranged from \$1,614,000 for Repair Scheme A to \$4,743,000 for Repair Scheme D.




2.0 Project Description

The purpose of this study is to develop repair options and cost estimates for consideration by the Tennessee Valley Authority (TVA) for the bridge over Wilson Dam. The primary goal is to present viable conceptual repair options for stopping the flow of water through the deck and parapets and removing and replacing deteriorated concrete on the arch faces. The project limits for this study include the concrete arches on the dam above the spring line, bridge deck, curbs, parapets, and sidewalks between the control building and the beginning of the main bridge over the lock. Deficiencies and associated repair options have been identified. The repair options provided herein have been developed through review of state DOT bridge repair practice for similar deficiencies and discussions with product suppliers. Repairs have been grouped to provide repair schemes and their associated cost estimates that range from a lower end to a higher end rehabilitation option.

The original construction of Wilson Dam by the Army Corp of Engineers began in 1918 and was completed in 1924. The dam was acquired by TVA in 1933. The original wearing surface was brick pavers which were removed in the late 1950s and replaced with a concrete deck when the additional steel superstructure viaduct was constructed over the lock. The arch appears to be constructed of mass unreinforced concrete. The bridge deck also appears to be unreinforced. Available plans are provided in Appendix A.

The dam and bridge are listed on the National Register of Historic Places and Wilson Dam is listed as a National Historic Landmark. Wilson Dam spans the Tennessee River between Florence and Muscle Shoals, Alabama (see Figure 1). The impoundment of the Tennessee River above Wilson Dam has created Wilson Lake to the east with Pickwick Lake to the west.





3.0 Field Investigation

For this Phase 1 study, only a minor amount of field investigation was undertaken. For future phases of the project, more field investigation is recommended to better refine quantities used to develop cost estimates. The field investigation for this study included a combination of traffic counts, ground penetrating radar (GPR), concrete sampling and testing, concrete sounding using hammers, visual observation, and field survey.

3.1 Traffic Analysis

Traffic counts were completed using two cameras attached to a light pole approximately 500' north of the main bridge over the lock along South Cox Creek Parkway. Data was collected on Thursday, July 27, 2017 through Saturday, July 29, 2017. Bi-directional average daily traffic (ADT) in 15-minute increments was collected. Average Daily Traffic and Peak Hour Traffic are shown in Table 1 and Table 2, respectively.

DATE	ADT	NORTHBOUND	SOUTHBOUND
Thursday, July 27, 2017	3,639	1,749	1,890
Friday, July 28, 2017	3,472	1,660	1,812
Saturday, July 29, 2017	3,492	1,626	1,866

TIME	PEAK TOTAL	NORTHBOUND	SOUTHBOUND			
Thursday, July 27, 2017						
7:15 – 8:15	240	69	171			
11:15 – 12:15	229	124	105			
15:30 - 16:30	358	232	126			
Friday, July 28, 2017						
6:30 - 7:30	182	44	138			
11:00 - 12:00	218	122	96			
15:30 - 16:30	326	208	118			
Saturday, July 29, 2017						
7:45 - 8:45	138	77	61			
11:00 - 12:00	269	142	127			
15:15 - 16:15	291	132	159			

Table 1: Average Daily Traffic

Table 2: Peak Hour Traffic (By Day)

Additional traffic data including turn movement counts, can be found in Appendix B.



3.2 Concrete Sampling and Testing Results

A total of six locations were identified for deck sampling. At each location, a core sample was taken through the newer concrete deck (deck) and the original arch structure (arch). At each location, ground penetrating radar (GPR) testing was performed prior to concrete coring to determine if any obstructions (conduit, reinforcement, etc.) would interfere with the coring. Sampling locations for which conduit interfered were relocated slightly to avoid the conflict. During GPR testing, it was observed that a thin layer was present approximately eight to ten inches below the surface. It is believed that this is potentially a layer of deteriorated bedding material (void) from the original pavers that was not properly removed before the new deck was cast. A sample GPR image is presented in Figure 2. A schematic of the core locations is shown in Figure 3 with a summary of the sample locations, deck and void thicknesses, and tests to be performed shown in Table 3. For the complete GPR Observation Report, see Appendix C.




Figure 2: Sample GPR Image

CORE	DECK	VOID	SPECIMENS TO BE TESTED					
NO.	тніск.	DEPTH	CHLORIDE		PETROGRAPHY		COMPRESSION	
			DECK	ARCH	DECK	ARCH	DECK	ARCH
1	8.250"	0.250"		YES		YES	YES	
2	7.750"	0.250″					YES	
3	9.250"	0.500"	YES	YES	YES	YES		
4	8.750"	0.125″	YES	YES	YES	YES		
5	9.125″	0.250"		YES		YES	YES	
6	9.625"	0.125″					YES	

Table 3: Concrete Deck and Arch Sample Data



TVA

WILSON DAM BRIDGE DECK REFURBISHMEN STUDY

DGE	DRAWN BY	A.D.A.	DATE	10-10-2017	FIGURE
MENT	CHECKED BY	J.T.E.	PROJ.NO.	741400.17	3
	BACKCHECKED BY	A.A.M.	SCALE	N.T.S.	6








Figure 4: Typical Concrete Coring Setup



Figure 5: Typical Deck and Arch Samples



As can be seen in Table 3, this deteriorated layer (void) varied in depth from 0.125" to 0.500" for the samples collected. It is believed that the differential settlement along the deck slab is the probable cause of the cracking in the deck. This cracking has allowed water to pass through the deck, where it travels along the construction joint between the arch and the deck, eventually daylighting along the arch face. This passage of water is believed to be the cause of the deterioration of the concrete in the face of the arch.

Concrete testing on samples collected included petrographic examination, thin section examination, Los-Alamos stain tests, chloride analysis, and compressive testing. A complete report of the testing results can be found in Appendix D. A summary of the findings include:

- The concrete represented by each of the cores consisted of plain well-hydrated concrete. Coarse aggregates consisted of a combination of crushed limestone and chert, and fine aggregates consisted of natural sand.
- The presence of alkali-silica reactive aggregates was not detected by either Los Alamos staining or visual or microscopic examinations.
- The bridge deck cores were slightly-to-moderately air entrained. The arch cores were not air entrained. No honeycombing was observed in the samples.
- > None of the samples contained reinforcing steel or wire mesh.
- Core #3 from the bridge deck was cored over an apparent open fracture, as evidenced by discoloration and the presence of calcium carbonate deposits. Core #3 from the arch exhibited the presence of carbonated fractures normal to the core axis, indicative of likely freeze-thaw distress.
- Microfracturing of the matrices was observed in each of the cores. In half of the cores (Core #3 and Core #4 from the arch and Core #3 from the bridge deck), these fractures appeared to the associated with the presence of expansive ettringite, which was also present in the matrices and air voids of the majority of the cores. This is suggestive of sulfate attack of the concrete.
- Chloride analyses indicated slightly elevated to elevated acid soluble (total) chlorides in half of the samples, but water-soluble chlorides, those typically associated with corrosion of steel reinforcement or concrete scaling, were minimal, with several results just above detection limits.
- Compressive strength tests from the bridge deck samples indicated strengths of 4,830 psi to 5,610 psi.



3.3 Field Observations and Measurements

Concrete faces for the arches adjacent to the turnaround, at approximate station 73+55, were visually observed from the turnaround and their areas of deteriorated concrete estimated. Five arches were estimated in all totaling approximately 10% of the project limits. The deteriorated area of those five arches was assumed to be representative of the entire project when calculating repair quantities. Further hands-on inspection of the arch faces by sounding is recommended in future project phases to better quantify the limits of this deterioration. It is also recommended that concrete cores be taken horizontally along the arch for further evaluation.



Figure 6: Typical Arch Deterioration

Beginning at the turnaround and extending approximately 722' toward the control building, our staff sounded the concrete surfaces of the bridge rails and sidewalks on both sides of the roadway to estimate the deteriorated concrete areas. The length of visible deck crack in each span as well as any areas of needed full depth deck repair were also estimated. The inspected account for approximately 27% of the structure. The areas of repair observed over these limits was assumed to be representative of the entire project limits when calculating repair quantities for the cost estimates.






Figure 7: Typical Deck Cracking



Figure 8: Typical Deck Patching





Figure 9: Typical Sidewalk Spall



Figure 10: Typical Rail Spall



3.4 Field Survey and Deck Drainage

Field survey was completed by taking cross-sections at approximately fifty foot intervals along the structure. In addition to these cross-sections, each deck drain was also located and the elevations recorded. The finished grade elevation determined through this survey matched very closely with the elevation shown in the plans of 524.60. The surveyed elevations stayed fairly consistent and ranged from approximately 524.52 to 524.78. The cross-slope of the roadway measured approximately between one and two percent.

A hydraulic analysis was performed to see how the existing deck drains will handle a 10-year storm event. The 10-year design frequency is what is required by ALDOT for bridge deck drainage design. Using the FHWA HEC 21 formula for flat bridges, a required inlet spacing of 90' was derived. The spacing of the existing deck drains varies from approximately 46' to 55', so this criteria appears to be met. Due to the structure not having shoulders, the ALDOT criteria of limiting spread to the shoulders could not be met. Therefore, we assumed a maximum allowable spread of one-half of the travel lane, which is allowed by some agencies on lower speed facilities. The calculations can be found in Appendix E. These calculations do not take into consideration the size and flow capacity of the existing deck drains. The capacity of the existing drains could not be verified due to the unique configuration that is no longer typically used, and no published information could be found to confidently determine the existing grate capacities.



Figure 11: Typical Deck Drain



4.0 Repair Techniques

For each of the deficiencies noted during the field investigation, repair techniques have been identified based on our staff's experience with similar projects, research of multiple state DOT procedures, and discussions with product suppliers. Possible repair techniques are discussed in the following sections.

4.1 Bridge Deck

As discussed previously, it is believed that the presence of the "void" between the original arch concrete and the newer concrete deck is the probable cause of the deck cracking. Repair technique options include:

- Stabilize deck and "level-out" riding surface by spot grinding
- > Stabilize deck and construct new latex modified concrete overlay
- Remove and replace existing deck

Preliminary repair details for each of these techniques are shown in Figures 12 through 14. For stabilization of the deck, a product such as Uretek 486 STAR Polymer is recommended. These products can be injected through the deck using ports which will stabilize and stiffen the "void" layer. Product data can be found in Appendix F. Stabilizing the deck will provide a lower cost alternative when compared to a complete removal and replacement of the deck. It does, however, come with the risk of less certainty of whether or not the polymer filled all of the voids. This is discussed further in Section 6.0.

4.2 Concrete Arches

The concrete arch faces exhibit a large amount of concrete spall near the top surface as discussed in Section 3.3. This deterioration is believed to be a result of water passing through the existing deck and working its way across the construction joint between the original arch and new overlay and deteriorating the arch face. Once the deck is repaired and sealed from water infiltration, it is recommended to repair this deteriorated arch concrete. Arch faces should be sounded and deteriorated concrete removed. Since the arch is unreinforced, the patch concrete should be anchored in place through the use of concrete anchors and welded wire reinforcement as shown in Figure 15.

4.3 Miscellaneous Concrete Repairs


Additional concrete repairs were also identified during this preliminary field investigation. They include full depth deck repairs, sidewalk spall repairs, and barrier rail spall repairs. Details for each of these





repairs are presented in Figures 16 through 18. The details provided for full depth deck repair should be used on spot areas should the stabilization option be selected for the global scheme on the deck.


4.4 Deck Drainage


Based on past experience, we do not expect the existing deck drains to be able to adequately drain the deck surface once the deck cracks are sealed. We recommend that additional deck drains be added to the structure. These could be placed near the mid-span of each arch and have a similar shape and size as the existing grate inlets currently installed on the deck near the beginning of the flyover over the lock.



















5.0 Preliminary Cost Estimates

Based on the field investigation undertaken for this phase of the project, preliminary estimated quantities were calculated as shown in Appendix G. Using the repair details provided herein, unit prices were developed by comparing historical pricing data from other projects, discussions with product suppliers, and discussions with contractors. A discussion of each repair scheme and its associated cost estimate are provided in the following sections.

5.1 Repair Scheme A

The first repair scheme considered seeks to provide a least-cost alternative to meet the minimum needs of the project. This scheme will:

- Stabilize the bridge deck by pressure injecting Uretek polymer or an equivalent product into the "void" between the arch concrete and the existing concrete overlay.
- > Repair existing deck cracks by epoxy injection.
- > Perform spot full depth concrete deck repairs of the existing concrete overlay.
- > Perform spot grinding of existing bridge deck to remove high spots for rideability.
- > Patch deteriorated concrete arch faces.

TABLE 4: PRELIMINARY ESTIMATED COST - REPAIR SCHEME A								
Repair Item	Repair ItemLocationUnitQuantityUnit Price							
Deck Stabilization	Bridge Deck	GAL	744	\$220.00	\$163,680.00			
Deck Crack Repair	Bridge Deck	LF	3558	\$120.00	\$426,960.00			
Deck Crack Repair	Bridge Deck	GAL	178	\$190.00	\$33,820.00			
Deck Concrete Repair	Bridge Deck	SY	101	\$950.00	\$95,950.00			
Spot Grinding of Bridge Deck	Bridge Deck	SY	595	\$7.00	\$4,165.00			
Patch Arch Faces	Arches	CF	1186	\$375.00	\$444,750.00			
SUBTOTAL					\$1,169,325.00			
Mobilization			15%	\$175,398.75	\$175,398.75			
Contingency	20%	\$268,944.75	\$268,944.75					
PRELIMINARY ESTIMATED	COST:				\$1,614,000.00			



5.2 Repair Scheme B

The second repair scheme provides the same deck repair technique as Repair Scheme A and adds the patching of the sidewalks and rails and retrofits the deck drainage. This scheme will:

- Stabilize the bridge deck by pressure injecting Uretek polymer or an equivalent product into the "void" between the arch concrete and the existing concrete overlay.
- > Repair existing deck cracks by epoxy injection.
- > Perform spot full depth concrete deck repairs of the existing concrete overlay.
- > Perform spot grinding of existing bridge deck to remove high spots for rideability.
- Patch deteriorated concrete arch faces.
- > Patch deteriorated concrete surfaces of the rails and sidewalks.
- Provide retrofits to deck drainage.

TABLE 5: PRELIMINARY ESTIMATED COST - REPAIR SCHEME B							
Repair Item	Location	Unit	Quantity	Unit Price	Total Price		
Deck Stabilization	Bridge Deck	GAL	744	\$220.00	\$163,680.00		
Deck Crack Repair	Bridge Deck	LF	3558	\$120.00	\$426,960.00		
Deck Crack Repair	Bridge Deck	GAL	178	\$190.00	\$33,820.00		
Deck Concrete Repair	Bridge Deck	SY	101	\$950.00	\$95,950.00		
Spot Grinding of Bridge Deck	Bridge Deck	SY	595	\$7.00	\$4,165.00		
Patch Arch Faces	Arches	CF	1186	\$375.00	\$444,750.00		
Sidewalk Patching	Sidewalks	SF	1416	\$210.00	\$297,360.00		
Bridge Rail Patching	Bridge Rails	SF	553	\$150.00	\$82,950.00		
Install New Deck Drains	Bridge Deck	EA	106	\$2,500.00	\$265,000.00		
SUBTOTAL					\$1,814,635.00		
Mobilization			15%	\$272,195.25	\$272,195.25		
Contingency			20%	\$417,366.05	\$417,366.05		
PRELIMINARY ESTIMATED	COST:				\$2,505,000.00		



5.3 Repair Scheme C

The third repair scheme is similar to Repair Scheme B except that it also provides a new latex modified concrete overlay and the accompanying joint modifications. This scheme will:

- Stabilize the bridge deck by pressure injecting Uretek polymer or an equivalent product into the "void" between the arch concrete and the existing concrete overlay.
- > Repair existing deck cracks by epoxy injection.
- > Perform spot full depth concrete deck repairs of the existing concrete overlay.
- Patch deteriorated concrete arch faces.
- > Patch deteriorated concrete surfaces of the rails and sidewalks.
- Provide retrofits to deck drainage.
- Install a new latex modified concrete overlay.
- Resetting existing expansion joints.

TABLE 6: PRELIMINARY ESTIMATED COST - REPAIR SCHEME C							
Repair Item	Location	Unit	Quantity	Unit Price	Total Price		
Deck Stabilization	Bridge Deck	GAL	744	\$220.00	\$163,680.00		
Deck Crack Repair	Bridge Deck	LF	3558	\$120.00	\$426,960.00		
Deck Crack Repair	Bridge Deck	GAL	178	\$190.00	\$33,820.00		
Deck Concrete Repair	Bridge Deck	SY	101	\$950.00	\$95,950.00		
Patch Arch Faces	Arches	CF	1186	\$375.00	\$444,750.00		
Sidewalk Patching	Sidewalks	SF	1416	\$210.00	\$297,360.00		
Bridge Rail Patching	Bridge Rails	SF	553	\$150.00	\$82,950.00		
Surface Prep by Hydrodemolition	Bridge Deck	SY	5946	\$40.00	\$237,840.00		
Resetting Joints	Bridge Deck	LF	1100	\$300.00	\$330,000.00		
LMC Bridge Deck Overlay	Bridge Deck	CY	248	\$850.00	\$210,800.00		
Repaint Pavement Markings	Bridge Deck	LM	1	\$4,000.00	\$4,000.00		
Install New Deck Drains	Bridge Deck	EA	106	\$2,500.00	\$265,000.00		
SUBTOTAL					\$2,593,110.00		
Mobilization			15%	\$388,966.50	\$388,966.50		
Contingency			20%	\$596,415.30	\$596,415.30		
PRELIMINARY ESTIMATED COST	Г:				\$3,579,000.00		



5.4 Repair Scheme D

The final repair scheme calls for a complete removal and replacement of the existing deck. This scheme would allow for removal of the "void" layer and provide the most certainty in the condition of the underlying arch material. This scheme will:

- Remove existing concrete bridge deck.
- Remove deteriorated material between arch and existing concrete bridge deck by hydrodemolition.
- > Construct new reinforced concrete bridge deck.
- Reset existing bridge deck joints.
- > Seal longitudinal construction joint between existing concrete curbs and new concrete deck.
- > Patch deteriorated concrete arch faces.
- > Patch deteriorated concrete surfaces of the rails and sidewalks.
- Provide retrofits to deck drainage.

TABLE 7: PRELIMINARY ESTIMATED COST - REPAIR SCHEME D								
Repair Item	Location	Unit	Quantity	Unit Price	Total Price			
Remove Concrete Bridge Deck	Bridge Deck	SY	5946	\$24.00	\$142,704.00			
Surface Prep by Hydrodemolition	Bridge Deck	SY	5946	\$40.00	\$237,840.00			
Bridge Deck Concrete	Bridge Deck	CY	1487	\$950.00	\$1,412,650.00			
Bridge Deck Reinforcement	Bridge Deck	LB	87236	\$2.00	\$174,472.00			
Sealing Longitudinal Joints	Bridge Deck	LF	5352	\$5.00	\$26,760.00			
Sealing Longitudinal Joints	Bridge Deck	GAL	72	\$250.00	\$18,000.00			
Resetting Joints	Bridge Deck	LF	1100	\$300.00	\$330,000.00			
Patch Arch Faces	Arches	CF	1186	\$375.00	\$444,750.00			
Sidewalk Patching	Sidewalks	SF	1416	\$210.00	\$297,360.00			
Bridge Rail Patching	Bridge Rails	SF	553	\$150.00	\$82,950.00			
Repaint Pavement Markings	Bridge Deck	LM	1	\$4,000.00	\$4,000.00			
Install New Deck Drains	Bridge Deck	EA	106	\$2,500.00	\$265,000.00			
SUBTOTAL					\$3,436,486.00			
Mobilization		15%	\$515,472.90	\$515 <i>,</i> 472.90				
Contingency			20%	\$790,391.78	\$790,391.78			
PRELIMINARY ESTIMATED COST:					\$4,743,000.00			



5.5 Hybrid Repair Scheme

Another possible repair scheme that could also be considered by TVA is a hybrid scheme which combines Schemes A through D on a span-by-span basis. During the next phase of the project, Volkert and TVA staff could evaluate spans and assign a repair scheme to be used on each span. This approach may realize some cost savings, but would also require much more coordination between TVA's field representative, office staff, and the contractor to ensure that the proper repair technique is used on each respective span.




6.0 Assumptions, Risks, and Unknowns

Every project comes with some amount of inherent risk. The best way to mitigate this risk is through the accumulation of a greater amount of information to attempt to reduce the number of unknowns and assumptions. For this Phase 1 study, the following notes are provided for TVA's consideration in their decision making process regarding future phases of this project.


- It is assumed that the six concrete cores and their locations are representative of the entire project area. This is a risk typical with most roadway and bridge projects where a limited number of geotechnical borings are assumed to be representative of the entire project limits. This site has the additional risk with the uncertainty of the condition of the arch concrete below the existing concrete overlay and the extent of the "void" layer between the concrete lifts. While the arch cores that were sampled appear to be in good condition, it is possible that there could be areas of the arch concrete that are in poor condition due to years of water flowing through the deck. If this concrete is in poor condition or contains cracks, it could lead to additional material needing to be pumped in these areas resulting in quantity and price overruns.
- As shown in Section 3.2, the "void" layer appears as a dark band (reflection) when using the GPR testing. A risk of the stabilization schemes is the uncertainty in whether or not the pumped grout is filling all of the voids. It is most likely that a reflection will still be seen in that layer even after injection. It is the opinion of our GPR subconsultant that the reflection after injection would have a lower amplitude reflection than the void would cause. Unfortunately, however, they feel it would be a 50/50 chance whether or not accurate results are obtained. Additionally, they feel the best approach would be to do a pre-injection survey and then a post-injection survey at the same locations and compare the differences. A decision would need to be made as to whether these surveys would be done on the entire structure or whether a representative number of samples would be selected.
- There are potential environmental and safety risks on the project due to chipping of concrete and containment of materials. It will be of utmost importance that the contractor be aware of these risks and that proper means and methods are followed that will protect the environment, workers, and TVA staff and property.




- It is recommended that more hands-on inspection of the arch faces be performed during the next phase of the project to get a better estimate on the extent of the deterioration of the concrete. This may include the performance of horizontal cores in the arch face.
- Due to the historical significance of this structure, the contractor will be required to match the current appearance of the structure. It is recommended that the contractor be required to construct mock-ups using the same materials that will be incorporated in the repairs prior to the work being performed for approval by TVA or their representative.
- It is assumed that the bridge will be closed during the repairs to increase safety to workers and the motoring public and that these costs will not be included in contractor bids.
- Details and repair unit prices provided herein are based on past project experience with multiple DOTs for similar repair technique applications or discussions with product manufacturers. If TVA employs more strict contractual language than contractors typically see, fewer bidders may submit and/or higher unit prices could be seen to account for this perceived risk.
- It is assumed that the 1940s era deck slab and original concrete arch are unreinforced based on the limited plans information available. This is supported by the results of the GPR testing.




Appendix A Existing Plans







and the state of t




S.

2








States in the second states

MF



Appendix B Traffic Analysis

Volkert, Inc.

302 Innovation Drive Suite 100 Franklin, TN 37067

Office 615.656.1845 Fax 615.656.1870

www.volkert.com

August 8, 2017

Mr. Jon C. Riley, ASLA, PMP Tennessee Valley Authority 1010 Reservation Road Complex D, OSW 112 Muscle Shoals, AL 35662

RE: Wilson Dam Traffic Volume Data

VOLKERT

Dear Mr. Riley:

This memorandum provides a summary of the traffic volume data collected along South Cox Creek Parkway at Wilson Dam in Florence, Alabama. The parameters for the data collection were as follows:

- Data was collected along South Cox Creek Parkway on the north side of Wilson dam, just south of the first intersection (local access roadway) (see figure below);
- Data was collected on Thursday, July 27th through Saturday, July 29th, 2017;
- Bi-directional average daily traffic (ADT) in 15-minute increments were collected.



Table 1 shows the ADT and Table 2 shows the peak hour periods for each of the three days of data collection.

Office Locations:

Birmingham, Foley, Mobile, Alabama • Gainesville, Orlando, Pensacola, Tampa, Florida • Atlanta, Georgia Collinsville, Illinois • Baton Rouge, New Orleans, Slidell, Louisiana • Biloxi, Mississippi • Jefferson City, Missouri Raleigh, North Carolina • Columbia, South Carolina • Chattanooga, Franklin, Tennessee • Alexandria, Virginia • Washington, D.C.



TABLE 1 AVERAGE DAILY TRAFFIC

DATE	ADT	NORTHBOUND	SOUTHBOUND
Thursday, July 27 th 2017	3,639	1,749	1,890
Friday, July 28 th , 2017	3,472	1,660	1,812
Saturday, July 29 th , 2017	3,492	1,626	1,866

TABLE 2PEAK HOUR TRAFFIC (BY DAY)

DATE	PEAK TOTAL	NORTHBOUND	SOUTHBOUND					
Thursday, July 27 th 2017								
7:15 - 8:15	240	69	171					
11:15 - 12:15	229	124	105					
15:30 - 16:30	358	232	126					
	Friday, July 28th, 2017							
6:30 - 7:30	182	44	138					
11:00 - 12:00	218	122	96					
15:30 - 16:30	326	208	118					
	Saturday, Ju	ly 29 th , 2017						
7:45 - 8:45	138	77	61					
11:00 - 12:00	269	142	127					
15:15 - 16:15	291	132	159					

Additional traffic date collected included the vehicle classifications. Based on the various classified vehicles, Table 3 shows the percent breakdown.

TABLE 3 VEHICLE CLASSIFICATIONS (% ADT)

DATE	PASSENGER CARS/MOTORCYCLES	SINGLE UNIT/BUSES
Thursday, July 27 th 2017	72.7%	27.3%
Friday, July 28 th , 2017	71.4%	28.6%
Saturday, July 29 th , 2017	77.9%	22.1%

Should you have any questions or need additional information, please contact me.

Sincerely,

Gerald Bolden, PE, PTOE Traffic and ITS Manager

WILSON DAM TRAFFIC VOLUME DATA





0000 - 2400 (Weekday 24h Session)			Northbound		
	Thru	Thru	S Cox Creek Pkwy (South)	Peds	App
TIME 0000 - 0015	Thru 1.1 3	Thru 1.2		Peds 1a 0	App Tota 8
0015 - 0030 0030 - 0045	3	0	-	0	3
0045 - 0100	1	1		0	2
Hourly Total 0100 - 0115	9	6		0	15
0115 - 0130 0130 - 0145	2	2	-	0 0	4
0145 - 0200 Hourty Total	2	0		0	2
Hourly Total 0200 - 0215 0215 - 0230	1	0		0	1
0210 - 0230 0230 - 0245 0245 - 0300	0	1		0	1
0245 - 0300 Hourly Total	2	2		0	3
0300 - 0315 0315 - 0330	1	3	-	0 0	4
0330 - 0345 0345 - 0400	1	2	F	0	3
Hourly Total 0400 - 0415	5	9		0	14
0415 - 0430	0	3	-	0	3
0430 - 0445 0445 - 0500	0	3	-	0	3
Hourly Total	1	13 9		0	14
0500 - 0515 0515 - 0530	5	12	-	0	11
0530 - 0545 0545 - 0600	6	17 24	-	0	23
Hourly Total 0600 - 0615	21 6	62		0	83 29
0615 - 0630 0630 - 0645	6	29 48		0	35
0645 - 0700	9	53		0	53 62
Hourly Total 0700 - 0715	26 19	153 32	-	0	175
0715-0730 0730-0745	13 10	49		0	51 62
0745 - 0800	28	40		0	58 68
Hourly Total 0800 - 0815	70	169 34	-	00	235
0815 - 0830 0830 - 0845	22 26	17	l F	0	39
0845 - 0900	14	19		0	33
Hourly Total 0900 - 0915	80 22	87 14		0	167 36
0915 - 0930 0930 - 0945	12 11	20 20	F	0	32 31
0945 - 1000	23 68	16		0	39
Hourly Total 1000 - 1015	18	70 16		0	138 34
1015 - 1030 1030 - 1045	31 35	22 16	F	0	53 51
1045 - 1100 Hourly Total	18	25		0	43
1100 - 1115	102 29	20		0	181
1115 - 1130 1130 - 1145	39 31	26 29	l F	0	65 60
1145 - 1200 Hourly Total	25 124	29 104		0	54 228
1200 - 1215 1215 - 1230	29	21		0	50
1230 - 1245	29	30 35	-	0	54 64
1245 - 1300 Hourly Total	36 118	19 105	_	0	55 222
1300 - 1315 1315 - 1330	23	27		0	50
1330 - 1345	28	30	-	0	43
1345 - 1400 Hourly Total	22	26 99	-	0	48 199
1400 - 1415 1415 - 1430	20 29	26 29	F	0	46 58
1430 - 1445	25	27		0	52
1445 - 1500 Hourly Total	22 96	37 119		0	59 215
1500 - 1515 1515 - 1530	33 36	31 34		0	64 70
1530 - 1545 1545 - 1600	81	32	-	0	112
Hourly Total	208	127		0	335
1600 - 1615 1615 - 1630	41 52	38 26	-	0	79 78
1630 - 1645 1645 - 1700	48	29		0	$\frac{n}{n}$
Hourly Total	188	123		0	311
1700 - 1715 1715 - 1730	51 63	28 26		0	79 89
1730 - 1745 1745 - 1800	43 31	31 29	-	0	74 60
Hourly Total 1800 - 1815	188 37	114 25		0	302
1815 - 1830	35	26		0	62 61
1830 - 1845 1845 - 1900	20	36	-	0	54 56
Hourly Total 1900 - 1915	108	125 26	-	0	23
1915 - 1930	31	28		0	59
1930 - 1945 1945 - 2000	33 19	26 21		0	59 40
Hourly Total 2000 - 2015	99 16	101 29	l F	0	200 45
2015 - 2030 2030 - 2045	12 22	21 23		0	33 45
2045 - 2100	9	20		0	40 29 15
Hourly Total 2100 - 2115	59 3	93 22		0	25
2115 - 2130 2130 - 2145	12 6	14 18	F	0	26 24
2145 - 2200 Hourly Total	7 28	13 67		0	24 20 95
2200 - 2215 2215 - 2230	7	9		0	16
2230 - 2245	5	8		0	13
2245 - 2300 Hourly Total	8 27	16 40		00	24 67
2300 - 2315 2315 - 2330	7	8		0	15
2330 - 2345	1	5		0	6
2345 - 0000 Hourly Total	2	2		0	4
Grand Total		1890		0	363
App Percentage Int Percentage	48.06 48.06	51.94 51.94	l E	0.00	100.0
Makersalas	11	7			18
Motorcycles Passenger cars 4 fire, single unit	1235	1392	l E		262
Buses	482	454 2	I F	-	936 3
2 axle, 6 tire, single unit 3 axle, single unit	20 0	35 0			55
4 or more axle, single unit	0	0			0
4 or less axle, single trailer	0	0	l F	-	0
5-axle tractor semitrailer	0	0	F	-	0
5-axle tractor semitrailer 6 or more axle, single trailer	4 ×	0		-	0
5-axle tractor semitrailer 6 or more axle, single trailer 5 or less axle, multi trailer 6 axle, multi-trailer	0	U			0
5-axie tractor semitrailer 6 or more axie, single trailer 5 or less axie, multi trailer	0				0.4
5-axie tractor sentihaler 6 or more axie, single trailer 5 or less axie, muß trailer 7 or more axie, muß-trailer Motorcycles (%) Passenger cars (%)	0 0.63 70.61	0.37	F	-	72.1
5-axie tractor sentinaler 6 or more axe, single trailer 5 or less axie, muß trailer 6 axie, muß trailer 7 or more axie, muß-trailer Motorcycles (%) Passenger cars (%) 4 (m.e. right unt (%)	0 0.63 70.61 27.56	73.65 24.02			72.1
5-aub tactor semilater 6-m more xolis ingle taler 5-or less aub, multi-taler 6-aub; multi-taler 7-or more aub, multi-taler Motorcycles (%) Passenger cars (%) 4-tes, angle unit (%) Buster (%) 2-aub (%) series autoriant (%)	0 0.63 70.61 27.56 0.06 1.14	73.65 24.02 0.11 1.85		-	72.1 25.7 0.0 1.5
5-axb tractor semifiater 6 or none axb, might traiter 9 or less axb, mult traiter 9 or less axb, mult traiter 7 or more axb, mult-traiter Motorcycles (%) Passenger cars (%) 4 4 ne, night ont (%) Buses (%) 2 axb, 6 night ont (%) 3 axb, single ant (%)	0 0.63 70.61 27.56 0.06 1.14 0.00 0.00	73.65 24.02 0.11 1.85 0.00 0.00			72.1 25.7 0.0 1.5
5 and backs semifabre 6 or none and, might shaler 7 or tess and, might shaler 8 and might shaler 7 or more ands, mult shaler Motorcycles (%) 9 and semifabre 9 and semifabre 9 and 6 tess, single unit (%) 9 and 6 tess, single unit (%) 4 or tess ands, single semif(%) 4 or tess ands, single semif(%)	0 0.63 70.61 27.56 0.06 1.14 0.00	73.65 24.02 0.11 1.85 0.00 0.00 0.00 0.00			72.1 25.7 0.00 1.5 0.00 0.00 0.00
Solid hards senthable for more and, only harding for these and, much table for these and, much table for more and, much table Motorcycles (%) Personage care (%) 4 fairs copies and (%) 2 and 6 first angle and (%) 3 and angle and (%) 4 are more and angle and (%) 4 are more and angle and (%) 5 solid tables angle and (%) 5 solid tables angle and (%) 5 solid tables angle and (%)	0 0.63 70.61 27.56 0.06 1.14 0.00 0.00 0.00 0.00 0.00	73.65 24.02 0.11 1.85 0.00 0.00 0.00 0.00 0.00			72.1 25.7 0.00 1.5 0.00 0.00 0.00
5 set lacts semihaler 6 or mos ads, ngle talar 6 or tess ads, null talar 7 or mos ads, null-falar 7 or mos ads, null-falar Motorydes (%) Passenger cars (%) 8 bese (%) 8 bese (%) 9 and, single und (%) 8 bese (%) 9 and, single und (%) 9 and, single und (%) 9 and, single und (%) 9 and	0 0.63 70.61 27.56 0.06 1.14 0.00 0.00 0.00 0.00	73.65 24.02 0.11 1.85 0.00 0.00 0.00 0.00		· · · · · · · · · · · · · · · · · · ·	0.4 72.1 25.7 0.00 1.5 0.00 0.00 0.00 0.00 0.00 0.00

Grand Total (All Sessions)

	r		Northbound		
			S Cox Creek Pkwy (South)		
	Thru	Thru		Peds	Арр
TIME	1.1	1.2		1a	Total
Grand Total	1749	1890		0	3639
			1		
			_		
App Percentage	48.06	51.94		0.00	
Int Percentage	48.06	51.94		0.00	100.00
Motorcycles	11	7]	-	18
Passenger cars	1235	1392		-	2627
4 tire, single unit	482	454		-	936
Buses	1	2		-	3
2 axle, 6 tire, single unit	20	35		-	55
3 axle, single unit	0	0		-	0
4 or more axle, single unit	0	0		-	0
4 or less axle, single trailer	0	0		-	0
5-axle tractor semitrailer	0	0		-	0
6 or more axle, single trailer	0	0		-	0
5 or less axle, multi trailer	0	0		-	0
6 axle, multi-trailer	0	0		-	0
7 or more axle, multi-trailer	0	0		-	0
Motorcycles (%)	0.63	0.37]	-	0.49
Passenger cars (%)	70.61	73.65		-	72.19
4 tire, single unit (%)	27.56	24.02		-	25.72
Buses (%)	0.06	0.11		-	0.08
2 axle, 6 tire, single unit (%)	1.14	1.85		-	1.51
3 axle, single unit (%)	0.00	0.00		-	0.00
4 or more axle, single unit (%)	0.00	0.00		-	0.00
4 or less axle, single trailer (%)	0.00	0.00		-	0.00
5-axle tractor semitrailer (%)	0.00	0.00		-	0.00
6 or more axle, single trailer (%)	0.00	0.00]	-	0.00
5 or less axle, multi trailer (%)	0.00	0.00		-	0.00
6 axle, multi-trailer (%)	0.00	0.00]	-	0.00
7 or more axle, multi-trailer (%)	0.00	0.00]	-	0.00

9


0000 - 2400 (Weekday 24h Session)

1530 - 1630 (Intersection Peak Hour)

			Northbound		
	-		S Cox Creek Pkwy (South)		
	Thru	Thru		Peds	App
TIME	1.1	1.2		1a	Total
1530 - 1545	81	32		0	113
1545 - 1600	58	30		0	88
1600 - 1615	41	38		0	79
1615 - 1630	52	26		0	78
Hourly Total	232	126		0	358
Grand Total	232	126		0	358
			1		
App Percentage	64.80	35.20		0.00	
Int Percentage	64.80	35.20		0.00	100.00
Motorcycles	1	0	1	-	1
Passenger cars	149	98			247
4 tire, single unit	79	25			104
Buses	0	1			1
2 axle, 6 tire, single unit	3	2		-	5
3 axle, single unit	0	0		-	0
4 or more axle, single unit	0	0		-	0
4 or less axle, single trailer	0	0		-	0
5-axle tractor semitrailer	0	0		-	0
6 or more axle, single trailer	0	0		-	0
5 or less axle, multi trailer	0	0		-	0
6 axle, multi-trailer	0	0		-	0
7 or more axle, multi-trailer	0	0		-	0
			i i		
Motorcycles (%)	0.43	0.00		-	0.28
Passenger cars (%)	64.22	77.78		-	68.99
4 tire, single unit (%)	34.05	19.84		-	29.05
Buses (%)	0.00	0.79		-	0.28
2 axle, 6 tire, single unit (%) 3 axle, single unit (%)	0.00	0.00		-	0.00
	0.00	0.00		-	0.00
4 or more axle, single unit (%) 4 or less axle, single trailer (%)	0.00	0.00		-	0.00
5-axle tractor semitrailer (%)	0.00	0.00			0.00
6 or more axle, single trailer (%)	0.00	0.00		<u> </u>	0.00
5 or less axle, multi trailer (%)	0.00	0.00		-	0.00
6 axle, multi-trailer (%)	0.00	0.00		-	0.00
7 or more axle, multi-trailer (%)	0.00	0.00		-	0.00
. 51 11616 0200, 11010 02001 (70)	0.00	0.00	I	·	.0.00
	1				
PHF	0.716	0.829		-	0.792
	1				







0.792

Florence, AL Classified Turn Movement Count

Site 1 of 1 S Cox Creek Pkwy (South)

Lat/Long 34.806695°, -87.627815°

Date Thursday 27 July 2017


Weather

Sunny Intervals Temp: 36°C

Peak Hour Data (Interactive Diagram)



41 Peabody Street, Nashville, TN 37210 1 (615) 431-6750 1 (800) 615-3765




0600 - 0900 (Weekday AM Peak)

0715 - 0815 (Intersection Peak Hour)

	r		Northbound		
			S Cox Creek Pkwy (South)		
	Thru	Thru	S COX CIEEK F KWY (SOULI)	Peds	Арр
TIME	1.1	1.2		1a	Total
0715 - 0730	13	49		0	62
0730 - 0745	10	48		0	58
0745 - 0800	28	40		0	68
0800 - 0815	18	34		0	52
Hourly Total	69	171		0	240
• • •					
Grand Total	69	171		0	240
App Percentage	28.75	71.25		0.00	
Int Percentage	28.75	71.25		0.00	100.00
Mataanialaa	0	0	1		0
Motorcycles	47	111		-	
Passenger cars	47	50		-	158 72
4 tire, single unit Buses	0	0		-	0
2 axle, 6 tire, single unit	0	10			10
2 axie, 6 tire, single unit 3 axle, single unit	0	0		-	0
4 or more axle, single unit	0	0		-	0
4 or less axle, single trailer	0	0		-	0
5-axle tractor semitrailer	0	0		-	0
6 or more axle, single trailer	0	0		-	0
5 or less axle, multi trailer	0	0		-	0
6 axle, multi-trailer	0	0		-	0
7 or more axle, multi-trailer	0	0		-	0
		, v		L	Ű
Motorcycles (%)	0.00	0.00		-	0.00
Passenger cars (%)	68.12	64.91		-	65.83
4 tire, single unit (%)	31.88	29.24		-	30.00
Buses (%)	0.00	0.00		-	0.00
2 axle, 6 tire, single unit (%)	0.00	5.85		-	4.17
3 axle, single unit (%)	0.00	0.00		-	0.00
4 or more axle, single unit (%)	0.00	0.00		-	0.00
4 or less axle, single trailer (%)	0.00	0.00		-	0.00
5-axle tractor semitrailer (%)	0.00	0.00		-	0.00
6 or more axle, single trailer (%)	0.00	0.00		-	0.00
5 or less axle, multi trailer (%)	0.00	0.00		-	0.00
6 axle, multi-trailer (%)	0.00	0.00		-	0.00
7 or more axle, multi-trailer (%)	0.00	0.00		-	0.00
	0.045	0.076	1		0.04-
PHF	0.616	0.872		-	0.882







0.882

Florence, AL Classified Turn Movement Count

Site 1 of 1 S Cox Creek Pkwy (South)

Lat/Long 34.806695°, -87.627815°

Date Thursday 27 July 2017


Weather

Sunny Intervals Temp: 36°C

Peak Hour Data (Interactive Diagram)



41 Peabody Street, Nashville, TN 37210 1 (615) 431-6750 1 (800) 615-3765





1100 - 1300 (Weekday Inter Peak)

1115 - 1215 (Intersection Peak Hour)

			Northbound		
			S Cox Creek Pkwy (South)		
	Thru	Thru	S OUN CIEER FRWY (SOULII)	Peds	Арр
TIME	1.1	1.2		1a	Total
1115 - 1130	39	26		0	65
1130 - 1145	31	29		0	60
1145 - 1200	25	29		0	54
1200 - 1215	29	21		0	50
Hourly Total	124	105		0	229
Grand Total	124	105		0	229
App Percentage	54.15	45.85		0.00	
Int Percentage	54.15	45.85		0.00	100.00
Motorcycles	0	0		-	0
Passenger cars	85	75		-	160
4 tire, single unit	37	27		-	64
Buses	0	0		-	0
2 axle, 6 tire, single unit	2	3		-	5
3 axle, single unit	0	0		-	0
4 or more axle, single unit	0	0		-	0
4 or less axle, single trailer	0	0		-	0
5-axle tractor semitrailer	0	0		-	0
6 or more axle, single trailer	0	0		-	0
5 or less axle, multi trailer	0	0		-	0
6 axle, multi-trailer	0	0		-	0
7 or more axle, multi-trailer	0	0		-	0
Motorcycles (%)	0.00	0.00		-	0.00
Passenger cars (%)	68.55	71.43			69.87
4 tire, single unit (%)	29.84	25.71		-	27.95
Buses (%)	0.00	0.00		-	0.00
2 axle, 6 tire, single unit (%)	1.61	2.86		-	2.18
3 axle, single unit (%)	0.00	0.00		-	0.00
4 or more axle, single unit (%)	0.00	0.00		-	0.00
4 or less axle, single trailer (%)	0.00	0.00		-	0.00
5-axle tractor semitrailer (%)	0.00	0.00		-	0.00
6 or more axle, single trailer (%)	0.00	0.00		-	0.00
5 or less axle, multi trailer (%)	0.00	0.00		-	0.00
6 axle, multi-trailer (%)	0.00	0.00		-	0.00
7 or more axle, multi-trailer (%)	0.00	0.00		-	0.00
· · · · · · · · · · · · · · · · · · ·	1	•			
PHF	0.795	0.905		-	0.881







Florence, AL Classified Turn Movement Count

Site 1 of 1 S Cox Creek Pkwy (South)

Lat/Long 34.806695°, -87.627815°

Date Thursday 27 July 2017


Weather

Sunny Intervals Temp: 36°C

Peak Hour Data (Interactive Diagram)



41 Peabody Street, Nashville, TN 37210 1 (615) 431-6750 1 (800) 615-3765




1500 - 1800 (Weekday PM Peak)

1530 - 1630 (Intersection Peak Hour)

	-		Northbound		
			S Cox Creek Pkwy (South)		
	Thru	Thru	S GOX GIEEK PKWY (SOUTH)	Peds	Арр
TIME	1.1	1.2		1a	Total
1530 - 1545	81	32		0	113
1545 - 1600	58	30		0	88
1600 - 1615	41	38		0	79
1615 - 1630	52	26		0	78
Hourly Total	232	126		0	358
Though rotal	202	120			
Grand Total	232	126		0	358
App Percentage	64.80	35.20		0.00	
Int Percentage	64.80	35.20		0.00	100.00
Motorcycles	1	0		-	1
Passenger cars	149	98		-	247
4 tire, single unit	79	25		-	104
Buses	0	1		-	1
2 axle, 6 tire, single unit	3	2		-	5
3 axle, single unit	0	0		-	0
4 or more axle, single unit	0	0		-	0
4 or less axle, single trailer	0	0		-	0
5-axle tractor semitrailer	0	0		-	0
6 or more axle, single trailer	0	0		-	0
5 or less axle, multi trailer	0	0		-	0
6 axle, multi-trailer	0	0		-	0
7 or more axle, multi-trailer	0	0		-	0
			1		
Motorcycles (%)	0.43	0.00		-	0.28
Passenger cars (%)	64.22	77.78		-	68.99
4 tire, single unit (%)	34.05	19.84		-	29.05
Buses (%)	0.00	0.79		-	0.28
2 axle, 6 tire, single unit (%)	1.29	1.59		-	1.40
3 axle, single unit (%)	0.00	0.00		-	0.00
4 or more axle, single unit (%)	0.00	0.00		-	0.00
4 or less axle, single trailer (%)	0.00	0.00		-	0.00
5-axle tractor semitrailer (%)	0.00	0.00		-	0.00
6 or more axle, single trailer (%)	0.00	0.00		-	0.00
5 or less axle, multi trailer (%)	0.00	0.00		-	0.00
6 axle, multi-trailer (%)	0.00	0.00		-	0.00
7 or more axle, multi-trailer (%)	0.00	0.00			0.00
	1				
DHE	0.710	0.000	1		0.700
PHF	0.716	0.829		-	0.792







0.792

Florence, AL Classified Turn Movement Count

Site 1 of 1 S Cox Creek Pkwy (South)

Lat/Long 34.806695°, -87.627815°

Date Thursday 27 July 2017


Weather


Sunny Intervals Temp: 36°C

Peak Hour Data (Interactive Diagram)



41 Peabody Street, Nashville, TN 37210 1 (615) 431-6750 1 (800) 615-3765







			Northbound S Cox Creek Pkwy (South)
TME	Thru 1.1	Thru 1.2	Peds Ap 1a Tot
0000 - 0015 0015 - 0030	1	1 4	0 2
0030 - 0045	3	1	0 4
0045 - 0100 Hourly Total	6	1	0 1
0100 - 0115 0115 - 0130	0	3	0 3
0130 - 0145	0	2	0 2
0145 - 0200 Hourly Total	0	1	0 1
0200 - 0215	1	Ő	0 1
0215 - 0230 0230 - 0245	2	2	0 4
0245 - 0300	1	0	0 1
Hourly Total 0300 - 0315	4	2	0 6
0315 - 0330	0	1	0 1
0330 - 0345 0345 - 0400	1	3	0 4
Hourly Total	2	4	0 4
0400 - 0415	2	3	0 5
0415 - 0430 0430 - 0445	0	5	0 6
0445 - 0500	0	5	0 5
Hourly Total 0500 - 0515	3	15 5	0 6
0515 - 0530	1	5 14	0 6
0530 - 0545 0545 - 0600	4	14	0 15
Hourly Total	7	41	0 48
0600 - 0615 0615 - 0630	2	21 26	0 23
0630 - 0645	5	40	0 45
0645 - 0700 Hourly Total	19 35	46	0 65
0700 - 0715	10	21	0 31
0715 - 0730 0730 - 0745	10	31 24	0 41 0 35
0745 - 0800	21	23	0 44
Hourly Total 0800 - 0815	52 12	99 26	0 15
0815 - 0830	24	20	0 30
0830 - 0845 0845 - 0900	20	14 15	0 34
Hourly Total	71	72	0 14
0900 - 0915 0915 - 0930	15 16	18 16	0 33
	23	14	0 32
0930 - 0945 0945 - 1000 Hourly Total	17	19	0 36
1000 - 1015	71	67 16	0 30
1015 - 1030	18	18	0 36
1030 - 1045 1045 - 1100	23 25	21 21	0 46
Hourly Total	80	76	0 15
1115 - 1130	43 25	18 28	0 61 0 53
1130 - 1145 1145 - 1200	27	22 28	0 49
1145 - 1200 Hourly Total	27	28 96	0 55
1200 - 1215	23	29 23	0 52
1215 - 1230 1230 - 1245	33 28	23 23	0 56
1245 - 1300	35	22	0 57
Hourly Total 1300 - 1315	119 31	97 27	0 21
1315 - 1330	24	14	0 38
1330 - 1345 1345 - 1400	26 17	27	0 53 0 51
Hourly Total	98	102	0 20
1400 - 1415	29	33	0 62
1415 - 1430 1430 - 1445	30 32	33 33	0 63
1445 - 1500	23	32	0 55
Hourly Total 1500 - 1515	114	131 33	0 24
1515 - 1530	35	31	0 66
1530 - 1545 1545 - 1600	78	23 28	0 10
Hourly Total	200	115	0 31
1600 - 1615 1615 - 1630	37 48	31 36	0 68
1630 - 1645	32	28	0 60
1645 - 1700 Hourly Total	35 152	26 121	0 61
1700 - 1715	56	41 29	0 97
1715 - 1730 1730 - 1745	44 34	29 29	0 73
1745 - 1800	40	20	0 60
Hourly Total 1800 - 1815	174	119 35	0 290
1815 - 1830	26	39	0 65
1830 - 1845 1845 - 1900	39	29	0 68
Hourly Total	119	136	0 25
1900 - 1915 1915 - 1930	24 39	33 30	0 57
1930 - 1945	21	25	0 46
1945 - 2000 Hourly Total	14 98	20	0 34
2000 - 2015	21	108 19	0 40
2015 - 2030	14	29	0 43
2030 - 2045 2045 - 2100	8	27	0 35
Hourly Total	52	99	0 15
2100 - 2115 2115 - 2130	14	22	0 36
2130 - 2145 2145 - 2200	1	28	0 29
Hourly Total	5	20 87	0 12
	6	15	0 21
2200 - 2215		A	U 16
2215 - 2230 2230 - 2245	2	9 11	0 13
2215 - 2230 2230 - 2245 2245 - 2300	2	9 11 8	0 13
2215 - 2230 2230 - 2245 2245 - 2300 Hourty Total 2300 - 2315	2 5 20 9	9 11 8 43 13	0 13
2215 - 2230 2230 - 2245 2245 - 2300 Hourly Total 2300 - 2315 2315 - 2330	2 5 20 9 5	9 11 8 43 13 9	0 13 0 63 0 22 0 14
2215 - 2230 2230 - 2245 2245 - 2300 Houry Total 2300 - 2315 2330 - 2345 2330 - 2345 2345 - 0000	2 5 20 9 5 4 5	9 11 8 43 13 9 9 1	0 13 0 63 0 22 0 14 0 13 0 6
2215 - 2230 2230 - 2245 2245 - 2300 Houry Total 2300 - 2315 2315 - 2330 2330 - 2345	2 5 20 9 5 4 5	9 11 8 43 13 9 9	0 13 0 63 0 22 0 14
2215 - 2230 2230 - 2245 2245 - 2300 Houry Total 2300 - 2315 2330 - 2345 2330 - 2345 2345 - 0000	2 5 20 9 5 4 5 23	9 11 8 43 13 9 9 1	0 13 0 63 0 22 0 14 0 13 0 6
2215 - 2220 2230 - 2245 2245 - 2300 Hourly Total 2300 - 2315 2315 - 2330 2230 - 2345 2345 - 0000 Hourly Total	2 5 20 9 5 4 5 23	9 11 8 43 13 9 9 9 1 32	0 113 0 63 0 22 0 14 0 13 0 6 0 55
215 - 2230 220 - 2245 2245 - 2300 Hourly Tetal 2200 - 2315 2315 - 2330 2320 - 2345 2345 - 0000 Hourly Tetal Grand Tetal App Percentage	2 5 20 9 5 4 5 23 1660 47.81	9 11 8 43 13 9 9 1 32 1812 52.19	0 13 0 63 0 22 0 14 0 13 0 6 0 95 0 347 0 347
215 - 2230 2230 - 2445 2245 - 2200 Hown Total 2200 - 2215 2215 - 2330 2235 - 2345 2235 - 6000 Hown/Total Grand Total	2 5 20 9 5 4 5 23 1660	9 11 8 43 13 9 9 1 32 1812	0 13 0 63 0 22 0 14 0 13 0 6 0 347 0 347
215 - 520 228 - 528 228 - 520 Houry Teal 200 - 2315 215 - 520 215 - 520 Houry Teal Caned Tabl App Percentage htPercentage	2 5 20 9 5 4 4 5 23 1660 47.81 47.81	9 11 8 43 13 9 9 1 32 1812 52.19 52.19	0 13 0 00 22 0 14 0 22 0 14 0 33 0 55 0 34 0 35 0 34 0 35 0 35 0 0 0 0 0 0 0 0 0 0 0 0 0
215 - 520 226 - 528 245 - 520 How'r fael 200 - 215 215 - 226 215 - 226 215 - 226 215 - 226 215 - 226 215 - 226 215 - 226 225 - 500 How'r fael Gened Tabl Gened Tabl	2 5 20 9 5 4 5 23 1660 47.81 47.81 47.81	9 11 8 43 9 9 1 32 1812 52.19 52.19	0 13 0 00 22 0 14 0 15 0 5 0 5 0 5 0 5 0 5 0 5 0 5 0
215 - 520 226 - 524 245 - 520 Heart Fall 220 - 215 215 - 224 220 - 215 215 - 224 220 - 215 215 - 224 225 - 500 Heart Tabl Genet Tabl Genet Tabl Mobrophs Mobrophs Passenger can 4 - 5 - 5 - 5 - 5 - 5 - 5 - 5 - 5 - 5 -	2 5 20 9 5 4 4 5 23 1680 47.81 47.81 1189 452	9 11 8 43 9 9 1 32 1812 52.19 52.19 52.19 52.19 52.19	0 13 0 23 0 22 0 22 0 34 0 35 0 35 0 0 0 0 0 0 0 0 0 0 0 0 0
215 - 220 226 - 226 245 - 220 Newly Teal 220 - 275 215 - 226 215 - 226 215 215 215 215 215 215 215 215 215 215	2 5 20 9 5 4 5 23 1680 47.81 47.81 47.81 11189 452 0	9 11 8 43 9 9 1 32 1812 52.19 52.19 52.19 52.19 1 2 1287 507 1	
215 - 220 226 - 226 226 - 226 226 - 226 226 - 226 220 - 2215 215 - 2216 215 - 2216 215 - 2216 215 - 2216 215 - 2216 215 - 2216 215 - 2216 216 - 2216	2 5 20 9 5 4 4 5 23 1680 47.81 47.81 1189 452	9 11 8 43 9 9 1 32 1812 52.19 52.19 52.19 52.19 52.19	
215 - 220 220 - 2245 226 - 2260 1860 - 2545 2015 - 255	2 5 20 9 5 4 5 5 23 1680 47.81 47.81 47.81 11 1180 452 0 18 0 0 0	9 11 8 43 13 9 9 1 32 1812 52.19 52.19 52.19 2 1287 507 1 15 0 0	
215 - 220 226 - 2285 226 - 2285 226 - 2285 226 - 2285 220 - 2215 210 - 2215 210 - 2215 220 - 2385 220 - 2	2 5 20 9 5 4 5 23 1660 47.81 47.81 47.81 47.81 1189 452 0 8 8 8 0	9 11 8 43 13 9 9 1 32 52.19 52.19 52.19 2 1287 507 1 507 1 50 0	0 3 0 3 0 0
215 - 220 226 - 226 226 - 226 226 - 226 226 - 226 226 - 226 226 - 226 227 - 227 229 - 228 229 - 228	2 5 20 9 5 4 5 23 1680 47.81 47.81 1189 45.2 0 188 0 0 0 0 0 0 0 0	9 9 11 8 43 13 9 9 9 1 132 1812 52.19 52.19 52.29 1287 1 15 0 0 0 0 0 0	
215 - 220 225 - 225 226 - 225 226 - 225 226 - 225 225 - 225 226 - 225	2 5 20 9 5 4 5 23 1660 47.81 47.81 47.81 47.81 1189 452 0 18 0 0 0 0	9 111 8 43 13 9 9 9 1 1 32 1812 1812 2 1287 507 1 15 0 0 0 0 0	
215 - 226 226 - 228 226 - 228 226 - 228 226 - 228 220 - 2215 215 - 2215 215 - 2216 215 - 228 220 - 22	2 5 20 9 5 4 5 23 1660 47.81 47.81 47.81 47.81 1189 452 0 18 10 0 0 0 0 0 0 0 0	9 11 8 43 13 9 9 9 1 132 52.19 52.19 52.19 52.19 507 1 15 0 0 0 0 0 0 0	
215 - 220 225 - 225 226 - 225 226 - 225 226 - 215 220 - 215 2215 - 2235 2215 - 2215 2215	2 5 20 9 5 4 4 5 23 1060 47.81 47.81 1180 1180 0 118 0 0 0 0 0 0 0 0 0 0 0	9 9 11 8 43 9 9 9 1 132 1812 52.19 52.19 52.19 52.19 12.87 15 0 0 0 0 0 0 0 0	
215 - 220 220 - 2245 226 - 226 226 - 226 226 - 226 227 227 228 - 227 229 - 2215 229 - 22	2 5 20 9 5 5 7 20 9 9 5 7 23 20 9 9 5 7 23 23 23 23 23 24 24 24 21 23 20 9 9 5 7 20 9 9 5 7 20 9 9 5 7 20 9 9 5 5 20 9 9 5 5 5 20 9 9 5 5 5 20 9 9 5 5 20 9 9 5 5 20 9 9 5 5 20 9 9 5 5 20 9 9 5 5 20 9 9 5 5 20 9 9 5 5 20 9 9 5 5 20 9 9 5 5 20 9 1 20 9 1 20 20 1 20 1 20 20 1 20 20 20 20 20 20 20 20 20 20 20 20 20	9 11 8 43 9 9 1 32 1812 1812 2 1812 2 1287 52.19 52.19 52.19 52.19 52.10 0 0 0 0 0 0 0 0 0 0 0 0 0	
215 - 226 226 - 228 226 - 228 226 - 228 226 - 228 220 - 2215 215 - 2216 215 - 2216 215 - 2216 215 - 2216 215 - 2216 215 - 2216 216 - 2216	2 5 30 9 5 4 4 5 22 23 47.81 47.81 47.81 1189 452 0 0 118 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	9 11 8 43 9 9 1 32 1812 1812 2 1287 52.19 2 2 1287 507 1 507 0 0 0 0 0 0 0 0 0 0 0 0 0	
215 - 220 226 - 226 226 - 226 226 - 226 226 - 226 220 - 2215 215 - 2216 215 - 2216 215 - 2216 215 - 2216 215 - 2216 215 - 2216 215 - 2216 216 - 2216	2 5 20 9 5 4 4 5 7 22 22 22 47.81 47.81 1189 452 0 1188 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	9 11 8 43 9 9 1 13 9 9 1 32 52 19 1287 507 1 15 507 1 15 0 0 0 0 0 0 0 0 0 0 0 0 0	
215 - 226 216 - 226 216 - 226 216 - 226 226 -	2 5 20 9 5 4 4 5 5 23 4 7 8 1 8 6 6 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	9 11 8 43 9 9 1 13 2 1812 1812 2 1287 52 19 52 19 52 19 0 0 0 0 0 0 0 0 0 0 0 0 0	
215 - 220 226 - 226 226 - 226	2 5 5 5 5 5 4 4 5 5 5 7 8 9 5 5 7 4 7 8 1 9 5 5 7 4 7 8 1 8 9 7 5 7 8 7 8 1 8 9 7 5 7 8 7 8 1 8 7 8 1 9 7 5 7 8 7 8 7 8 7 8 7 8 7 8 7 8 7 8 7 8	9 9 11 8 43 13 9 9 9 1 1 32 18 12 22 19 50 19 50 19 50 19 50 19 50 19 50 19 50 19 50 19 50 19 50 19 50 19 50 19 50 10 10 10 10 10 10 10 10 10 1	
215 - 220 226 - 226 226 - 226 226 - 226 226 - 226 226 - 226 226 - 226 220 - 215 220 - 215 220 - 226 220 - 226 200 - 226	2 2 3 5 5 23 5 5 23 5 23 5 23 5 23 5 23	9 9 11 8 43 13 9 9 1 32 1812 52.19 52.1	0 13 0 13 0 13 0 13 0 13 0 13 0 13 0 13 0 13 0 13 0 13 10 13
215 - 220 225 - 225 226 - 225 226 - 225 226 - 215 226 - 215 226 - 215 225 - 225 225 - 225	2 5 5 5 5 4 4 5 5 7 23 7 1660 47.81 1189 452 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	9 9 11 8 43 13 9 9 1 32 1812 52 19 50 10 10 52 19 50 10 10 10 10 10 10 10 10 10 1	
215 - 226 226 - 226	2 5 5 5 5 5 4 4 5 5 5 4 4 5 5 7 4 9 5 5 7 4 9 5 5 7 4 9 5 7 8 7 8 1 8 660 9 9 5 5 7 8 7 8 1 8 7 8 1 9 7 5 7 8 7 8 7 8 7 8 7 8 7 8 7 8 7 8 7 8	9 9 11 8 43 13 9 9 1 1 32 1812 2 1812 2 2 2 1812 2 2 1812 2 1812 507 1 15 0 0 0 0 0 0 0 0 0 0 0 0 0	

Grand Total (All Sessions)


TIME 1.1 1.2 1a Total				Northbound			
Thru Thru Thru Thru Thru Thru Thru Thru Total 1a Total 0 3472 Grand Total 1660 1812 0 3472 0 3472 App Percentage 47.81 52.19 0.00 0.00 100.00 Int Percentage 47.81 52.19 0.00 100.00 Motorcycles 1 2 - 3 - 2476 4 tire, single unit 452 507 - 959 - 1 - 33 - 0 - </th <th></th> <th colspan="6">S Cox Creek Pkwy (South)</th>		S Cox Creek Pkwy (South)					
Grand Total 1660 1812 App Percentage 47.81 52.19 Int Percentage 47.81 52.19 Motorcycles 1 2 Passenger cars 1189 1287 4 tire, single unit 452 507 Buses 0 1 2 axle, 6 tire, single unit 0 0 4 or more axle, single trailer 0 0 4 or more axle, single trailer 0 0 6 or more axle, single trailer 0 0 5 or less axle, multi trailer 0 0 7 or more axle, multi-trailer 0 0 7 or more axle, single unit (%) 0.00 0.00 7 or more axle, multi-trailer 0 0 989 0.00 0.00 - 0 0 - 0 7 or more axle, multi-trail		Thru	Thru		Peds	Арр	
$\begin{array}{c c c c c c c c c c c c c c c c c c c $	TIME	1.1	1.2		1a	Total	
Int Percentage 47.81 52.19 0.00 100.00 Motorcycles 1 2 - 3 - 2476 4 tire, single unit 452 507 - 959 - 1 2 axle, 6 tire, single unit 452 507 - 959 - 1 2 axle, 6 tire, single unit 0 1 - 3 - 1 - 33 3 axle, single unit 0 0 - 0 <td< td=""><td>Grand Total</td><td>1660</td><td>1812</td><td></td><td>0</td><td>3472</td></td<>	Grand Total	1660	1812		0	3472	
Int Percentage 47.81 52.19 0.00 100.00 Motorcycles 1 2 - 3 - 2476 4 tire, single unit 452 507 - 959 - 1 2 axle, 6 tire, single unit 452 507 - 959 - 1 2 axle, 6 tire, single unit 0 1 - 3 - 1 - 33 3 axle, single unit 0 0 - 0 <td< td=""><td></td><td></td><td></td><td></td><td></td><td></td></td<>							
Int Percentage 47.81 52.19 0.00 100.00 Motorcycles 1 2 - 3 - 2476 4 tire, single unit 452 507 - 959 - 1 2 axle, 6 tire, single unit 452 507 - 959 - 1 2 axle, 6 tire, single unit 0 1 - 3 - 1 - 33 3 axle, single unit 0 0 - 0 <td< td=""><td></td><td></td><td></td><td></td><td></td><td></td></td<>							
Motorcycles 1 2 Passenger cars 1189 1287 - 2476 4 tire, single unit 452 507 - 959 Buses 0 1 - 1 2 axle, 6 tire, single unit 18 15 - 33 3 axle, single unit 0 0 - 0 4 or more axle, single trailer 0 0 - 0 5 axle tractor semitrailer 0 0 - 0 5 or less axle, nulti-trailer 0 0 - 0 6 axle, multi-trailer 0 0 - 0 7 or more axle, single unit (%) 27.23 27.82 - 27.62 Buses (%) 0.00 0.06 - 0.00 - 0.00 4 tire, single unit (%) 1.08 0.83 - 0.95 - 0.92 9 27.62 Buses (%) 0.00 0.06 - 0.00 - 0.00 <	App Percentage						
Passenger cars 1189 1287 4 tire, single unit 452 507 Buses 0 1 2 axle, 6 tire, single unit 18 15 3 axle, single unit 0 0 4 or ress axle, single unit 0 0 4 or ress axle, single trailer 0 0 5 axle tractor semitrailer 0 0 6 or more axle, single trailer 0 0 6 or more axle, single trailer 0 0 6 axle, multi-trailer 0 0 7 or more axle, multi-trailer 0 0 7 or more axle, multi-trailer 0 0 9 9 27.23 27.98 9 9 27.23 27.82 9 9 0.00 0.06 10 1.08 0.83 2 axle, 6 tire, single unit (%) 1.08 0.83 3 axle, single unit (%) 0.00 0.00 4 or ess axle, single trailer (%) 0.00 0.00 4 or oresa	Int Percentage	47.81	52.19		0.00	100.00	
Passenger cars 1189 1287 4 tire, single unit 452 507 Buses 0 1 2 axle, 6 tire, single unit 18 15 3 axle, single unit 0 0 4 or ress axle, single unit 0 0 4 or ress axle, single trailer 0 0 5 axle tractor semitrailer 0 0 6 or more axle, single trailer 0 0 6 or more axle, single trailer 0 0 6 axle, multi-trailer 0 0 7 or more axle, multi-trailer 0 0 7 or more axle, multi-trailer 0 0 9 9 27.23 27.98 9 9 27.23 27.82 9 9 0.00 0.06 10 1.08 0.83 2 axle, 6 tire, single unit (%) 1.08 0.83 3 axle, single unit (%) 0.00 0.00 4 or ess axle, single trailer (%) 0.00 0.00 4 or oresa							
Passenger cars 1189 1287 4 tire, single unit 452 507 Buses 0 1 2 axle, 6 tire, single unit 18 15 3 axle, single unit 0 0 4 or ress axle, single unit 0 0 4 or ress axle, single trailer 0 0 5 axle tractor semitrailer 0 0 6 or more axle, single trailer 0 0 6 or more axle, single trailer 0 0 6 axle, multi-trailer 0 0 7 or more axle, multi-trailer 0 0 7 or more axle, multi-trailer 0 0 9 9 27.23 27.98 9 9 27.23 27.82 9 9 0.00 0.06 10 1.08 0.83 2 axle, 6 tire, single unit (%) 1.08 0.83 3 axle, single unit (%) 0.00 0.00 4 or ess axle, single trailer (%) 0.00 0.00 4 or oresa				1			
4 tire, single unit 452 507 Buses 0 1 2 axle, 6 tire, single unit 18 15 3 3 axle, single unit 0 0 4 or more axle, single unit 0 0 4 or more axle, single trailer 0 0 5 axle, single trailer 0 0 5 or less axle, multi trailer 0 0 6 or more axle, single trailer 0 0 5 or less axle, multi trailer 0 0 7 or more axle, multi-trailer 0 0 7 or more axle, multi-trailer 0 0 9 0 0 0 9 0.00 0.00 0 7 or more axle, multi-trailer 0 0 0 9 0.00 0.00 0 0 9 0.00 0.00 0.00 0.00 10 0.00 0.00 0.00 0.00 11 10 0.00 0.00 0.00 10<					-		
Buses 0 1 2 axle, 6 füre, single unit 18 15 3 axle, single unit 0 0 4 or more axle, single unit 0 0 4 or more axle, single trailer 0 0 5-axle tractor semitrailer 0 0 6 or more axle, single trailer 0 0 5 or less axle, multi-trailer 0 0 6 or more axle, single trailer 0 0 7 or more axle, multi-trailer 0 0 7 or more axle, multi-trailer 0 0 7 or more axle, single unit (%) 0.06 0.11 9 9 9 Motorcycles (%) 0.00 0.06 9 0.00 0.00 9 1.88 es (%) 0.00 0.00 9 3 2.27.62 9 10 0.00 0.00 0.00 4 or more axle, single unit (%) 0.00 0.00 4 or more axle, single unit (%) 0.00 0.00 4 or mor					-		
2 axle, 6 tire, single unit 18 15 3 axle, single unit 0 0 4 or more axle, single trailer 0 0 5 axle tractor semitrailer 0 0 5 or less axle, multi trailer 0 0 6 axle, multi-trailer 0 0 7 or more axle, multi-trailer 0 0 7 or more axle, multi-trailer 0 0 9 0 - 0 10 71.63 71.03 - 11 - 0.00 - 0.03 2 axle, fingle unit (%) 27.23 27.98 - 27.62 Buses (%) 0.00 0.06 - 0.03 - 0.095 3 axle, single unit (%) 0.00 0.00 - 0.00 - 0.00 4 or more axle, single trailer (%) 0.00 0.00					-		
3 axle, single unit 0 0 4 or more axle, single unit 0 0 4 or less axle, single trailer 0 0 5 axle tractor semitrailer 0 0 6 or more axle, single trailer 0 0 5 or less axle, multi trailer 0 0 6 axle, multi-trailer 0 0 7 or more axle, multi-trailer 0 0 9 0 0 - 10 0 0 - 11 0 0 - 12 0 0 - 13 11 - 0.09 14 176.3 71.03 - 14 176.3 10.03 - 15 3 axle, single unit (%) 0.00 0.06 2 axle, 6 tire, single unit (%) 0.00 0.00		-			-		
4 or more axle, single unit 0 0 4 or more axle, single trailer 0 0 5-axle tractor semitrailer 0 0 6 or more axle, single trailer 0 0 5 or less axle, multi-trailer 0 0 7 or more axle, single trailer 0 0 7 or more axle, single trailer 0 0 7 or more axle, single trailer 0 0 7 or more axle, single unit (%) 0.06 0 7 or more axle, single unit (%) 27.23 27.98 Buses (%) 0.00 0.06 2 axle, fitre, single unit (%) 0.00 0.00 4 or more axle, single unit (%) 0.00 0.00 4 or more axle, single trailer (%) 0.00 0.00 4 or more axle, single trailer (%) 0.00 0.00 5 or less axle, single trailer (%) 0.00 0.00 6 or more axle, single trailer (%) 0.00 0.00 6 or more axle, single trailer (%) 0.00 0.00 6 or more axle, single trailer (%) 0.00 0.00 </td <td></td> <td></td> <td></td> <td></td> <td>-</td> <td></td>					-		
4 or less axle, single trailer 0 0 5-axle tractor semitrailer 0 0 6 or more axle, single trailer 0 0 5 or less axle, multi trailer 0 0 6 or more axle, single trailer 0 0 6 axle, multi-trailer 0 0 7 or more axle, multi-trailer 0 0 7 or more axle, multi-trailer 0 0 9 0 - 0 9 0 - 0 9 0 - 0 9 0 - 0 9 0 - 0 9 - 0 - 9 - 0 - 9 - 0 - 0 14 tree, single unit (%) 27.23 27.98 - 22.762 13 axle, single unit (%) 0.00 0.00 - 0.00 4 or more axle, single unit (%) 0.00 0.00 - 0.00					-		
5-axle tractor semitrailer 0 0 6 or more axle, single trailer 0 0 5 or less axle, multi trailer 0 0 6 axle, multi-trailer 0 0 7 or more axle, multi-trailer 0 0 7 or more axle, multi-trailer 0 0 7 or more axle, multi-trailer 0 0 9 0 0 9 0 0 10 0 0 11 0 0 12 0 0 13 14 tire, single unit (%) 27.23 14 10 0.00 12 0.00 0.06 13 2 axle, single unit (%) 0.00 10 0.00 0.00 2 axle, single trailer (%) 0.00 0.00 4 or more axle, single trailer (%) 0.00 0.00 4 or more axle, single trailer (%) 0.00 0.00 5 arke tractor semitrailer 0.00 0.00 5 or less axle, single tr			-		-		
6 or more axle, single trailer 0 0 5 or less axle, multi trailer 0 0 6 axle, multi-trailer 0 0 7 or more axle, multi-trailer 0 0 7 or more axle, multi-trailer 0 0 9 0 0 9 0 0 9 0 0 9 0 0 9 0 0 9 0 0 9 0 0 9 0 0 9 0 0.06 10 0 0 11 0 0.09 12 27.82 27.62 13 1 4 tire, single unit (%) 1.08 12 3 axle, single unit (%) 0.00 0.00 13 1.08 0.63 - 0.02 2 axle, single unit (%) 0.00 0.00 4 or more axle, single trailer (%) 0.00 0.00					-		
5 or less axle, multi trailer 0 0 6 axle, multi-trailer 0 0 7 or more axle, multi-trailer 0 0 7 or more axle, multi-trailer 0 0 9 - 0 9 - 0 9 - 0 9 - 0 9 - 0 9 - 0 9 - 0 9 - 0 9 - 71.63 14 tire, single unit (%) 27.23 27.98 2 axle, 6 tire, single unit (%) 0.00 0.00 14 or more axle, single unit (%) 0.00 0.00 4 or more axle, single unit (%) 0.00 0.00 4 or more axle, single trailer (%) 0.00 0.00 0 or more axle, single trailer (%) 0.00 0.00 5 or less axle, multi-trailer (%) 0.00 0.00 6 or more axle, single trailer (%) 0.00 0.00 0 0.00<					-		
6 axle, multi-trailer 0 0 7 or more axle, multi-trailer 0 0 Motorcycles (%) 0.06 0.11 Passenger cars (%) 71.63 71.03 4 tire, single unit (%) 27.23 27.98 Buses (%) 0.00 0.06 2 axle, 6 tire, single unit (%) 1.08 0.83 3 axle, single unit (%) 0.00 0.00 4 or more axle, single trailer (%) 0.00 0.00 5 or less axle, single trailer (%) 0.00 0.00 5 or less axle, multi-trailer (%) 0.00 0.00 6 or more axle, imgle trailer (%) 0.00 0.00 5 or less axle, multi-trailer (%) 0.00 0.00 6 axle, multi-trailer (%) 0.00 0.00					-		
7 or more axle, multi-trailer 0 0 Motorcycles (%) 0.06 0.11 - 0.09 Passenger cars (%) 71.63 71.03 - 71.31 4 tire, single unit (%) 27.23 27.98 - 27.62 Buses (%) 0.00 0.06 - 0.03 2 axle, 6 tire, single unit (%) 1.08 0.83 - 0.95 3 axle, single unit (%) 0.00 0.00 - 0.00 4 or more axle, single unit (%) 0.00 0.00 - 0.00 4 or more axle, single trailer (%) 0.00 0.00 - 0.00 5 axle tractor semitrailer (%) 0.00 0.00 - 0.00 5 or less axle, single trailer (%) 0.00 0.00 - 0.00 5 or less axle, multi-trailer (%) 0.00 0.00 - 0.00 6 axle, multi-trailer (%) 0.00 0.00 - 0.00					-		
Motorcycles (%) 0.06 0.11 - 0.09 Passenger cars (%) 71.63 71.03 - 71.31 4 tire, single unit (%) 27.23 27.98 - 27.62 Buses (%) 0.00 0.06 - 0.03 2 axle, 6 tire, single unit (%) 0.00 0.00 - 0.00 4 or more axle, single unit (%) 0.00 0.00 - 0.00 4 or more axle, single trailer (%) 0.00 0.00 - 0.00 5 axle tractor semitrailer (%) 0.00 0.00 - 0.00 5 or less axle, multi trailer (%) 0.00 0.00 - 0.00 6 axle, multi trailer (%) 0.00 0.00 - 0.00					-		
Passenger cars (%) 71.63 71.03 4 tire, single unit (%) 27.23 27.98 - 27.62 Buses (%) 0.00 0.06 - 0.03 2 axle, 6 tire, single unit (%) 1.08 0.83 - 0.95 3 axle, single unit (%) 0.00 0.00 - 0.00 4 or more axle, single unit (%) 0.00 0.00 - 0.00 4 or more axle, single trialer (%) 0.00 0.00 - 0.00 5 axle tractor semitrailer (%) 0.00 0.00 - 0.00 5 or less axle, single trialer (%) 0.00 0.00 - 0.00 6 or more axle, single trialer (%) 0.00 0.00 - 0.00 5 or less axle, multi-trialer (%) 0.00 0.00 - 0.00 6 axle, multi-trialer (%) 0.00 0.00 - 0.00	7 or more axle, multi-trailer	0	0		-	0	
Passenger cars (%) 71.63 71.03 4 tire, single unit (%) 27.23 27.98 - 27.62 Buses (%) 0.00 0.06 - 0.03 2 axle, 6 tire, single unit (%) 1.08 0.83 - 0.95 3 axle, single unit (%) 0.00 0.00 - 0.00 4 or more axle, single unit (%) 0.00 0.00 - 0.00 4 or more axle, single trialer (%) 0.00 0.00 - 0.00 5 axle tractor semitrailer (%) 0.00 0.00 - 0.00 5 or less axle, single trialer (%) 0.00 0.00 - 0.00 6 or more axle, single trialer (%) 0.00 0.00 - 0.00 5 or less axle, multi-trialer (%) 0.00 0.00 - 0.00 6 axle, multi-trialer (%) 0.00 0.00 - 0.00							
Passenger cars (%) 71.63 71.03 4 tire, single unit (%) 27.23 27.98 - 27.62 Buses (%) 0.00 0.06 - 0.03 2 axle, 6 tire, single unit (%) 1.08 0.83 - 0.95 3 axle, single unit (%) 0.00 0.00 - 0.00 4 or more axle, single unit (%) 0.00 0.00 - 0.00 4 or more axle, single trialer (%) 0.00 0.00 - 0.00 5 axle tractor semitrailer (%) 0.00 0.00 - 0.00 5 or less axle, single trialer (%) 0.00 0.00 - 0.00 6 or more axle, single trialer (%) 0.00 0.00 - 0.00 5 or less axle, multi-trialer (%) 0.00 0.00 - 0.00 6 axle, multi-trialer (%) 0.00 0.00 - 0.00				1			
4 tire, single unit (%) 27.23 27.98 - 27.62 Buses (%) 0.00 0.06 - 0.03 2 axle, 6 tire, single unit (%) 1.08 0.83 - 0.95 3 axle, single unit (%) 0.00 0.00 - 0.00 4 or more axle, single unit (%) 0.00 0.00 - 0.00 4 or less axle, single trailer (%) 0.00 0.00 - 0.00 5 axle tractor semitrailer (%) 0.00 0.00 - 0.00 5 or less axle, single trailer (%) 0.00 0.00 - 0.00 5 or less axle, multi-trailer (%) 0.00 0.00 - 0.00 6 axle, multi-trailer (%) 0.00 0.00 - 0.00					-		
Buses (%) 0.00 0.06 - 0.03 2 axle, 6 tire, single unit (%) 1.08 0.83 - 0.95 3 axle, single unit (%) 0.00 0.00 - 0.00 4 or more axle, single unit (%) 0.00 0.00 - 0.00 4 or less axle, single trailer (%) 0.00 0.00 - 0.00 5-axle tractor semitrailer (%) 0.00 0.00 - 0.00 6 or more axle, single trailer (%) 0.00 0.00 - 0.00 5 or less axle, multi-trailer (%) 0.00 0.00 - 0.00 6 axle, multi-trailer (%) 0.00 0.00 - 0.00					-		
2 axle, 6 tire, single unit (%) 1.08 0.83 - 0.95 3 axle, single unit (%) 0.00 0.00 - 0.00 4 or more axle, single unit (%) 0.00 0.00 - 0.00 4 or more axle, single trailer (%) 0.00 0.00 - 0.00 5 -axle tractor semitrailer (%) 0.00 0.00 - 0.00 5 or more axle, single trailer (%) 0.00 0.00 - 0.00 5 or less axle, multi-trailer (%) 0.00 0.00 - 0.00 6 axle, multi-trailer (%) 0.00 0.00 - 0.00					-		
3 axle, single unit (%) 0.00 0.00 - 0.00 4 or more axle, single unit (%) 0.00 0.00 - 0.00 4 or less axle, single trailer (%) 0.00 0.00 - 0.00 5-axle tractor semitrailer (%) 0.00 0.00 - 0.00 6 or more axle, single trailer (%) 0.00 0.00 - 0.00 5 or less axle, multi trailer (%) 0.00 0.00 - 0.00 6 axle, multi-trailer (%) 0.00 0.00 - 0.00					-		
4 or more axle, single unit (%) 0.00 0.00 - 0.00 4 or less axle, single trailer (%) 0.00 0.00 - 0.00 5-axle tractor semitrailer (%) 0.00 0.00 - 0.00 6 or more axle, single trailer (%) 0.00 0.00 - 0.00 5 or less axle, multi-trailer (%) 0.00 0.00 - 0.00 6 axle, multi-trailer (%) 0.00 0.00 - 0.00					-		
4 or less axle, single trailer (%) 0.00 0.00 - 0.00 5-axle tractor semitrailer (%) 0.00 0.00 - 0.00 6 or more axle, single trailer (%) 0.00 0.00 - 0.00 5 or less axle, multi-trailer (%) 0.00 0.00 - 0.00 6 axle, multi-trailer (%) 0.00 0.00 - 0.00							
5-axle tractor semitrailer (%) 0.00 0.00 - 0.00 6 or more axle, single trailer (%) 0.00 0.00 - 0.00 5 or less axle, multi-trailer (%) 0.00 0.00 - 0.00 6 axle, multi-trailer (%) 0.00 0.00 - 0.00					-		
6 or more axle, single trailer (%) 0.00 0.00 - 0.00 5 or less axle, multi trailer (%) 0.00 0.00 - 0.00 6 axle, multi-trailer (%) 0.00 0.00 - 0.00					-		
5 or less axle, multi-trailer (%) 0.00 0.00 - 0.00 6 axle, multi-trailer (%) 0.00 0.00 - 0.00					-		
6 axle, multi-trailer (%) 0.00 0.00 - 0.00					-		
					-		
7 or more axle, multi-trailer (%) 0.00 0.00 - 0.00					-		
	7 or more axle, multi-trailer (%)	0.00	0.00		-	0.00	


0000 - 2400 (Weekday 24h Session)

1530 - 1630 (Intersection Peak Hour)

			Northbound		
	-	_	S Cox Creek Pkwy (South)		
70.07	Thru	Thru		Peds	App
TIME	1.1	1.2		1a	Total
1530 - 1545	78	23		0	101
1545 - 1600	45	28		0	73
1600 - 1615	37	31		0	68
1615 - 1630	48	36		0	84
Hourly Total	208	118]	0	326
Crand Tatal	208	118	1	0	326
Grand Total	208	110	_	0	320
App Percentage	63.80	36.20	1	0.00	<u> </u>
Int Percentage	63.80	36.20		0.00	100.00
			1		
Motorcycles	1	1		-	2
Passenger cars	128	92		-	220
4 tire, single unit	77	23		-	100
Buses	0	0		-	0
2 axle, 6 tire, single unit	2	2		-	4
3 axle, single unit	0	0		-	0
4 or more axle, single unit	0	0		-	0
4 or less axle, single trailer	0	0		-	0
5-axle tractor semitrailer	0	0		-	0
6 or more axle, single trailer	0	0		-	0
5 or less axle, multi trailer	0	0		-	0
6 axle, multi-trailer	0	0		-	0
7 or more axle, multi-trailer	0	0		-	0
Motorcycles (%)	0.48	0.85	1	-	0.61
Passenger cars (%)	61.54	77.97		-	67.48
4 tire, single unit (%)	37.02	19.49		-	30.67
Buses (%)	0.00	0.00		-	0.00
2 axle, 6 tire, single unit (%)	0.96	1.69		-	1.23
3 axle, single unit (%)	0.00	0.00		-	0.00
4 or more axle, single unit (%)	0.00	0.00		-	0.00
4 or less axle, single trailer (%)	0.00	0.00		-	0.00
5-axle tractor semitrailer (%)	0.00	0.00	1	-	0.00
6 or more axle, single trailer (%)	0.00	0.00		-	0.00
5 or less axle, multi trailer (%)	0.00	0.00		-	0.00
6 axle, multi-trailer (%)	0.00	0.00		-	0.00
7 or more axle, multi-trailer (%)	0.00	0.00	J	-	0.00
PHF	0.667	0.819]	-	0.807







0.807

Florence, AL Classified Turn Movement Count

Site 1 of 1 S Cox Creek Pkwy (South)

Lat/Long 34.806695°, -87.627815°


Date Friday 28 July 2017

Weather Light Rain Temp: 31°C

Peak Hour Data (Interactive Diagram)



41 Peabody Street, Nashville, TN 37210 1 (615) 431-6750 1 (800) 615-3765




0600 - 0900 (Weekday AM Peak)

0630 - 0730 (Intersection Peak Hour)

			Northbound		
			S Cox Creek Pkwy (South)		
	Thru	Thru	S COX CIEEK F KWY (SOUIII)	Peds	Арр
TIME	1.1	1.2		1a	Total
0630 - 0645	5	40		0	45
0645 - 0700	19	46		0	65
0700 - 0715	10	21		0	31
0715 - 0730	10	31		0	41
Hourly Total	44	138		0	182
Grand Total	44	138		0	182
App Percentage	24.18	75.82		0.00	
Int Percentage	24.18	75.82		0.00	100.00
Motorcycles	0	0		-	0
Passenger cars	20	79		-	99
4 tire, single unit	23	58		-	81
Buses	0	0		-	0
2 axle, 6 tire, single unit	1	1		-	2
3 axle, single unit	0	0		-	0
4 or more axle, single unit	0	0		-	0
4 or less axle, single trailer	0	0		-	0
5-axle tractor semitrailer	0	0		-	0
6 or more axle, single trailer	0	0		-	0
5 or less axle, multi trailer	0	0		-	0
6 axle, multi-trailer	0	0		-	0
7 or more axle, multi-trailer	0	0		-	0
	0.00	0.00	Ì		0.00
Motorcycles (%)					
Passenger cars (%) 4 tire, single unit (%)	45.45 52.27	57.25 42.03		-	54.40 44.51
4 tire, single unit (%) Buses (%)	0.00	42.03			0.00
2 axle, 6 tire, single unit (%)	2.27	0.00		<u> </u>	1.10
3 axle, single unit (%)	0.00	0.72		-	0.00
4 or more axle, single unit (%)	0.00	0.00		-	0.00
4 or less axle, single trailer (%)	0.00	0.00		<u> </u>	0.00
5-axle tractor semitrailer (%)	0.00	0.00		<u> </u>	0.00
6 or more axle, single trailer (%)	0.00	0.00		-	0.00
5 or less axle, multi trailer (%)	0.00	0.00		-	0.00
6 axle, multi-trailer (%)	0.00	0.00		-	0.00
7 or more axle, multi-trailer (%)	0.00	0.00		<u> </u>	0.00
	0.00	0.00	l	<u> </u>	0.00
	1				
PHF	0.579	0.750			0.700
110	0.515	0.150			0.100







0.700

Site 1 of 1 S Cox Creek Pkwy (South)


Lat/Long 34.806695°, -87.627815°

Date Friday 28 July 2017

Weather Light Rain Temp: 31°C

Peak Hour Data (Interactive Diagram)





Peak Hour Window


1100 - 1300 (Weekday Inter Peak)

1100 - 1200 (Intersection Peak Hour)

			Manthelan and		
			Northbound		
	Thru	Thru	S Cox Creek Pkwy (South)	Peds	Арр
TIME	1.1	1.2		1a	Total
1100 - 1115	43	18		0	61
1115 - 1130	25	28		0	53
1130 - 1145	27	20		0	49
1145 - 1200	27	28		0	55
Hourly Total	122	96		0	218
Houry rotar	122	50		0	210
Grand Total	122	96		0	218
App Percentage	55.96	44.04		0.00	
Int Percentage	55.96	44.04		0.00	100.00
			i i		
Motorcycles	0	0		-	0
Passenger cars	77	63		-	140
4 tire, single unit	43	33		-	76
Buses	0	0		-	0
2 axle, 6 tire, single unit	2	0		-	2
3 axle, single unit	0	0		-	0
4 or more axle, single unit	0	0		-	0
4 or less axle, single trailer	0	0		-	0
5-axle tractor semitrailer	0	0		-	0
6 or more axle, single trailer	0	0		-	
5 or less axle, multi trailer 6 axle, multi-trailer	0	0		-	0
	0	0		-	0
7 or more axle, multi-trailer	U	U		-	U
Motorcycles (%)	0.00	0.00		-	0.00
Passenger cars (%)	63.11	65.63		-	64.22
4 tire, single unit (%)	35.25	34.38		-	34.86
Buses (%)	0.00	0.00		-	0.00
2 axle, 6 tire, single unit (%)	1.64	0.00		-	0.92
3 axle, single unit (%)	0.00	0.00		-	0.00
4 or more axle, single unit (%)	0.00	0.00		-	0.00
4 or less axle, single trailer (%)	0.00	0.00		-	0.00
5-axle tractor semitrailer (%)	0.00	0.00		-	0.00
6 or more axle, single trailer (%)	0.00	0.00		-	0.00
5 or less axle, multi trailer (%)	0.00	0.00		-	0.00
6 axle, multi-trailer (%)	0.00	0.00		-	0.00
7 or more axle, multi-trailer (%)	0.00	0.00		-	0.00
		0.005	1		0.007
PHF	0.709	0.857		-	0.893







0.893

Site 1 of 1 S Cox Creek Pkwy (South)


Lat/Long 34.806695°, -87.627815°

Date Friday 28 July 2017

Weather Light Rain Temp: 31°C

Peak Hour Data (Interactive Diagram)






Peak Hour Window


1500 - 1800 (Weekday PM Peak)

1530 - 1630 (Intersection Peak Hour)

			Manthalan und		
			Northbound		
	Thru	Thru	S Cox Creek Pkwy (South)	Peds	Арр
TIME	1.1	1.2		1a	Total
1530 - 1545	78	23		0	101
1545 - 1600	45	28		0	73
1600 - 1615	37	31		0	68
1615 - 1630	48	36		0	84
Hourly Total	208	118		0	326
Tioury rotar	200	110		v	010
Grand Total	208	118		0	326
orana rotar	200				020
App Percentage	63.80	36.20		0.00	
Int Percentage	63.80	36.20		0.00	100.00
Motorcycles	1	1		-	2
Passenger cars	128	92		-	220
4 tire, single unit	77	23		-	100
Buses	0	0		-	0
2 axle, 6 tire, single unit	2	2		-	4
3 axle, single unit	0	0		-	0
4 or more axle, single unit	0	0		-	0
4 or less axle, single trailer	0	0		-	0
5-axle tractor semitrailer	0	0		-	0
6 or more axle, single trailer	0	0		-	0
5 or less axle, multi trailer	0	0		-	0
6 axle, multi-trailer	0	0		-	0
7 or more axle, multi-trailer	0	0		-	0
			1		
Motorcycles (%)	0.48	0.85		-	0.61
Passenger cars (%)	61.54	77.97		-	67.48
4 tire, single unit (%)	37.02	19.49		-	30.67
Buses (%)	0.00	0.00		-	0.00
2 axle, 6 tire, single unit (%)	0.96	1.69		-	1.23
3 axle, single unit (%)	0.00	0.00		-	0.00
4 or more axle, single unit (%)	0.00	0.00		-	0.00
4 or less axle, single trailer (%)	0.00	0.00		-	0.00
5-axle tractor semitrailer (%)	0.00	0.00		-	0.00
6 or more axle, single trailer (%)	0.00	0.00		-	0.00
5 or less axle, multi trailer (%)	0.00	0.00		-	0.00
6 axle, multi-trailer (%)	0.00	0.00		-	0.00
7 or more axle, multi-trailer (%)	0.00	0.00			0.00
	1				
DHE	0.667	0.910	1		0.007
PHF	0.667	0.819		-	0.807







0.807

Site 1 of 1 S Cox Creek Pkwy (South)


Lat/Long 34.806695°, -87.627815°


Date Friday 28 July 2017

Weather Light Rain Temp: 31°C

Peak Hour Data (Interactive Diagram)









0000 - 2400 (Saturday 24h Session)			Northbound	
	Thru	Thru	S Cox Creek Pixey (South)	Арр
TME	1.1	1.2	Peds 1a	Tota
0000 - 0015 0015 - 0030	5	9	0	14
0030 - 0045 0045 - 0100	1	0	0	1 4
Hourly Total	11	12	0	23
0100 - 0115 0115 - 0130	2	1	0	4
0130 - 0145	1	4	0	5
Hourly Total 0200 - 0215	8	12	0	20
0200 - 0215 0215 - 0230	0	2	0	2
0230 - 0245 0245 - 0300	1	2	0	3
Hourly Total 0300 - 0315	3	6	0	9
0300 - 0315 0315 - 0330	2	3	0	5
0330 - 0345	4	Ő	0	4
0345 - 0400 Hourly Total	0	7	0	7 20
0400 - 0415	0	4	0	4
0415 - 0430 0430 - 0445	2	3	0	4
0445 - 0500 Hourly Total	2	4	0	6 17
0500 - 0515	1	4	0	5
0515 - 0530 0530 - 0545	1	3 5	0	4
0545 - 0600	2	4	0	6
Hourly Total 0600 - 0615	5	16 3	0	23
0615 - 0630	5	9 12	0	14
0630 - 0645 0645 - 0700	9	10	0	16
Hourly Total	23	34	0	57
0700 - 0715 0715 - 0730	5	6 8	0	19
0730 - 0745 0745 - 0800	20 25	8 13	0	28 38
Hourly Total 0800 - 0815	61	35	0	30 96 34
0800 - 0815 0815 - 0830	17	17	0	34 25
0830 - 0845	21	20	0	41
0845 - 0900 Hourly Total	18	10	0	28
0900 - 0915	18	15	0	33
0915 - 0930 0930 - 0945	24 23	16 23	0	40
0945 - 1000 Hourly Total	22 87	19 73	0	41
1000 - 1015	14	25	0	39
1015 - 1030 1030 - 1045	32 36	22 23	0	54 59
1045 - 1100	39	22	0	61
Hourly Total 1100 - 1115	121	92 38	0	213 73
1115 - 1130 1130 - 1145	34	24	0	58
1145 - 1200	39 34	31 34	0	70
Hourly Total 1200 - 1215	142	127	0	265
1215 - 1230	31 33	18 31	0	49 64
1230 - 1245 1245 - 1300	45	38	0	83 57
Hourly Total 1300 - 1315	144	109	0	253 67
1300 - 1315 1315 - 1330	33 30	34 29	0	67 59
1330 - 1345 1345 - 1400	26	43	0	69 69
1345 - 1400 Hourly Total	33	36	0	264
1400 - 1415	26	31	0	57
1415 - 1430 1430 - 1445	22 32	36 42	0	58 74
1445 - 1500	28 108	50 159	0	78
Hourly Total 1500 - 1515	23	32	0	267 55
1515 - 1530 1530 - 1545	34 37	39 39	0	73 76
1545 - 1600	31	39	0	70
Hourly Total 1600 - 1615	125	149 42	0	274
1615 - 1630 1630 - 1645	34 25	35 29	0	69
1645 - 1700	34	33	0	67
Hourly Total 1700 - 1715	123	139 37	0	263 72
1715 - 1730	24	31	0	55
1730 - 1745 1745 - 1800	25 26	36 36	0	61
Hourly Total 1800 - 1815	110	140	0	250
1815 - 1830	27	41 31	0	68 52
1830 - 1845 1845 - 1900	18	31	0	49
Hourly Total	93	132	0	22
1900 - 1915 1915 - 1930	19 30	39 29	0	58
1930 - 1945	20	27	0	47
1945 - 2000 Hourly Total	22 91	25 120	0	47
2000 - 2015	30	33	0	63
2015 - 2030 2030 - 2045	13 12	33 28	0	48
2045 - 2100 Hourly Total	17 72	36 130	0	53 200
2100 - 2115	10	21	0	31
2115 - 2130 2130 - 2145	12 10	24 11	0	36
2145 - 2200	11	12	0	23
Hourly Total 2200 - 2215	43	68 23	0	34
2215 - 2230	4	19 12	0	23
2230 - 2245	7			
2245 - 2300	6	6	0	12
2245 - 2300 Hourly Total 2300 - 2315	6 28 10	60 13	0	88
2245 - 2300 Hourty Total 2300 - 2315 2315 - 2330	6 28 10 8	60 13 7	0 0 0	88 23 15
2245 - 2300 Hourly Total 2300 - 2315 2315 - 2330 2330 - 2345 2345 - 0000	6 28 10 8 3 1	60 13 7 4 4	0 0 0 0	88 23 15 7 5
2245 - 2300 Hourly Total 2300 - 2315 2315 - 2330 2330 - 2345 2345 - 0000 Hourly Total	6 28 10 8 3 1 22	60 13 7 4 4 28	0 0 0 0 0 0	88 23 15 7 5 50
2245 - 2300 Hourly Total 2300 - 2315 2315 - 2330 2330 - 2345 2345 - 0000	6 28 10 8 3 1 22	60 13 7 4 4	0 0 0 0 0 0	88 23 15 7 5 50
245-200 Houty Total 200-215 215-2330 235-2345 245-000 Houty Total Grand Total	6 28 10 8 3 1 22 1626	60 13 7 4 4 28 1866		888 23 15 7 5 50 349
2255-2200 Hoart Total 2200-2215 2215-2200 2233-2345 2245-2000 Hoarty Total Grand Total App Percentage ht Percentage	6 28 10 8 3 1 22	60 13 7 4 4 28 1866		88 23 15 7 5 50 349 100
2245 - 2300 Houry Teal 2300 - 2315 2315 - 2330 2330 - 2345 2345 - 5000 Houry Teal Moury Teal App Protectop Int Proceedings He Proceedings	6 28 10 8 3 1 22 1626 46.56 46.56 46.56 26 1234	60 13 7 4 28 1866 53.44 53.44 23 1437		88 23 15 7 5 50 349 100
245 - 220 Heart Teal 200 - 2315 2315 - 2316 2315 - 2316 2325 - 330 Heart Teal Age Persentage Motorsystes Persentage Motorsystes Passenger care 4 fan anglu unt	6 28 10 8 3 1 22 22 1626 46.56 46.56 26 1234 362 0 0	60 13 7 4 28 1966 53.44 53.44 53.44 23 1437 402 0	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	88 23 15 7 5 50 349 100
2245 - 2200 Houry Teal 2200 - 2315 2305 - 2315 2305 - 2345 2305 - 2345 2305 - 2345 2305 - 2000 Houry Teal Grand Teal App Percentage Hotoropids Percentage Motoropids Percentage Motoropids Percentage Motoropids Percentage Motoropids Percentage Motoropids Percentage Percentage Notice Percentage Percentage Notice Percentage Percentage Notice Percentage Percentage Notice Percentage Perce	6 28 10 8 3 1 1 22 46.56 46.56 46.56 26 1234 362 0 4	60 13 7 4 28 1866 53,44 53,44 53,44 23 1437 402 0 4	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	888 233 155 7 5 50 500 3499 100. 100. 100. 100. 100. 8
2245 - 2200 Housy Teal 2200 - 2215 2210 - 2215 2210 - 2215 2215 - 2216 2215 - 2216 2216 - 2000 Housy Teal App Percentage Horsentage Horsentage Horsentage Motorspots Passenger cm 4 per entry Res emple unit Base of the second	6 28 10 8 3 1 22 1626 46.56 46.56 26 1234 362 0 4 0 0 0	60 13 7 4 28 1966 53.44 53.44 53.44 23 1437 402 0 4 0 0 0 0	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	883 233 155 7 7 5 50 50 100. 100. 100. 100. 100. 100. 1
224 - 220 Houry Teal 200 - 2315 210 - 2315 213 - 2314 214 - 2314 214 - 2314 214 - 2314 214 - 2314 214 - 2314 Houry Teal Houry Teal Molecyches Molecyches Passingte cit Bases 2 and, 6 vs. single unt a des single unt Bases 2 and, 6 vs. single unt a des single unt Bases 2 and, 6 vs. single unt a des single unt Bases 2 and, 6 vs. single unt a des si	6 28 10 8 3 1 22 1626 46.56 46.56 46.56 1234 362 0 4 0	60 13 7 4 28 1866 53.44 53.44 53.44 23 1437 402 0 4 0 4 0	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	888 233 155 500 3499 2677 60 0 8 8 0 0 0 0 0 0 0 0 0 0 0
224 - 220 Houry Teal 200 - 2315 210 - 2315 213 - 2314 214 - 2314 214 - 2314 214 - 2314 214 - 2314 214 - 2314 Houry Teal Houry Teal Molecyches Molecyches Passingte cit Bases 2 and, 6 vs. single unt a des single unt Bases 2 and, 6 vs. single unt a des single unt Bases 2 and, 6 vs. single unt a des single unt Bases 2 and, 6 vs. single unt a des si	6 28 10 8 3 1 22 22 46.56 46.56 46.56 1234 362 0 4 0 0 0 0 0 0 0 0 0	60 13 7 4 4 28 1866 53,44 53,44 53,44 23 1437 402 0 402 0 0 0 0 0 0 0 0 0	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	883 233 155 7 7 5 50 50 100. 100. 100. 100. 100. 100. 1
2245 - 2200 Housy Teal 2200 - 2215 2210 - 2215 2210 - 2215 2215 - 2216 2215 - 2216 2215 - 2216 2215 - 2216 2215 - 2216 2245 - 0200 Housy Teal Cannot Teal App Percentage Horsentage Hor	6 28 3 1 22 22 46.56 46.56 46.56 28 1234 0 4 4.56 0 0 0 0 0 0 0 0 0 0 0	60 13 7 4 4 28 1866 53.44 53.44 53.44 53.44 23 1437 402 0 4 0 0 0 0 0 0 0	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	888 23 15 7 7 5 50 349 100. 349 267 76- 0 8 8 0 0 0 0 0 0 0
2245 - 2200 Heady Teal 2200 - 2755 - 2200 - 2755 - Heady Teal - Grave Teal - - 	6 28 3 1 1626 46.56 46.56 1234 46.56 1234 4 0 0 0 0 0 0 0 0 0 0 0	60 13 7 4 4 4 28 1866 53.44 53.44 53.44 53.44 53.44 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	883 233 15 7 7 50 50 349 267 7 6 7 6 7 6 7 6 7 7 6 0 0 8 8 0 0 0 0 0 0 0 0 0 0 0 0 0 0
2245 - 2200 Houry Teal 2015 - 2315 2315 - 2315 2315 - 2325 2325 - 2325 2325 - 2325 2326 - 2020 Houry Teal Grand Teal Grand Teal Grand Teal Motorspote Passessipt cont 4 See, engle unit 4 Gran engle unit 4 Grand See units 5 Or tes als, ungle trait 6 or nors als, ungle trait 7 or nors als, ungle trait 8 ord traits 6 or nors als, ungle trait 7 or nors als, ungle traits 8 ord traits 6 or nors als, ungle traits 7 or nors als, ungle traits 8 ord tes als (not have 1 or nors als, und traits 8 ord tes als (not have 1 ord tes als (not have) Motorspote (%)	6 28 3 1 1626 46.56 46.56 26 1234 362 0 1234 4 0 0 0 0 0 0 0 1 1 1 1 1 1 1 1 1 1 1 1 1	60 13 7 4 4 28 1866 53.44 23 1437 402 0 4 0 0 0 0 0 0 0 0 1 23 1437 4 23 1437 4 23 1437 4 23 1437 4 23 1437 4 153.44 155	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	883 233 15 7 7 50 50 349 267 7 6 7 6 7 6 7 6 7 7 6 0 0 8 8 0 0 0 0 0 0 0 0 0 0 0 0 0 0
2245 - 2200 Houry Teal 2015 - 2315 2315 - 2315 2315 - 2325 2325 - 2325 2325 - 2325 2326 - 2020 Houry Teal Grand Teal Grand Teal Grand Teal Motorspote Passessipt cont 4 See, engle unit 4 Gran engle unit 4 Grand See units 5 Or tes als, ungle trait 6 or nors als, ungle trait 7 or nors als, ungle trait 8 ord traits 6 or nors als, ungle trait 7 or nors als, ungle traits 8 ord traits 6 or nors als, ungle traits 7 or nors als, ungle traits 8 ord tes als (not have 1 or nors als, und traits 8 ord tes als (not have 1 ord tes als (not have) Motorspote (%)	6 28 31 10 10 8 3 3 1 1 22 46.56 5 28 1234 4 5 6 5 28 1234 4 0 0 0 0 0 0 0 0 160 0 1 28 1234 4 55 1234 1234 1234 1234 1234 1234 1234 1234	60 13 7 4 28 1866 53.44 23 1437 402 0 40 0 0 0 0 0 0 0 0 0 123 77.01 4	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	883 233 15 5 5 5 5 5 0 100.1 7 6 4 9 267 76 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
224 - 220 Houry Teal 2013 - 2313 2313 - 2324 2315 - 2325 2315 - 2325 2315 - 2325 2315 - 2325 2315 - 2325 2315 - 2325 2315 - 2325 Result Teal General Teal General Teal Molecogetes Presentage Molecogetes Presentage 4 or form a call, single unit 2 article scripts unit 2 articl	6 6 28 10 10 8 3 1 1 22 46.56 46.56 26 1234 4 0 0 0 0 0 0 0 0 160 160	60 13 7 4 28 1966 53.44 53.44 53.44 53.44 53.44 60 1437 452 0 0 0 0 0 0 0 0 0 0 0 0 0 123 77.01	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	883 233 155 500 349 267 76- 0 0 8 8 8 0 0 0 0 0 0 0 0 0 0 0 0 0 0
2245 - 2200 Weay'Teal 2200 - 2310 2200 - 2310 2200 - 2310 2200 - 2345 2345 - 2000 Weay'Teal 2345 - 2000 Weay'Teal Committee App Proceetings In Proceedings I	6 28 10 10 8 3 1 122 26 1626 46.56 46.56 46.56 26 1234 4 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	60 13 7 4 28 7 7 4 28 1866 53.44 53.44 53.44 53.44 53.44 53.44 0 0 <	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	88 23 16 7 5 50 349 267 764 0 0 0 0 0 0 0 0 0 0 0 0 0
2245 - 2200 Houry Teal 2000 - 2215 2010 - 2215 Houry Teal Hours - 2215 - 2	6 28 10 8 3 1 122 22 28 48.56 48.56 48.56 28 28 28 28 28 0 0 0 0 0 0 0 0 0 0 0 0	60 13 7 4 28 1866 1886 53.44 53.44 53.44 53.44 53.44 0 0 4 0 0 0 <td< td=""><td>0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0</td><td>88 23 15 5 50 349 100.3 49 267 764 0 0 8 0 0 0 0 0 0 0 0 0 0 0 0 0</td></td<>	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	88 23 15 5 50 349 100.3 49 267 764 0 0 8 0 0 0 0 0 0 0 0 0 0 0 0 0
206 - 200 Houry Teal 201 - 2	6 6 28 10 8 10 8 10 8 1 1 1 1 1 1 1 1 1 1 1 1	60 13 7 4 4 28 1966 53.44 53.44 53.44 23 1437 442 0 0 4 0 0 0 <t< td=""><td>0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0</td><td>88 23 315 77 5 50 349 267 76 4 9 267 76 4 9 267 76 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0</td></t<>	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	88 23 315 77 5 50 349 267 76 4 9 267 76 4 9 267 76 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
206 - 200 Heart Feel 200 - 2013 2013 - 2013 2013 - 2013 2013 - 2013 2013 - 2013 2014 - 2013 Reart Feel Motorycka	6 2 3 3 10 8 3 1 1 1 6 5 3 1 1 1 1 6 6 5 1 1 6 1 6 5 1 1 6 1 6 1 1 6 1 6	60 13 7 4 4 4 28 1866 53.44 53.44 13 1437 402 0 402 0 0	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	88 23 15 7 5 5 50 100.00
204 - 200 Houry Teal 200 - 275 2 201 - 275 2 202 - 275 2 203 - 275 2 203 - 275 2 204 - 5000 Houry Teal Grant Teal App Percentege Horonopy Horono	6 6 728 728 728 728 728 728 728 728 728 728	60 13 7 4 28 1866 53.44 23 14.37 23 14.37 0	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	88 233 15 77 5 50 349 267 764 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0

Grand Total (All Sessions)

	Northbound				
	-		S Cox Creek Pkwy (South)		
	Thru	Thru		Peds	Арр
TIME	1.1	1.2		1a	Total
Grand Total	1626	1866		0	3492
			_		
App Percentage	46.56	53.44		0.00	
Int Percentage	46.56	53.44		0.00	100.00
Motorcycles	26	23	1		49
Passenger cars	1234	1437		-	2671
4 tire, single unit	362	402		-	764
Buses	0	402		-	0
2 axle, 6 tire, single unit	4	4		-	8
3 axle, single unit	4	4			0
4 or more axle, single unit	0	0		-	0
4 or less axle, single trailer	0	0			0
5-axle tractor semitrailer	0	0		-	0
6 or more axle, single trailer	0	0		-	0
5 or less axle, multi trailer	0	0		-	0
6 axle, multi-trailer	0	0			0
7 or more axle, multi-trailer	0	0			0
For more date, main trailer	Ů	Ŭ	J		Ŭ
Motorcycles (%)	1.60	1.23		-	1.40
Passenger cars (%)	75.89	77.01		-	76.49
4 tire, single unit (%)	22.26	21.54		-	21.88
Buses (%)	0.00	0.00		-	0.00
2 axle, 6 tire, single unit (%)	0.25	0.21		-	0.23
3 axle, single unit (%)	0.00	0.00		-	0.00
4 or more axle, single unit (%)	0.00	0.00		-	0.00
4 or less axle, single trailer (%)	0.00	0.00		-	0.00
5-axle tractor semitrailer (%)	0.00	0.00		-	0.00
6 or more axle, single trailer (%)	0.00	0.00		-	0.00
5 or less axle, multi trailer (%)	0.00	0.00]	-	0.00
6 axle, multi-trailer (%)	0.00	0.00]	-	0.00
7 or more axle, multi-trailer (%)	0.00	0.00		-	0.00

9

Peak Hour Window


0000 - 2400 (Weekday 24h Session)

1515 - 1615 (Intersection Peak Hour)

	r		Northbound		
			S Cox Creek Pkwy (South)		
	Thru	Thru	Contraction of the second s	Peds	Арр
TIME	1.1	1.2		1a	Total
1515 - 1530	34	39		0	73
1530 - 1545	37	39		0	76
1545 - 1600	31	39		0	70
1600 - 1615	30	42		0	72
Hourly Total	132	159		0	291
Grand Total	132	159		0	291
			i i		
App Percentage	45.36	54.64		0.00	
Int Percentage	45.36	54.64		0.00	100.00
Motorcycles	7	0	1		7
Passenger cars	98	121		-	219
4 tire, single unit	26	38		-	64
Buses	0	0		-	04
2 axle, 6 tire, single unit	1	0			1
3 axle, single unit	0	0		-	0
4 or more axle, single unit	0	0			0
4 or less axle, single trailer	0	0		-	0
5-axle tractor semitrailer	0	0		-	0
6 or more axle, single trailer	0	0		-	0
5 or less axle, multi trailer	0	0		-	0
6 axle, multi-trailer	0	0		-	0
7 or more axle, multi-trailer	0	0		-	0
Motorcycles (%)	5.30	0.00		-	2.41
Passenger cars (%)	74.24	76.10		-	75.26
4 tire, single unit (%)	19.70	23.90		-	21.99
Buses (%)	0.00	0.00		-	0.00
2 axle, 6 tire, single unit (%)	0.76	0.00		-	0.34
3 axle, single unit (%)	0.00	0.00		-	0.00
4 or more axle, single unit (%)	0.00	0.00		-	0.00
4 or less axle, single trailer (%)	0.00	0.00		-	0.00
5-axle tractor semitrailer (%)	0.00	0.00		-	0.00
6 or more axle, single trailer (%)	0.00	0.00		-	0.00
5 or less axle, multi trailer (%) 6 axle, multi-trailer (%)	0.00	0.00		-	0.00
	0.00			-	
7 or more axle, multi-trailer (%)	0.00	0.00	l	-	0.00
PHF	0.892	0.946		-	0.957
110	0.002	0.040			0.001







0.957

Site 1 of 1 S Cox Creek Pkwy (South)

Lat/Long 34.806695°, -87.627815°


Date Saturday 29 July 2017

Weather Cloudy

Cioudy Temp: 30°C

Peak Hour Data (Interactive Diagram)





Peak Hour Window


0600 - 0900 (Weekday AM Peak)

0745 - 0845 (Intersection Peak Hour)

			Northbound		
			S Cox Creek Pkwy (South)		
	Thru	Thru	5 GOX GIEEK PKWY (SOUTH)	Peds	App
TIME	1.1	1.2		1a	Total
0745 - 0800	25	13		0	38
0800 - 0815	17	10		0	34
0815 - 0830	14	11		0	25
0830 - 0845	21	20		0	41
Hourly Total	77	61		0	138
Houry rotar		0.			
Grand Total	77	61		0	138
		•			
App Percentage	55.80	44.20		0.00	
Int Percentage	55.80	44.20		0.00	100.00
<u> </u>				-	
Motorcycles	0	0		-	0
Passenger cars	58	39		-	97
4 tire, single unit	19	22		-	41
Buses	0	0		-	0
2 axle, 6 tire, single unit	0	0		-	0
3 axle, single unit	0	0		-	0
4 or more axle, single unit	0	0		-	0
4 or less axle, single trailer	0	0		-	0
5-axle tractor semitrailer	0	0		-	0
6 or more axle, single trailer	0	0		-	0
5 or less axle, multi trailer	0	0		-	0
6 axle, multi-trailer	0	0		-	0
7 or more axle, multi-trailer	0	0		-	0
			1	r	
Motorcycles (%)	0.00	0.00		-	0.00
Passenger cars (%)	75.32	63.93		-	70.29
4 tire, single unit (%)	24.68	36.07		-	29.71
Buses (%)	0.00	0.00		-	0.00
2 axle, 6 tire, single unit (%)	0.00	0.00		-	0.00
3 axle, single unit (%)	0.00	0.00		-	0.00
4 or more axle, single unit (%)	0.00	0.00		-	0.00
4 or less axle, single trailer (%)	0.00	0.00		-	0.00
5-axle tractor semitrailer (%)	0.00	0.00		-	0.00
6 or more axle, single trailer (%)	0.00	0.00		-	0.00
5 or less axle, multi trailer (%)	0.00	0.00		-	0.00
6 axle, multi-trailer (%)	0.00	0.00		-	0.00
7 or more axle, multi-trailer (%)	0.00	0.00		-	0.00
PHF	0.770	0.700	1		0.0/1
PHF	0.770	0.763		-	0.841







0.841

Site 1 of 1 S Cox Creek Pkwy (South)

Lat/Long 34.806695°, -87.627815°


Date Saturday 29 July 2017

Weather Cloudy

Cioudy Temp: 30°C

Peak Hour Data (Interactive Diagram)





Peak Hour Window


1100 - 1300 (Weekday Inter Peak)

1100 - 1200 (Intersection Peak Hour)

			No alla la consul		
			Northbound		
	Thru	Thru	S Cox Creek Pkwy (South)	Peds	Арр
TIME	1.1	1.2		1a	Total
1100 - 1115	35	38		0	73
1115 - 1130	34	24		0	58
1130 - 1145	39	31		0	70
1145 - 1200	34	34		0	68
Hourly Total	142	127		0	269
Thousy rotai	142	121		v	205
Grand Total	142	127		0	269
App Percentage	52.79	47.21		0.00	
Int Percentage	52.79	47.21		0.00	100.00
Motorcycles	2	5		-	7
Passenger cars	114	93		-	207
4 tire, single unit	24	29		-	53
Buses	0	0		-	0
2 axle, 6 tire, single unit	2	0		-	2
3 axle, single unit	0	0		-	0
4 or more axle, single unit	0	0		-	0
4 or less axle, single trailer	0	0		-	0
5-axle tractor semitrailer	0	0		-	0
6 or more axle, single trailer	0	0		-	0
5 or less axle, multi trailer	0	0		-	0
6 axle, multi-trailer	0	0		-	0
7 or more axle, multi-trailer	0	0		-	0
Motorcycles (%)	1.41	3.94		-	2.60
Passenger cars (%)	80.28	73.23			76.95
4 tire, single unit (%)	16.90	22.83		-	19.70
Buses (%)	0.00	0.00		-	0.00
2 axle, 6 tire, single unit (%)	1.41	0.00		-	0.74
3 axle, single unit (%)	0.00	0.00		-	0.00
4 or more axle, single unit (%)	0.00	0.00		-	0.00
4 or less axle, single trailer (%)	0.00	0.00		-	0.00
5-axle tractor semitrailer (%)	0.00	0.00		-	0.00
6 or more axle, single trailer (%)	0.00	0.00		-	0.00
5 or less axle, multi trailer (%)	0.00	0.00		-	0.00
6 axle, multi-trailer (%)	0.00	0.00		-	0.00
7 or more axle, multi-trailer (%)	0.00	0.00		-	0.00
	1				
PHF	0.910	0.836		-	0.921







0.921

Site 1 of 1 S Cox Creek Pkwy (South)

Lat/Long 34.806695°, -87.627815°


Date Saturday 29 July 2017

Weather Cloudy

Cioudy Temp: 30°C

Peak Hour Data (Interactive Diagram)






Peak Hour Window


1500 - 1800 (Weekday PM Peak)

1515 - 1615 (Intersection Peak Hour)

			Northbound		
			S Cox Creek Pkwy (South)		
	Thru	Thru	S OUX CIEEK PKWy (SOUTH)	Peds	Арр
TIME	1.1	1.2		1a	Total
1515 - 1530	34	39		0	73
1530 - 1545	37	39		0	76
1545 - 1600	31	39		0	70
1600 - 1615	30	42		0	72
Hourly Total	132	159		0	291
Grand Total	132	159		0	291
App Percentage	45.36	54.64		0.00	
Int Percentage	45.36	54.64		0.00	100.00
				-	
Motorcycles	7	0		-	7
Passenger cars	98	121		-	219
4 tire, single unit	26	38		-	64
Buses	0	0		-	0
2 axle, 6 tire, single unit	1	0		-	1
3 axle, single unit	0	0		-	0
4 or more axle, single unit	0	0		-	0
4 or less axle, single trailer	0	0		-	0
5-axle tractor semitrailer	0	0		-	0
6 or more axle, single trailer	0	0		-	0
5 or less axle, multi trailer	0	0		-	0
6 axle, multi-trailer	0	0		-	0
7 or more axle, multi-trailer	U	U		-	U
Motorcycles (%)	5.30	0.00		-	2.41
Passenger cars (%)	74.24	76.10		-	75.26
4 tire, single unit (%)	19.70	23.90		-	21.99
Buses (%)	0.00	0.00		-	0.00
2 axle, 6 tire, single unit (%)	0.76	0.00		-	0.34
3 axle, single unit (%)	0.00	0.00		-	0.00
4 or more axle, single unit (%)	0.00	0.00		-	0.00
4 or less axle, single trailer (%)	0.00	0.00		-	0.00
5-axle tractor semitrailer (%)	0.00	0.00		-	0.00
6 or more axle, single trailer (%)	0.00	0.00		-	0.00
5 or less axle, multi trailer (%)	0.00	0.00		-	0.00
6 axle, multi-trailer (%)	0.00	0.00		-	0.00
7 or more axle, multi-trailer (%)	0.00	0.00		-	0.00
		0.016	1		0.05
PHF	0.892	0.946		-	0.957







0.957

Site 1 of 1 S Cox Creek Pkwy (South)

Lat/Long 34.806695°, -87.627815°


Date Saturday 29 July 2017


Weather Cloudy

Cioudy Temp: 30°C

Peak Hour Data (Interactive Diagram)







Appendix C GPR Report

GENERAL OBSERVATION REPORT

 Report Number:
 E1171088.0001

 Service Date:
 08/10/17

 Report Date:
 08/11/17

Client

Volkert, Inc.

Suite A-1

Attn: Adam Davidson 330 Mallory Station Road

Franklin, TN 37067



Project

Bridge Over TVA Wilson Dam Bridge over TVA Wilson Dam Florence, AL

Project Number: E1171088

Terracon representative Scott Looney visited the project site on 7/31/17 as scheduled by Mr. Justin Eckel with Volkert, Inc. The purpose of the visit was to perform ground-penetrating radar (GPR) evaluations of the concrete pavement.

GSSI SIR-3000 Structure-Scan GPR equipment with a 1.6 GHz antenna for concrete scanning was utilized to perform the evaluations. GPR evaluations were made using 2-D scanning techniques. The GPR scan area surfaces consisted of bare concrete.

Our representative performed GPR evaluations to locate reinforcing steel, utilities, and voids within the upper layer of concrete pavement over the dam at six locations selected by Mr. Eckel with Volkert for scanning and concrete core samples. The GPR scanning was performed on the top side of the pavement within approximately 3'-0" of the proposed location for each concrete core sample.

TVA personnel with similar GPR equipment performed GPR evaluations at the same locations and with the same results. The upper layer of concrete pavement typically appeared to be approximately 8" to 10" in thickness over the original dam concrete construction. At several locations there appeared to be a potential void between the original dam concrete construction and the upper layer of concrete pavement. For the most part, the concrete at the test locations appeared to be free of reinforcing steel or utilities as few targets were detected with the GPR equipment. The location of the few targets detected with GPR in the test areas was marked directly on the face of the concrete with blue wax crayon and/or white spray paint by TVA personnel. The markings represent the approximate longitudinal center line of each component detected. Terracon and the TVA personnel performing GPR evaluations recommended drilling or coring of the concrete be performed a minimum of 2" away from the lines marking the location of the targets detected with GPR.

An image of the GPR data from each location scanned is attached for reference. It must be noted that the depth of the potential voids and targets in the attached images are approximate as ground truth was not utilized in the field to adjust the GPR settings.

The intent of our scope is to determine the location of the steel reinforcement, utilities, and voids in the concrete components. Thereafter, others than Terracon will review our findings to determine necessary repairs and future use of the structure.

Ground Penetrating Radar utilizes electromagnetic waves to detect changes in the subsurface of the area being scanned or evaluated. Changes in the signal generally indicate material property changes such as, but not limited to electromagnetic conductivity and dielectric constant, which in some cases can be qualitatively linked to other material properties such as density, moisture, or material type. While this can be effective in identifying the presence and approximate location of items such as embedded reinforcing steel and post tensioned tendons, utilities and voids in concrete and masonry structures, among other things, it must be understood that, as with any nondestructive evaluation method, these processes rely on instrument signals to indicate physical conditions in the field. Signal information can be affected by on-site conditions beyond the control of the operator such as but not limited to, concrete types, concrete moisture, and/or reinforcing steel or other

Services:

Terracon Rep.: Scott Looney Reported To: Contractor: Report Distribution: (1) Volkert, Inc., Adam Davidson

> **Reviewed By:** rvw1: drs

Kiondra

Project Manager

The tests were performed in general accordance with applicable ASTM, AASHTO, or DOT test methods. This report is exclusively for the use of the client indicated above and shall not be reproduced except in full without the written consent of our company. Test results transmitted herein are only applicable to the actual samples tested at the location(s) referenced and are not necessarily indicative of the properties of other apparently similar or identical materials. CT0001, 5-5-10, Rev.7 Page 1 of 2

GENERAL OBSERVATION REPORT

 Report Number:
 E1171088.0001

 Service Date:
 08/10/17

 Report Date:
 08/11/17

Client

Volkert, Inc.

Suite A-1

Attn: Adam Davidson 330 Mallory Station Road

Franklin, TN 37067



Project

Bridge Over TVA Wilson Dam Bridge over TVA Wilson Dam Florence, AL

Project Number: E1171088

detected component's layout, orientation and spacing, as well as the presence of unknown and unexpected conditions. Utilizing conventional observation, sampling and testing ("truthing") of select areas is highly recommended to confirm the results from the GPR evaluation.

As with other nondestructive evaluation methods, the GPR results may provide a level of confidence but should not be considered precise or absolute. Further, it should be recognized that the results of GPR are one-dimensional and operator's cannot guarantee the accuracy of the information and may not be able to discern or predict with specificity what has given off the signals being recorded. As such, unexpected items and materials may be present and remain undetected. Due to the previously identified limitations of the GPR method, there is an inherent level of risk that must be accepted by the end user of the information provided. Terracon shall not be held responsible for any associated damages, losses or injuries resulting from use of the information provided. Terracon has identified the approximate locations of the detected targets, but Terracon will not be responsible for clearing areas for coring, sawing or other penetrations.

Services:


Terracon Rep.: Scott Looney Reported To: Contractor: Report Distribution: (1) Volkert, Inc., Adam Davidson

> **Reviewed By:** rvw1: drs


Kiondra

Project Manager


The tests were performed in general accordance with applicable ASTM, AASHTO, or DOT test methods. This report is exclusively for the use of the client indicated above and shall not be reproduced except in full without the written consent of our company. Test results transmitted herein are only applicable to the actual samples tested at the location(s) referenced and are not necessarily indicative of the properties of other apparently similar or identical materials. CT0001, 5-5-10, Rev.7 Page 2 of 2




Bridge Over TVA Wilson Dam	Core location: #1 Report Number: E1171088.0001	lerracon
Bridge over TVA Wilson Dam	Technician: Scott Looney	110 12th St N
Florence, AL	Date: 08/10/17	Birmingham, AL 35203-1537
	Scale: Not to Scale	205-942-1289



Bridge Over TVA Wilson Dam	Core location: #2 Report Number: E1171088.0001	lerracon
Bridge over TVA Wilson Dam	Technician: Scott Looney	110 12th St N
Florence, AL	Date: 08/10/17	Birmingham, AL 35203-1537
	Scale: Not to Scale	205-942-1289




Bridge Over TVA Wilson Dam	Core location: #3 Report Number: E1171088.0001	lerracon
Bridge over TVA Wilson Dam	Technician: Scott Looney	110 12th St N
Florence, AL	Date: 08/10/17	Birmingham, AL 35203-1537
	Scale: Not to Scale	205-942-1289




Bridge Over TVA Wilson Dam	Core location: #4 Report Number: E1171088.0001	lerracon
Bridge over TVA Wilson Dam	Technician: Scott Looney	110 12th St N
Florence, AL	Date: 08/10/17	Birmingham, AL 35203-1537
	Scale: Not to Scale	205-942-1289


BD000L, 08-24-13, Rev.1



Bridge Over TVA Wilson Dam	Core location: #5 Report Number: E1171088.0001	Terraron
Bridge over TVA Wilson Dam	Technician: Scott Looney	110 12th St N
Florence, AL	Date: 08/10/17	Birmingham, AL 35203-1537
	Scale: Not to Scale	205-942-1289



Bridge Over TVA Wilson Dam	Core location: #6 Report Number: E1171088.0001	lerracon
Bridge over TVA Wilson Dam	Technician: Scott Looney	110 12th St N
Florence, AL	Date: 08/10/17	Birmingham, AL 35203-1537
	Scale: Not to Scale	205-942-1289



Appendix D Concrete Testing Report

Results of Petrographic Examinations and Laboratory Testing of Concrete Cores

TVA Wilson Dam Florence, Alabama

Terracon Project No. E1171088 Lab Nos. 6650-6655 September 15, 2017

Prepared for:

Volkert, Inc. Franklin, Tennessee

Prepared by:

Terracon Consultants, Inc. Cincinnati, Ohio



RESULTS OF PETROGRAPHIC EXAMINATIONS AND LABORATORY TESTING OF CONCRETE CORES TVA Wilson Dam Florence, Alabama Terracon Project No. E1171088 September 12, 2017

1.0 INTRODUCTION & BACKGROUND

A total of 10 nominal 4-inch diameter concrete cores were obtained by Terracon, Birmingham, Alabama personnel and were received at the Terracon, Cincinnati, Ohio materials laboratory on August 14, 2017. The cores were provided to perform petrographic examinations and laboratory testing to determine the general condition of the concrete. Core identifications and assigned laboratory numbers are presented in Table I, below.

TABLE I Core Identification				
CORE IDENTIFICATION	STATION NUMBER	CORE LOCATION	LAB NUMBER	
#1	64+25.76	BRIDGE DECK	6646	
#2	68+37.76	BRIDGE DECK	6647	
#5	79+52.76	BRIDGE DECK	6648	
#6	80+22.76	BRIDGE DECK	6649	
#3	72+70.76	BRIDGE DECK	6650	
#4	77+21.76	BRIDGE DECK	6651	
#1	64+25.76	ARCH	6652	
#3	72+70.76	ARCH	6653	
#4	77+21.76	ARCH	6654	
#5	79+52.76	ARCH	6655	

2.0 PETROGRAPHIC METHODOLOGY

Petrographic examinations were performed on 6 of the cores selected by the client in accordance with ASTM Method C 856 and concrete proportions and hardened air contents were determined in accordance with ASTM Method C 457, Procedure B. The cores were measured, visually examined and photographed as received. Cores were then sawn lengthwise to obtain cross sections of each core for visual and stereomicroscopic examinations. Twenty-five micron thick thin-sections of each core were prepared and examined by polarized light microscopy.

Sawn sections were stained using proprietary Los Alamos stains to further detect the presence of ASR. Phenolphthalein stain was also applied to sawn surfaces of the cores. Phenolphthalein is a pH indicator which turns from colorless to magenta at about a pH of 9-10. When the stain remains colorless after application, the concrete is usually carbonated and maintains a pH below 9.



Photographs of the cores as received, after sawing and after stain application, as well as thinsection photomicrographs, are included in Appendix A. A summary of information obtained for each core is presented in Table II, below.

TABLE II Concrete Proportions & Hardened Air Content,% (ASTM C457, Procedure B)					
Core ID.	Lab No.	Total Aggregates	Total Cementitious Material	Total Air	
#3, Bridge Deck	6650	68.4	28.2	3.4 (1.7)	
#4, Bridge Deck	6651	70.5	24.5	5.0 (2.7)	
#1, Arch	6652	73.1	25.9	1.0 (1)	
#3, Arch	6653	65.3	33.8	0.9 (0.9)	
#4, Arch	6654	71.7	22.8	2.5 (2.5)	
#5, Arch	6655	71.3	28.4	0.3 (0.3)	

Note: Air contents in parentheses represent entrapped size air (>0.04 inches). ASTM C 457 does not distinguish between entrained and entrapped air. The distinction is typically made by the petrographer based on void size, shape and location within the matrix.

TABLE III Summary of General Physical Characteristics						
Core ID.	Lab No.	Coarse Aggregate	Fine Aggregate	Cementitious Materials	Carbonation Depth, Inches, based on Phenolphthalein stain	Los Alamos Staining
#3, Bridge Deck	6650	3/4" Crushed Limestone, Chert	Natural Sand	Portland Cement	Carbonated along fracture and slightly carbonated throughout	No ASR detected
#4, Bridge Deck	6651	1" Crushed Limestone, Chert	Natural Sand	Portland Cement	Carbonated in upper 1/4 inches	No ASR detected
#1, Arch	6652	1 1/2" Crushed Limestone, Chert	Natural Sand	Portland Cement	Carbonated less than 1/16 inches	No ASR detected
#3, Arch	6653	1⁄2" Crushed Limestone, Chert	Natural Sand	Portland Cement	Carbonated in upper 1/8 inches	No ASR detected
#4, Arch	6654	2" Crushed Limestone, Chert	Natural Sand	Portland Cement	Completely carbonated	No ASR detected
#5, Arch	6655	3/4" Crushed Limestone, Chert	Natural Sand	Portland Cement	Carbonated in upper 3/4 inches	No ASR detected

Results of Petrographic Examinations and Laboratory Testing of Concrete Cores Bridge Over TVA Wilson Dam Florence, Alabama Volkert, Inc. Terracon Project No. E1171088



TABLE IV Summary of Microscopy Characteristics				
Core ID.	Lab No.	Reactive Aggregates	Void fillings	Microfracturing
#3, Bridge Deck	6650	No	Ettringite (V,P), no apparent ASR gels	Throughout sample
#4, Bridge Deck	6651	No	Ettringite (V,F,P), no apparent ASR gels	Throughout sample
#1, Arch	6652	No	No apparent ettringite or ASR gels	Common upper 1"
#3, Arch	6653	No	Ettringite (V,F,P), no apparent ASR gels	Throughout sample
#4, Arch	6654	No	Ettringite (V,F,P), no apparent ASR gels	Throughout sample
#5, Arch	6655	No	Ettringite (V,P), no apparent ASR gels	Common upper 5mm

V=Voids, F=Fractures and P=Paste

3.0 SUMMARY OF GROSS CORE CHARACTERISTICS

The cores were each 3-5/8 inches in diameter, varied in length from 1-1/2 inches to 9-1/4 inches, and were broken off at their interior surfaces. The Core #3 and Core #4 from the bridge deck were moderately air entrained. The cores from the arches are not air entrained. The concrete was well consolidated, with few coalescing voids and no honeycombing. The cores contained no steel or wire mesh. The top surfaces of Core #3 and Core #4 from the bridge deck were sandy. In all arch cores the top surface consisted of bituminous and cementitious material.

The cores were generally intact, with the exception of Core #3 from the bridge deck, which was cored over a full-depth fracture and Core #3 from the arch, which had subparallel fractures associated with freeze-thaw damage. The fracture in Core #3 from the bridge was stained black and also exhibited filmy deposits of white calcium carbonate. The bottom surface of Core #3 and Core #5 from the arch exhibited calcium carbonate deposits around aggregates.

Aggregate materials were hard, dense and rounded to subangular. These materials consisted of ³/₄-inch to 2-inch maximum size crushed limestone and chert coarse aggregate, and natural sand fine aggregate. Cementitious materials in all samples consisted solely of Portland cement. These materials appeared to be well mixed and evenly distributed, with no aggregate segregation or preferred particle orientation.

The concrete appeared to be undergoing sulfate attack. The presence of ettringite was noted in 5 of the 6 samples (except for Core #1 from the arch) and its presence in both air voids and cement paste was associated with microfracturing. The presence of ASR gels was not identified either by Los Alamos staining or by visual or microscopic examinations.

Results of Petrographic Examinations and Laboratory Testing of Concrete Cores Bridge Over TVA Wilson Dam
Florence, Alabama Volkert, Inc.
Terracon Project No. E1171088



Carbonation of the matrix was identified by phenolphthalein stain in the exterior 1/16 inches to 3/4 inches of all the cores, except Core #3 from the bridge deck, which was slightly carbonated around the fracture, and Core #4 from the arch, which was completely carbonated.

Although microfracturing was observed to some extent in all cores, the majority of the microfracturing was confined to the exterior 1 to 2 inches of the sample.

7.0 THIN-SECTION EXAMINATION

Thin-sections from each core were examined for the occurrence of alkali-silica reactivity, other chemical reactions, microfracturing, degree of hydration of cementitious materials and the presence of matrix carbonation. Photomicrographs are presented in Appendix A. Based on the examinations, cementitious materials consisted solely of well-hydrated Portland cement. Microfracturing of the matrix was observed in each sample, although minor in amount. Generally, the observed charts consisted of microcrystalline quartz, with no chalcedonic chert, opal or agate.

Core #4 from the bridge deck, contained trace amounts of chalcedonic chert. Microfracturing associated with the chert was generally isolated and trivial in amount. The presence of ettringite was common in air voids and minor amounts occurred in the cement paste, with none observed in Core #1 from the arch. Ettringite was commonly associated with microfracturing in Core #3 and Core #4 from the arch and Core #4 from the bridge deck. Ettringite was rarely associated with microfracturing in the remaining cores. The was no apparent presence of silica gels in any of the samples.

8.0 LOS-ALAMOS STAIN TESTS

"Los Alamos" stains are commercially available, but proprietary, stains that are used to identify areas of occurrence of ASR. The stains consist of "yellow" stain and a "red" stain which is further applied only if the yellow stain indicates the presence of ASR. The yellow stain is first applied, then rinsed off. Areas of ASR are identified by bright yellow staining remaining after the rinsing. The cores submitted exhibited no apparent detection of ASR. This suggests that ASR is not occurring.

9.0 CHLORIDE ANALYSES

Both water-soluble (W/S) (ASTM C1218) and acid-soluble (total) (A/S) (ASTM C1152) chloride analyses were performed by the Terracon, Las Vegas, Nevada laboratory on powdered samples from each core. Results are summarized below in Table V and presented in Appendix B.

TABLE V Chloride Analyses					
CORE IDENTIFICATION	CORE LOCATION	LAB NUMBER	W/S CHLORIDE	A/S CHLORIDE	
#3	BRIDGE DECK	6650	0.002	0.008	
#4	BRIDGE DECK	6651	0.005	0.072	
#1	ARCH	6652	0.002	0.085	
#3	ARCH	6653	0.001	0.005	
#4	ARCH	6654	0.001	0.005	
#5	ARCH	6655	0.004	0.020	

Note: All results in % by weight of concrete

Based on these analyses, Core #4 from the bridge deck and Core#1 from the arch exhibit elevated acid-soluble chloride concentrations. Core #5 from the arch exhibited slightly elevated acid-soluble (total) chloride concentrations. Water-soluble chlorides, those typically responsible for chloride attack of reinforcing steel and concrete scaling, appear to be present in only minimal concentrations.

10.0 COMPRESSIVE STRENGTH

Compressive strength tests were performed on the remaining 4 cores not used for petrographic examinations, in accordance with ASTM C 42. Compressive strength results are summarized below in Table VI and presented in Appendix C.

TABLE VI Compressive Strength ASTM C42				
CORE	CORE	LAB	COMPRESSIVE	
IDENTIFICATION	LOCATION	NUMBER	STRENGTH, PS	
#1	BRIDGE DECK	6646	5030	
#2	BRIDGE DECK	6647	5280	
#5	BRIDGE DECK	6648	5610	
#6	BRIDGE DECK	6649	4830	

Results of Petrographic Examinations and Laboratory Testing of Concrete Cores Bridge Over TVA Wilson Dam
Florence, Alabama Volkert, Inc.
Terracon Project No. E1171088



11.0 FINDINGS/CONCLUSIONS

- The concrete represented by each of the cores consisted of a plain (Portland cement only) well-hydrated concrete. Coarse aggregates, while highly variable in size, consisted of a combination of crushed limestone and chert, and fine aggregates consisted of natural sand.
- The presence of alkali-silica reactive aggregates was not detected either by Los Alamos staining or visual or microscopic examinations.
- The bridge deck cores were slightly to moderately air entrained. The arch cores were not air entrained. No honeycombing was observed in the samples.
- None of the samples contained reinforcing steel or wire mesh.
- Core #3 from the bridge deck was cored over an apparently open fracture, as evidenced by discoloration and the presence of calcium carbonate deposits. Core #3 form the arch exhibited the presence of carbonated fractures normal to the core axis, indicative of likely freeze-thaw distress.
- Microfracturing of the matrices was observed in each of the cores. In half of the cores (Core #3 and Core #4 from the arch, and Core #3 from the bridge deck), these fractures appeared to be associated with the presence of expansive ettringite, which was also present in the matrices and air voids of the majority of the cores. This is suggestive of sulfate attack of the concrete.
- Chloride analyses indicated slightly elevated to elevated acid-soluble (total) chlorides in half of the samples, but water-soluble chlorides, those typically associated with corrosion of steel reinforcement or concrete scaling, were minimal, with several results just above detection limits.
- Compressive strength tests run on companion cores from the bridge deck indicated strengths of 4,830 psi to 5,610 psi.

Results of Petrographic Examinations and Laboratory Testing of Concrete Cores Bridge Over TVA Wilson Dam

Florence, Alabama Volkert, Inc.

Terracon Project No. E1171088



Terracon appreciates the opportunity to be of service to you on this project. Please contact the undersigned if you have any questions or need additional information.

Sincerely, Terracon Consultants, Inc.

Stewart Abrams Geologist (513) 612-9169

Terry E. Stransky, P.G. Senior Geologist / Manager Petrographic Services (513) 612-9081

Wil Beckwith, P.E. Senior Associate / Materials Engineering Manager (513) 612-9089

Attachments: Photographs & Photomicrographs Chloride Test Results Compressive Strength Test Results Results of Petrographic Examinations and Laboratory Testing of Concrete Cores Bridge Over TVA Wilson Dam Florence, Alabama Volkert, Inc. Terracon Project No. E1171088



APPENDIX A

Photographs & Photomicrographs

Responsive = Resourceful = Reliable

Results of Petrographic Examinations and Laboratory Testing of Concrete Cores Bridge Over TVA Wilson Dam
Florence, Alabama Volkert, Inc.
Terracon Project No. E1171088





Photo 1: Core #3 from bridge deck (Lab No. 6650), as received.



Photo 2: Top surface of Core #3 from bridge deck.

Results of Petrographic Examinations and Laboratory Testing of Concrete Cores Bridge Over TVA Wilson Dam
Florence, Alabama Volkert, Inc.
Terracon Project No. E1171088

Terracon




Photo 3: Fractured side of Core #3 from bridge deck.




Photo 4: Core #4 from bridge deck (Lab No. 6651), as received.



Photo 5: Top surface of Core #4 from bridge deck.




Photo 6: Core #1 from arch (Lab No. 6652), as received.




Photo 7: Top surface of Core #1 from arch.




Photo 8: Core #3 from arch (Lab No. 6653), as received. Note subparallel fracturing likely due to freeze-thaw distress.




Photo 9: Top surface of Core #3 from arch.




Photo 10: Interior surface of Core 3 from arch; showing possible carbonate deposits (white) around aggregate particles.

llerracon




Photo 11: Core #4 from arch (Lab No. 6654), as received.




Photo 12: Bottom surface of Core #4 from arch showing large aggregate and shell (white).



Photo 13: Top surface of Core #4 from arch



Photo 14: Core #5 from arch (Lab No. 6655), as received




Photo 15: Top surface of Core #5 from arch, as received



Photo 16: Bottom surface of Core #5 arch from arch showing possible calcium deposits (faint white)



Photo 17: Longitudinally sawn sections of Core #3 from bridge deck. No fractures are apparent.



Photo 18: Longitudinally sawn sections of Core #4 from bridge deck. No fractures are apparent.

llerracon




Photo 19: Longitudinally sawn sections of Core #1 from arch. No fractures are apparent, but "rinds" around coarse aggregate particles are evident.




Photo 20: Longitudinally sawn sections of Core #3 from arch showing subparallel fractures normal to the core axis, likely from freeze/thaw distress.




Photo 21: Longitudinally sawn sections of Core #4 from arch. No fractures are apparent. Note white arcuate shell fragment.




Photo 22: Longitudinally sawn sections of Core #5 from arch. No fractures are apparent.

Terracon



Photo 23: Los Alamos stains used.




Photo 24: Sawn surfaces of Core #3 from bridge deck (Lab No. 6650) (left) and Core #4 from bridge deck (Lab No. 6651) (right) after application and rinsing of Los Alamos stains. No ASR is apparent.




Photo 25: Sawn surfaces of Cores Core #1 from arch (Lab No. 6652) (left) and Core #3 from arch (Lab No. 6653) (right) after application and rinsing of Los Alamos stains. No ASR is apparent.






Photo 26: Sawn surfaces of Core #4 from arch (Lab No. 6654) (left) and Core #5 from arch (Lab No. 6655) (right) after application and rinsing of Los Alamos stains. No ASR is apparent.



Photo 27: Sawn surfaces of Core #3 from bridge deck (Lab No. 6650) (left) and Core #4 from bridge deck (Lab No. 6651) (right) after application of phenolphthalein stain. Areas not stained magenta are carbonated.




Photo 28: Sawn surfaces of Cores Core #1 from arch (Lab No. 6652) (left) and Core #3 from arch (Lab No. 6653) (right) after application of phenolphthalein stain. Areas not stained magenta are carbonated.

Terracon




Photo 29: Sawn surfaces of Core #4 from arch (Lab No. 6654) (left) and Core #5 from arch (Lab No. 6655) (right) after application of phenolphthalein stain. Areas not stained magenta are carbonated.




Photo 30: Thin-section photomicrograph of Core #3 from bridge deck (Lab No. 6650) showing ettringite needles in matrix and air voids (red arrows). Plane polarized light, magnification 200X.

Terracon




Photo 31: Thin-section photomicrograph of Core #3 from bridge deck (Lab No. 6650) showing ettringite needles in the paste of the concrete. Plane polarized light, magnification 200X.





Photo 32: Photomicrograph of Core #3 from bridge deck (Lab No. 6650) showing carbonated (left) and noncarbonated (right) matrix. Crossed polars, magnification 100X.



lerracon




Photo 33: Photomicrograph of Core #4 from bridge deck (Lab No. 6651) showing ettringite needles in paste (yellow arrow), microfracting (blue arrow) and air voids (red arrows). Plane polarized light, magnification 400X.




Photo 34: Photomicrograph of Core #4 from bridge deck (Lab No. 6651) showing ettringite needles in paste (red arrows) associated with microfracturing (blue arrow). Plane polarized light, magnification 600X.

Terracon




Photo 35: Photomicrograph of Core #4 from bridge deck (Lab No. 6651) showing carbonated (top) and non-carbonated (bottom) matrix. Crossed polars, magnification 100X.




Photo 36: Photomicrograph of Core #1 from arch (Lab No. 6652) showing carbonation of exterior surface and microfracturing parallel to the exterior surface. Plane polarized light, magnification 100X.




Photo 37: Photomicrograph of Core #1 from arch (Lab No. 6652) showing carbonated (top) and non-carbonated (bottom) matrix. Crossed polars, magnification 100X.




Photo 38: Photomicrograph of Core #3 from arch (Lab No. 6653) showing entrapped air void filled with ettringite (red arrow) and microfractures (blue arrow). Plane polarized light, magnification 200X.

Terracon




Photo 39: Photomicrograph of Core #3 from arch (Lab No. 6653) showing ettringite present in paste (red arrow) and associated microfracturing (blue arrows). Plane polarized light, magnification 200X.




Photo 40: Photomicrograph of Core #3 from arch (Lab No. 6653) showing carbonation isolated to microfractures. Crossed polars, magnification 100X.

Terracon




Photo 41: Photomicrograph of Core #4 from arch (Lab No. 6654) showing entrapped air void containing ettringite needles (red arrow). Plane polarized light, magnification 400X.




Photo 42: Photomicrograph of Core #4 from arch (Lab No. 6654) showing exterior surface microfractures (blue arrows) and ettringite in paste (red arrow). Plane polarized light, magnification 100X.




Photo 43: Photomicrograph of Core #4 from arch (Lab No. 6654) showing carbonated (top) and non-carbonated (bottom) matrix. Crossed polars, magnification 100X.




Photo 44: Photomicrograph of Core #5 from arch (Lab No. 6655) showing ettringite present in paste (red arrow), and associated microfracture. Plane polarized light, magnification 200X.




Photo 45: Photomicrograph of Core #5 from arch (Lab No. 6655) showing exterior surface carbonation and microfracture (blue arrow). Crossed Polars, magnification 100X.



APPENDIX B

Chloride Analyses

CHEMICAL LABORATORY TEST REPORT

 Project Number:
 E1171088

 Service Date:
 09/01/17

 Report Date:
 09/11/17

 Task:

Client

Volkert, Inc.

750 Pilot Road, Suite F Las Vegas, Nevada 89119 (702) 597-9393

Project

Bridge Over TVA Wilson Dam

Sample Submitted By: Terracon (N1)

Date Received: 9/1/2017

Lab No: 17-0900

Results of Chlorides in Concrete

Lab Number	6550	6551	6552	6553
Sample Location	Core 3 Br.	Core 4 Br.	Core 1 Ar.	Core 3 Ar.
Sample Depth (ft.)				
Acid-Soluble Chlorides in Concrete and Mortar, ASTM C 1152 (percent %)	0.008	0.072	0.085	0.005
Water-Soluble Chlorides in Concrete and Mortar, ASTM C 1218 (percent %)	0.002	0.005	0.002	0.001

Analyzed By:

Trisha Campo Chemist

The tests were performed in general accordance with applicable ASTM, AASHTO, or DOT test methods. This report is exclusively for the use of the client indicated above and shall not be reproduced except in full without the written consent of our company. Test results transmitted herein are only applicable to the actual samples tested at the location(s) referenced and are not necessarily indicative of the properties of other apparently similar or identical materials.

CHEMICAL LABORATORY TEST REPORT

 Project Number:
 E1171088

 Service Date:
 09/01/17

 Report Date:
 09/11/17

 Task:

Client

Volkert, Inc.

750 Pilot Road, Suite F Las Vegas, Nevada 89119 (702) 597-9393

Project Bridge Over TVA Wilson Dam

Sample Submitted By: Terracon (N1)

Date Received: 9/1/2017

Lab No: 17-0900

Lab Number	6554	6555
Sample Location	Core 4 Ar.	Core 5 Ar.
Sample Depth (ft.)		
Acid-Soluble Chlorides in Concrete and Mortar, ASTM C 1152 (percent %)	0.005	0.020
Water-Soluble Chlorides in Concrete and Mortar, ASTM C 1218 (percent %)	0.001	0.004

Results for Chlorides in Concrete

Analyzed By:

Trisha Campo Chemist

The tests were performed in general accordance with applicable ASTM, AASHTO, or DOT test methods. This report is exclusively for the use of the client indicated above and shall not be reproduced except in full without the written consent of our company. Test results transmitted herein are only applicable to the actual samples tested at the location(s) referenced and are not necessarily indicative of the properties of other apparently similar or identical materials.



APPENDIX C

Core Report




CORE REPORT - ASTM C-42

Client:	Volkert, Inc.	Order No.	E1171088
Project:	Bridge Over TVA Wilson Dam	Date Typed:	8-18-17
	Florence, AL	Date Drilled:	

Description of Pavement or Structure: Bridge Deck

Lab No.	6646	6647	6648	6649
Identification	Core 1	Core 2	Core 5	Core 6
Location of Core	Bridge Deck	Bridge Deck	Bridge Deck	Bridge Deck
Condition of Core				
Length of Core (Approx)	8.431	7.897	9.243	9.648
Thickness Required				
Depth of Reinforcement				
Type of Coarse Agg.	Limestone/Chert	Limestone/Chert	Limestone/Chert	Limestone/Chert
Mixture Used	N/A	N/A	N/A	N/A
Condition of Sub Soil	N/A	N/A	N/A	N/A
Date Concrete Placed	Unknown	Unknown	Unknown	Unknown
COMPRESSION TESTS	S			
Date Tested	8-17-17	8-17-17	8-17-17	8-17-17
Weight, Lbs.	7.10	6.55	7.70	8.15
Length of Core (in.)	7.152	7.102	7.121	7.525
Diameter of Core (in.)	3.681	3.686	3.700	3.695
Area of Core (sq.in.)	10.64	10.67	10.75	10.72
Capped Length (in.)	7.537	7.409	7.411	7.789
Ratio Length to Dia.	2.05	2.01	2.00	2.11
Correction Factor	None	None	None	None
Total Load, Lbs.	53,514	56,310	54,980	51,830
Uncorrected Strength (psi)	5,030	5,280	5,610	4,830
Corrected Strength (psi)	5,030	5,280	5,110	4,830
Type of Fracture	D	D	D	C

Remarks:



Respectfully submitted

Tim Goodall,


Laboratory Manager

 Terracon
 611 Lunken Park Drive
 Cincinnati, Ohio 45226

 P
 [513] 321 5816
 F
 [513] 321 0294
 www.terracon.com

nviroamental

Geotechnic



Appendix E Deck Drainage Calculations




DESIGN COMPUTATIONS

DAB Designer Date 9/28/2017 Sheet No. 1 of 2 Checker Date _Job No. 741400 Wilson Dan - Deck Drainage Analysis Description_ 16.25' Assume 1/2 of barrier = 9"-5.5'SW 4 10' LANE 10' LANE Roadway Section - Existing inlet spacing varies ... use 56' c/c spacing -> worst Case average So drainage area.... 16.25 × 56 = 910 SF Sidewalk -E Road Exist. Drain, Typ. Dech in Plan View Pesign Storm ... ALDOT Structural Design Manual Lo Specifies 10 year storm as design frequency Lo states that rainfall spread on bridge shall be limited to shoulder area during design storm. Not feesible since this structure has no shoulder. Use 1/2 lanc, or 5', for spread. FHWA 'Design of Bridge Deck Prainage' paline document: LA Section 9.2 -> assume to = 5 minutes 2, 50 Lio = 8.21 in/hr per NOAA idf curves Manning's N= 0.016 spread T=S' prot. Width Wp=16.25' (contributing width) rational runoff coeff. C = 0.9gutter cross slope Sx= 2%

VOLKERT

DESIGN COMPUTATIONS

Designer DAB Date 9/28/2017Sheet No. 2 of 2 Checker Date Job No. 741400 Description Vilson Dam - Deck Drainage Analysis
Constant inlet spacing $L_c = \frac{1312}{(n c i Wp)^{0.67}} S_x^{1.44} - \frac{2.11}{(n c i Wp)^{0.67}} = \frac{1312}{\left[(0.016)(0.9)(8.21)(16.25)\right]^{1.67}} (.02)^{1.44} (5.)^{2.11}$
$L_{c} = 90'$
Le=90' > existing spacing ~ 55'
is Existing spacing meets FHWA criteria for this formula.
* However, this formula does not take into consideration the flow capacity of the existing drainage intets. Manufacturer's detail
drawings and flow data could not be found for existing grates.



Appendix F Manufacturer Information



URETEK 486 STAR Polymer

Polyurethane Foam Grout | Technical Data Sheet | February 26, 2016

PRODUCT DESCRIPTION

URETEK 486 STAR is a two component high density expanding thermo set polyurethane resin system formulated for the under sealing, void filling & lifting of settled pavement, the stabilizing & stiffening of weak soils, and for the encapsulation & sealing of buried infrastructure. URETEK 486 STAR coupled with minimally invasive injection techniques achieves repairs without the necessity of excavation or demolition.

UNIQUE PROPERTIES

URETEK 486 STAR is capable of expanding 15 to 20 times its original starting volume in unconfined conditions. Fully cured URETEK 486 STAR material is inert and non-toxic. URETEK 486 STAR polymers are formulated in various densities and expansive coefficients for specific project applications. The low viscosity & lubricity of URETEK 486 STAR polymer allows for easy penetration into soils while compacting surrounding soils and displacing water without detrimental dilution or loss of dimensional stability to the resin system.

URETEK 486 STAR has a patented chemical composition that allows for direct application into water or very damp regions while still maintaining good physical properties. The patented chemical nature of URETEK 486 STAR goes beyond available hydrophobic technologies currently available. URETEK 486 STAR will form proper polyurethane linkages even while being injected directly into water. This property makes it ideal for lifting and stabilizing in areas with elevated soil moisture. Because of the monolithic and hydrophobic nature of URETEK 486 STAR the polyurethane grout will resist underground water erosion or weakening.

PROCESSING PARAMETERS

URETEK 486 STAR is a two component system that must be applied with a proportioning unit designed to allow 1 to 1, by volume, metering of materials. The proportioning equipment must be capable of maintaining recommended injection temperatures and pressures.

APPLICATIONS INCLUDE

Slab Jacking; Foundation Repair; Soil Stabilization; Void Filling; Pavement Lifting; Bridge Approach Stabilization and lifting; Pipe and Culvert Repair; Airfield Pavement Stabilization; Increasing the Load Bearing Capacity of Weak Soils

STORAGE AND HANDLING

URETEK 486 STAR components have a shelf life of 1 year when stored at 60 – 80°F out of direct sunlight and extreme humidity, >80% RH. URETEK 486 STAR "A" component is water sensitive and caution must be taken to ensure "A" component is not exposed to moisture. If the material remains in a receptacle be sure to tightly seal lid to minimize moisture exposure.

The "A" and "B" components should not be stored in temperatures less than 50°F for prolonged periods. Some phase separation in the "B" component may be noticed at these temperatures. If there is phase separation the material must be warmed and thoroughly mixed prior to use. Consult URETEK for proper warming and mixing guidelines. If the "A" component is allowed to crystallize or separate from exposure to cold temperatures, it is not useable and must be replaced.

SAFETY PRECAUTIONS

Appropriate literature has been assembled which provides information concerning the health and safety precautions that must be observed when handling URETEK 486 STAR components. Before working with these products, you must read and become familiar with the available information on their hazards, proper use, and handling. Information is available in several forms, e.g., material safety data sheets and product labels. Contact URETEK USA, Inc. at 1.888.287.3835.



URETEK 486 STAR Polymer

Polyurethane Foam Grout | Technical Data Sheet | February 26, 2016


TECHNICAL DATA

Physical Property	Test Method	486 3LB	486 4LB BD	486 4LB	486 4LB GD	486 6LB	486 8LB
Apparent Density. min	ASTM D 1622	3 lbs./cu. ft.	4 lbs./cu. ft.	4 lbs./cu. ft.	4 lbs./cu. ft.	6 lbs./cu. ft.	8 lbs./cu. ft.
Compressive Strength	ASTM D 1621	30 psi	60 psi	60 psi	60 psi	100 psi	175 psi
Compressive Modulus	ASTM D 1621	1700 psi	2000 psi	2000 psi	2000 psi	3000 psi	4000 psi
Dimensional Stability	ASTM D 2126						
-40°F		< 2% change	< 2% change	< 2% change	< 2% change	< 1% change	< 1% change
+200°F		< 2% change	< 2% change	< 2% change	< 2% change	< 1% change	< 1% change
Flexural Strength	ASTM D 790	50 psi	90 psi	90 psi	90 psi	170 psi	280 psi
Flexural Modulus	ASTM D 790	950 psi	2000 psi	2000 psi	2000 psi	4000 psi	7000 psi
Shear Strength	ASTM C 273	35 psi	45 psi	45 psi	45 psi	100 psi	100 psi
Sheer Modulus	ASTM C 273	500 psi	900 psi	900 psi	900 psi	1100 psi	1400 psi
Tensile Strength	ASTM D 1623	60 psi	90 psi	90 psi	90 psi	120 psi	150 psi
Tensile Modulus	ASTM D 1623	1700 psi	2000 psi	2000 psi	2000 psi	3000 psi	4000 psi
Elongation	ASTM D 1623	< 1%	< 1%	< 1%	< 1%	< 1%	< 1%
% Water Absorption	ASTM D 2842	< 2%	< 2%	< 2%	< 2%	< 2%	< 2%
Closed Cell Content	ASTM D 6226	90%	90%	90%	90%	90%	90%

Disclaimer: Physical properties generated under controlled laboratory conditions. Actual properties may vary under real world conditions. No warranty expressed or implied is given as individual results may vary.

CHEMICAL RESISTANCE

Chemical	Resistance	Chemical	Resistance	Chemical	Resistance	Chemical	Resistance
Water	Excellent	Isopropanol	Excellent	Orthodichlorobenzene	Excellent	Ethylene Glycol	Good
Gasoline	Excellent	Benzene	Excellent	Mineral Spirits	Excellent	Butylacetate	Good
Tolulene	Excellent	Benzene Chloride	Excellent	NaO ₂ – 25%	Excellent	Anylactetate	Good
Carbon Tetrachloride	Excellent	Kerosene	Excellent	HCL – 25%	Excellent	Varsol	Good
Brine Saturated	Excellent	Linseed Oil	Excellent	Butyrol	Excellent	Ammonium Hydroxide – Conc.	Good
Brine 10%	Excellent	Diesel Oil	Excellent	Xylene	Excellent	Methylene Chloride	Fair
Styrene	Excellent	Diisobutyl ketone	Excellent	Hexane	Excellent	Ethylacetate	Fair
Turpentine	Excellent	Potassium Hydroxide 1%	Excellent	Diisobutylene	Excellent	Acetone	Poor
JP-4 Fuel	Excellent	Ammonium Sulfate 2%	Excellent	Diluted Hydrochloric Acid	Good	Ethyl Alcohol	Poor
JP-5 Fuel	Excellent	Potassium Chloride 5%	Excellent	Formaldehyde	Good	Methyl Alcohol	Poor
Sulfuric Acid 10%	Excellent	Hydrogen Sulfide 100% Wet	Excellent	O. Chlorobenzene	Good	Sulfuric Acid Concentrate	Chemical Attack
Hydrochloric Acid 10%	Excellent	Hydrogen Sulfide 80% Wet	Excellent	Trichloroethylene	Good	Nitric Acid Concentrate	Chemical Attack
Sodium Hydroxide Concentrate	Excellent	Ammonium Hydroxide 10%	Excellent	Acetic Acid 2%	Good		
Sodium Hydroxide 10%	Excellent	Motor Oil	Excellent			•	



Appendix G Preliminary Estimated Quantities

TVA Wilson Dam Phase 1 Study Quantity Calculations

Total Length of Project:	2675.57 FT

<u>Arches</u>

Number of Arches Viewed:	5
Length per Viewed Arch:	55.5 FT
Total Length of Arch Viewed:	277.5 FT
Percent Viewed Arch:	10.37%

Estimated Repair Areas			
Length	Width	Area	
6	3	18	
40	3	120	
6	6	36	
6	6	36	
12	3	36	
	$\Sigma =$	246	SF

Ratio for Entire Project:	9.64
Total Repair Area:	2372 SF
Assumed Repair Depth:	0.5 FT
Concrete Volume:	1186 CF

Deck Cracks

Total Length Measured:	722 FT

Estimated Deck Cracks per Span				
90	80	70	80	
130	100			
70	80			
	960	LF		
Percent of	26 98%			

Percent of Project Measured:	26.98%
Ratio for Entire Project:	3.71
Length of Deck Cracks:	3557.5 LF
Repair Volume:	178 GAL - assumes 20LF per GAL

Stabilize Void Under Deck

see core sample data:

^ "	N/ 11/1 N	1
Core #	Void (in.)	
1	0.25	
2	0.25	
3	0.5	
4	0.125	
5	0.25	
6	0.125	
	0.25	<=average vo

Total Length:	2675.57 FT
Width of Slab:	20 FT
Volume of Void:	1115 CF
Conversion 1:	6 LBS/CF
Weight of Void Material:	6688.9 LBS
Conversion 2:	9 LBS/GAL
Void Repair Volume:	743 GAL

Full Depth Deck Repair

Total Length Measured:

726 FT

Est. Deck Repair in Measured Spans				
Length	Width	Area (SF)	Area (SY)	
4	4	16	1.78	
6	6	36	4.00	
18	2	36	4.00	
16	2	32	3.56	
2	2	4	0.44	
2	2	4	0.44	
10	4	40	4.44	
14	5	70	7.78	
4	2	8	0.89	
		$\Sigma =$	27.33	S١

Percent of Project Measured:	27.13%
Ratio for Entire Project:	3.69
Deck Repair Area:	100.7 SY

Sidewalk Patching

Total Length Measured:

726 FT

Estimated Concrete Patching Area in Measured Spans					
			· ·		
	Left Side		Right Side		
Length	Width	Area (SF)	Length	Width	Area (SF)
6	2	12	2	1	2
6	2	12	10	1	10
12	2	24	3	1	3
18	2	36	15	1	15
6	2	12	40	0.5	20
6	2	12	20	1	20
6	1	6	6	1	6
24	1	24	25	1	25
18	1	18	25	1	25
48	1	48			126
30	1	30			
12	1	12			
12	1	12			

Total Meaured Repair Area:	384 SF
Percent of Project Measured:	27.13%
Ratio for Entire Project:	3.69
Repair Areas:	1415.2 SF

258

Bridge Rail Patching


Total Length Measured:

726 FT

Estimated Bridge Rail Patching Area in Measured Spans					pans
Right Side			Left Side		
Length	Width	Area (SF)	Length	Width	Area (SF)
6	1	6	3	1	3
9	1	9	2	2.5	5
6	1	6	2	3	6
8	1	8	1	1	1
3	4	12	1	1	1
2	2	4	2	1	2
2	2	4	1	1	1
8	2	16	4	1	4
12	2	24	4	4	16
6	2	12			39
6	1	6			
2	2	4			
		111			

Total Meaured Repair Area:	150 SF
Percent of Project Measured:	27.13%
Ratio for Entire Project:	3.69
Repair Areas:	552.8 SF

<u>Hydrodemolition</u>		
Project Length:	2675.57	FT
Roadway Width:	20	FT
Hydrodemolition Area:	5946 \$	SY
Latex Modified Concrete (LMC) (<u>Dverlay</u>	
Project Length:	2675.57	FT
Roadway Width:	20	FT
Overlay Depth:	0.125	FT
Concrete Volume:	248 (CY
Deck Replacement		
Deck Length:	2675.57 I	FT
Deck Width:	20 I	FT
Deck Thickness:	0.75 I	FT
Deck Concrete:	1486 (CY
<u>Deck Removal</u>		
Deck Length:	2676 I	FT
Deck Width:	20	FT
Deck Area:	5946 \$	SY
Resetting Existing Joints		
Length of Joint:	20	FT
Number of Joints:	55	
Total Length of Joint:	1100	FT
Sealing Longitudinal Deck Joint		
Deck Length:	2675.57	FT
Runs of Sealant:	2	
Total Sealant Length:	5351.14 I	FT
Conversion:	75 I	LF/GAL
Total Sealant:	71.3 (GAL
Deck Reinforcement		
Assume #4 bars at 12" centers ea	ich way	
Length of Longitudinal Bar:	2675.57	FT
Number of Long. Bars:	20	
Increase for Splices:	5%	
Total Longitudinal Bar Length:	56187 I	FT
Length of Transverse Bar:	20	FT
Number of Transverse Bars:	2676	
Total Transverse Bar Length:	53520 I	FT
Total Reinforcement Length:	109707 I	FT
Bar Unit Weight:	0.668 I	LB/FT
Total Deck Reinforcement Wt:	73285 I	LB
Number of Dowels:	5350 <	<=assume #5 dowels at 12" centers on each sid
Length of Dowes:	2.5 I	FT
Total Length of Dowels:	13375 I	FT
Bar Unit Weight:	1.043 I	
Bar Unit Weight: Total Weight of Dowels:	1.043 13951	





Appendix D – Scoping Study Alternatives Scoring

This page intentionally left blank

Pating Critoria	Options						
Rating Criteria	А	В	С	D	E (do nothing)	F (hybrid)	7
Does the option fix the problem?	10	10	10	20	0	15	It is unclear if the urethane injection the material does not flow to. Con option with the lowest risk and wi
What is the expected longevity of the option?	10	10	10	18	0	15	Urethane stabilization is a newer t deck can be expected to last at 50
What are the Environmental impacts?	10	10	10	10	15	10	There are environmental challeng equally. The "do nothing" option still result in concrete from the un
What is the inconvenience to the public?	15	13	12	10	20	13	For this specific project, the option road closure. However, it was als have a longer expected service life entire service life was considered.
Does this option address the safety concerns of the plant and public?	5	10	15	15	0	15	The safety concerns considered we conditions, and sidewalk and hance
Totals	50	53	57	73	35	68	

5.1 Repair Scheme A

The first repair scheme considered seeks to provide a least-cost alternative to meet the minimum needs of the project. This scheme will:

- > Stabilize the bridge deck by pressure injecting Uretek polymer or an equivalent product into the "void" between the arch concrete and the existing concrete overlay.
- Repair existing deck cracks by epoxy injection.
- Perform spot full depth concrete deck repairs of the existing concrete overlay.
- Perform spot grinding of existing bridge deck to remove high spots for rideability.
- Patch deteriorated concrete arch faces.

5.2 Repair Scheme B

The second repair scheme provides the same deck repair technique as Repair Scheme A and adds the patching of the sidewalks and rails and retrofits the deck drainage. This scheme will:

- Stabilize the bridge deck by pressure injecting Uretek polymer or an equivalent product into the "void" between the arch concrete and the existing concrete overlay.
- > Repair existing deck cracks by epoxy injection.
- > Perform spot full depth concrete deck repairs of the existing concrete overlay.
- > Perform spot grinding of existing bridge deck to remove high spots for rideability.
- > Patch deteriorated concrete arch faces.
- > Patch deteriorated concrete surfaces of the rails and sidewalks.
- Provide retrofits to deck drainage.

Notes

ction will fully stabilize the deck, there may be areas that Complete removal and replacement of the deck is the will fully address the stability of the deck.

r technology, and it longevity is uncertain. A new concrete 50 years.

nges with each repair option, so they were weighted on E, provides the lowest environmental impact, but would underside of the deck falling into the river.

ions are ranked based on the presumed duration of the also discussed that the options with long closures, also life, and could have a lower impact to the public if the ed.

were the falling concrete into the river, the road ndrail condition.

5.3 Repair Scheme C

The third repair scheme is similar to Repair Scheme B except that it also provides a new latex modified concrete overlay and the accompanying joint modifications. This scheme will:

- Stabilize the bridge deck by pressure injecting Uretek polymer or an equivalent product into the "void" between the arch concrete and the existing concrete overlay.
- Repair existing deck cracks by epoxy injection.
- Perform spot full depth concrete deck repairs of the existing concrete overlay. >
- Patch deteriorated concrete arch faces. >
- Patch deteriorated concrete surfaces of the rails and sidewalks.
- Provide retrofits to deck drainage. >
- Install a new latex modified concrete overlay.
- Resetting existing expansion joints.

5.4 Repair Scheme D

The final repair scheme calls for a complete removal and replacement of the existing deck. This scheme would allow for removal of the "void" layer and provide the most certainty in the condition of the underlying arch material. This scheme will:

- Remove existing concrete bridge deck.
- Remove deteriorated material between arch and existing concrete bridge deck by hydrodemolition.
- Construct new reinforced concrete bridge deck.
- Reset existing bridge deck joints.
- Seal longitudinal construction joint between existing concrete curbs and new concrete deck.
- Patch deteriorated concrete arch faces.
- Patch deteriorated concrete surfaces of the rails and sidewalks. >
- Provide retrofits to deck drainage.

Appendix E – Wilson Dam Traffic Volume Data

This page intentionally left blank

Volkert, Inc.

302 Innovation Drive Suite 100 Franklin, TN 37067

Office 615.656.1845 Fax 615.656.1870

www.volkert.com

August 8, 2017

Mr. Jon C. Riley, ASLA, PMP Tennessee Valley Authority 1010 Reservation Road Complex D, OSW 112 Muscle Shoals, AL 35662

RE: Wilson Dam Traffic Volume Data

VOLKERT

Dear Mr. Riley:

This memorandum provides a summary of the traffic volume data collected along South Cox Creek Parkway at Wilson Dam in Florence, Alabama. The parameters for the data collection were as follows:

- Data was collected along South Cox Creek Parkway on the north side of Wilson dam, just south of the first intersection (local access roadway) (see figure below);
- Data was collected on Thursday, July 27th through Saturday, July 29th, 2017;
- Bi-directional average daily traffic (ADT) in 15-minute increments were collected.



Table 1 shows the ADT and Table 2 shows the peak hour periods for each of the three days of data collection.

Office Locations:

Birmingham, Foley, Mobile, Alabama • Gainesville, Orlando, Pensacola, Tampa, Florida • Atlanta, Georgia Collinsville, Illinois • Baton Rouge, New Orleans, Slidell, Louisiana • Biloxi, Mississippi • Jefferson City, Missouri Raleigh, North Carolina • Columbia, South Carolina • Chattanooga, Franklin, Tennessee • Alexandria, Virginia • Washington, D.C.



TABLE 1 AVERAGE DAILY TRAFFIC

DATE	ADT	NORTHBOUND	SOUTHBOUND
Thursday, July 27 th 2017	3,639	1,749	1,890
Friday, July 28 th , 2017	3,472	1,660	1,812
Saturday, July 29 th , 2017	3,492	1,626	1,866

TABLE 2PEAK HOUR TRAFFIC (BY DAY)

DATE	PEAK TOTAL	NORTHBOUND	SOUTHBOUND		
Thursday, July 27 th 2017					
7:15 - 8:15	240	69	171		
11:15 - 12:15	229	124	105		
15:30 - 16:30	358	232	126		
Friday, July 28th, 2017					
6:30 - 7:30	182	44	138		
11:00 - 12:00	218	122	96		
15:30 - 16:30	326	208	118		
Saturday, July 29 th , 2017					
7:45 – 8:45	138	77	61		
11:00 - 12:00	269	142	127		
15:15 - 16:15	291	132	159		

Additional traffic date collected included the vehicle classifications. Based on the various classified vehicles, Table 3 shows the percent breakdown.

TABLE 3 VEHICLE CLASSIFICATIONS (% ADT)

DATE	PASSENGER CARS/MOTORCYCLES	SINGLE UNIT/BUSES
Thursday, July 27 th 2017	72.7%	27.3%
Friday, July 28 th , 2017	71.4%	28.6%
Saturday, July 29 th , 2017	77.9%	22.1%

Should you have any questions or need additional information, please contact me.

Sincerely,

Gerald Bolden, PE, PTOE Traffic and ITS Manager

WILSON DAM TRAFFIC VOLUME DATA

Appendix F – Consultation Correspondence

This page intentionally left blank



ALABAMA HISTORICAL COMMISSION

468 South Perry Street Montgomery, Alabama 36130-0900 334-242-3184 / Fax: 334-240-3477

Lisa D. Jones Executive Director State Historic Preservation Officer

February 28, 2019

Edward W. Wells TVA 400 West Summit Hill Drive Knoxville, TN 37902

Re: AHC 19-0549 Rehabilitation of Wilson Bridge Lauderdale and Colbert Counties

Dear Mr. Wells:

Upon review of the above-referenced project forwarded by your office, we have determined that project activities will have no effect on any cultural resources listed on or eligible for the National Register of Historic Places. Therefore, we concur with the proposed project activities.

However, should artifacts or archaeological features be encountered during project activities, work shall cease and our office shall be consulted immediately. Artifacts are objects made, used or modified by humans. They include but are not excluded to arrowheads, broken pieces of pottery or glass, stone implements, metal fasteners or tools, etc. Archaeological features are stains in the soil that indicate disturbance by human activity. Some examples are post holes, building foundations, trash pits and even human burials. This stipulation shall be placed on the construction plans to insure contractors are aware of it.

We appreciate your commitment to helping us preserve Alabama's historic archaeological and architectural resources. Should you have any questions, please contact Amanda McBride at 334.230.2692 or Amanda.McBride@ahc.alabama.gov. Have the AHC tracking number referenced above available and include it with any future correspondence.

Sincerely,

Lee Anne Wofford Deputy State Historic Preservation Officer

LAW/EDS/amh



Tennessee Valley Authority, 400 West Summit Hill Drive, Knoxville, TN 37902

March 12, 2019

Ms. Cynthia Walton National Historic Landmarks Program Manager National Park Service 100 Alabama Street, SW 1924 Building Atlanta, Georgia 30303

Dear Ms. Walton:

TENNESSEE VALLEY AUTHORITY (TVA), REHABILITATION OF WILSON BRIDGE, LAUDERDALE AND COLBERT COUNTIES, ALABAMA (34.798017, -87.625152)

TVA proposes to repair and refurbish the Wilson Dam Bridge deck and other concrete surfaces. Wilson Dam is TVA's only National Historic Landmark (NHL). For the purpose of this review, the limit of the repairs would include the concrete arches on the dam above the spring line; and bridge deck, curbs, parapets, and sidewalks between the control building and the beginning of the main bridge over the lock (Figure 1). The dam below the spring line, the equipment operating deck on the upstream side of the bridge, and the steel lock viaduct area are outside of the scope of work of this project.

Construction of Wilson Dam began in 1918 and ended in 1926. When the dam was dedicated in 1926, a primary roadway was opened between Muscle Shoals and Florence, Alabama crossing the Tennessee River over the top of the dam and the original lock. In May 1933, TVA acquired the dam from the U.S. Army Corps of Engineers (USACE). TVA owns Wilson Dam and the USACE Nashville District operates the Wilson Dam locks for TVA. In 1966, Wilson Dam was designated a NHL by the U. S. Department of the Interior (DOI), and was listed in the National Register of Historic Places (NRHP). The NHL was certified in 1977 (Rettig and Sheely 1976).

The original wearing surface of the bridge was comprised of brick pavers, which were removed in the late 1950s and replaced with a concrete deck when the additional steel superstructure viaduct was constructed over the lock. The arch appears to be constructed of mass unreinforced concrete. The bridge deck also appears to be unreinforced (Figure 2).

Over the years, the downstream face where the concrete arches interface with the parapet have developed widespread spalls with efflorescence and visible water movement. In addition, the sidewalk, curb, and deck have developed widespread cracking (Figures 3-5). The purpose of the proposed action is to refurbish and repair the Wilson Dam Bridge deck and other concrete surfaces, in order to stop the flow of water through the deck and parapets and to remove and replace deteriorated concrete on the arch faces. If the bridge is left unrepaired, deterioration of keyways and the arch may progress over time, and increase the potential for falling debris.

Ms. Cynthia Walton Page 2 March 12, 2019

TVA finds that the proposed improvements constitute an undertaking (as defined at 36 CFR § 800.16(y)) that has the potential to cause effects to historic properties. We are initiating consultation under Section 106 of the National Historic Preservation Act for this undertaking.

TVA defined the area of potential effects (APE) to be the following: the boundary of the Wilson Dam NHL (which includes the foundation lines of Wilson Dam, including the power house and the old and new locks); the planned lay down area within the lock operation area on the north shore of the Tennessee River; and any historic properties within 0.5 mi and direct line of sight of Wilson Dam. Given the scale and scope of the project and limited view beyond the bridge itself, the APE accounts for both direct and indirect/visual effects.

The direct APE is limited to the concrete arches on the dam above the spring line; the bridge deck, curbs, parapets, and sidewalks between the control building and the beginning of the main bridge over the lock; and an approximately 1.6 acre staging area located within the lock operations area (see Figure 1). The surface of the staging area is graveled and fenced in from when used as part of the Wilson Dam Bascule Bridge Replacement project (Figures 6-7). Pietak (2002:2) investigated the APE as part of Tract I in a Cultural Resources survey of the Muscle Shoals Reservation. No archaeological sites were discovered, and no additional work was recommended. Thus, TVA finds that the proposed bridge rehabilitation will have no effect on archaeological resources.

None of the identified resources in the Alabama Register of Landmarks and Heritage web map have direct line of sight to Wilson Dam. The nearest identified resource, the c. 1870 Norfolk-Southern Railroad Bridge, is located approximately 2.69 mi west-southwest of Wilson Dam and does not have a direct line of sight. NRHP data available through the National Park Service (NPS) indicates the only historic property within 1.25 mi of Wilson Dam is Florence Wagon Works Site, listed in the NRHP by TVA in 1996. The site is not within direct line of sight. TVA records indicate additional NRHP-eligible resources associated with TVA's Muscle Shoals Reservation (including, but not limited to the Power Service Building and CCC Pavilion) are also not located within direct line of sight. Thus, TVA finds that the only historic property within the APE is the Wilson Dam NHL.

TVA contracted with Volkert to assess the bridge and then develop a design for the project. The 100% design plans for the bridge rehabilitation are enclosed with this letter. The proposed plan is based on the information provided in the plans as well as a subsequent site visit.

As seen in the plans, TVA intends to rehabilitate the bridge, acknowledging the need to alter or add to a historic resource in order to provide continuing use while retaining the property's historic character. Rehabilitation of the bridge will ensure a vital connection between Florence and Muscle Shoals will remain across the dam, safety will be ensured, and the character-defining features of the bridge will be retained. In keeping with the Secretary of the Interior's Standards for rehabilitation:

- a) the bridge will retain its historic purpose;
- b) the character-defining features of the bridge will be retained;

Ms. Cynthia Walton Page 3 March 12, 2019

- c) distinctive features, finishes, and construction techniques or examples of craftsmanship that characterize the bridge will be preserved;
- d) deteriorated historic features will be repaired rather than replaced or new features will match the old in design, color, texture, and other visual qualities, and where possible, materials; and
- e) alterations will not destroy historic materials that characterize the property and new work will be differentiated from the old with compatible massing, size, scale, and architectural features to protect the historic integrity of the property and its environment.

Specifically, existing curbs, deck drain plates, and light fixtures within the bridge will be removed, retained, and reinstalled as a part of the project (Figures 8-11). Repair of any damaged lights is not a part of this project however, the damaged lights or those that are missing globes will be reinstalled for potential future repair or restoration. In places were curbs are missing, in-kind replacements will be installed. Additionally, any concrete or paint applied textural finishes will be matched to Wilson Dam's current appearance. Furthermore, as the plans specify, the contractor will take special care to protect any parts of the structure that are not to be removed specifically and the contractor is not allowed to use a hydraulic ram on a backhoe, mini excavator, or other equipment for concrete removal on portions of the structure to remain in service.

Given that the design of the rehabilitation of the bridge is keeping with the Secretary of the Interior's Standards for Rehabilitation, it is unlikely that the rehabilitation of the bridge over Wilson Dam will diminish the integrity of the c. 1918 NHL. Thus, TVA finds that the proposed project will have no adverse effect to historic properties.

In the letter dated February 28, 2019 (enclosed), the Alabama State Historic Preservation Office concurred with TVA that the proposed rehabilitation would not have an adverse effect on Wilson Dam and concurred with the project proceeding.

Pursuant to 36 CFR § 800.10(c), TVA is notifying the Secretary of consultation involving the NHL Wilson Dam.

Should you have any questions or comments, please contact Hallie Hearnes in Knoxville by email, <u>hahearnes@tva.gov</u> or by phone, (865) 632-3463.

Sincerely,

Clinton E. Jones Manager Cultural Compliance

HAH:ABM Enclosures

REFERENCES CITED


Pietak, Lynn Marie, Aaron Deter-Wolf, Ruth Nichols, Jim D'Angelo, and Kristin Wilson

2002 Cultural Resources Survey for the Muscle Shoals Reservation, Lauderdale and Colbert Counties, Alabama. Submitted to the Tennessee Valley Authority by TRC, Atlanta, Georgia.

Rettig, Polly M. and Horace J. Sheely, Jr.

1976 Wilson Dam, National Register of Historic Places Inventory – Nomination Form, United States Department of the Interior, National Park Service, Washington, D.C. INTERNAL COPIES NOT TO BE INCLUDED WITH OUTGOING LETTER:

Lana D. Bean, WT 10 C-K David L. Bowling, WT 11B-K Benjamin E. Byard, BR 1C-C Jon Day, PSC 1F-M Michael C. Easley, BR 2C-C Patricia B. Ezzell, WT 7C-K David B. Forster, WT 11A-K Hallie A. Hearnes, WT 11-B Susan R. Jacks, WT 11-B Susan R. Jacks, WT 11C-K Paul J. Pearman, BR 2C-C Ashley A. Pilakowski, WT 11-B M. Susan Smelley, BR 2C-C Lori A. Whitehorse, WT 11-B ECM, WT CA-K



Wilson Dam Rehabilitation

Source: TVA, ESRI, NPS, USGS

Author: Jacob Wall, TVA 1/23/2019

Figure 1. Aerial image and topographic quadrangle showing the APE and Wilson Dam NHL.



Figure 2. Overview of the deck of Wilson Bridge, facing north, toward Florence, AL.



Figure 3. Longitudinal deck crack.



Figure 4. Downstream face of the dam and bridge from the lock wall.



Figure 5. Typical spalling at parapet concrete arch interface



Figure 6. Overview of the access gate to the existing staging area.



Figure 7. Overview of the existing stage area, facing south to the Tennessee River/Pickwick Reservoir.



Figure 8. Historic light fixture on the interior of the bridge railing to be removed and reinstalled.



Figure 9. Damaged historic light fixture on the interior of the bridge railing to be removed and reinstalled.



Figure 10. Historic desk drain at the base of the curb at its intersection with the deck.



Figure 11. Previous repair flanked by existing steel at curb; sections like this will be repaired to feature new steel curb that matches the profile of the existing curb.



Tennessee Valley Authority, 400 West Summit Hill Drive, Knoxville, TN 37902

April 22, 2019

Ms. Lee Anne Wofford Deputy State Historic Preservation Officer Alabama Historical Commission 468 South Perry Street Montgomery, Alabama 36730-0900

Dear Ms. Wofford:

TENNESSEE VALLEY AUTHORITY (TVA), REHABILITATION OF WILSON BRIDGE (AHC 19-0549), LAUDERDALE AND COLBERT COUNTIES, ALABAMA (34.798017, -87.625152)

TVA previously consulted on the rehabilitation of Wilson Bridge (AHC 19-0549). We received concurrence on our finding of no adverse effect to historic properties.

Since the completion of previous consultation, TVA proposes to add additional actions to the project while the bridge is closed for rehabilitation. The bridge fly-over that crosses over the locks, and is adjacent to the dam consists of 30 steel spans (Figures 1 and 2). The epoxy overlay with flint aggregate wearing surface on the fly-over was installed in the 1980s, but is showing signs of wear and tear in areas where the epoxy overlay has been worn down or completely disappeared (Figure 3). In addition, expansion joints on the fly-over installed in the 1950s are deteriorating and the handrails need repainting. To address deterioration, TVA proposes to expand the previous project to include resealing of the fly-over epoxy overlay, removal and replacement of the fly-over expansion joints, and recoating/repainting of the fly-over handrails.

As a part of the process to replace the epoxy overlay with a flint aggregate wearing surface on the fly-over, a small surface preparation milling machine would scarify the surface; the surface would be pressure washed; and then the epoxy would be applied using a trailer mounted mixer/applicator. To replace the six expansion joints, a cut would be made in the concrete a few inches behind the joint and then the joint would be chipped out with small pneumatic hammers. A replacement joint would be set from the bottom, and concrete would be poured around the new joint. To remove the paint/coating on the handrails, an abrasive pressure wash would be used. This process has been used previously to remove paint on the handrails and has not caused harm to the handrails.

TVA finds that the proposed improvements constitute an undertaking (as defined at 36 CFR § 800.16(y)) that has the potential to cause effects to historic properties. We are initiating consultation under Section 106 of the National Historic Preservation Act for this undertaking.

Ms. Lee Anne Wofford Page 2 April 22, 2019

TVA defined the area of potential effects (APE) to be the following: the boundary of the Wilson Dam National Historic Landmark (NHL) - which includes the foundation lines of Wilson Dam, including the power house and the old and new locks; the planned lay down area within the lock operation area on the north shore of the Tennessee River; and any historic properties within 0.5 mi and direct line of sight of Wilson Dam (see Figure 1). The expanded direct APE includes the handrails, expansion joints, and deck of the fly-over portion of the bridge. APE for archaeology has not changed from the original scope, thus this consultation is in regards to historic archaeological resources.

Construction of Wilson Dam began in 1918 and ended in 1926. When the dam was dedicated in 1926, a primary roadway was opened between Muscle Shoals and Florence, Alabama crossing the Tennessee River over the top of the dam and the original lock. In May 1933, TVA acquired the dam from the U.S. Army Corps of Engineers (USACE). TVA owns Wilson Dam and the USACE Nashville District operates the Wilson Dam locks for TVA. In 1966, Wilson Dam was designated a NHL by the U. S. Department of the Interior (DOI) and listed in the National Register of Historic Places (NRHP) (Rettig and Sheely 1976). The NHL was certified in 1977.

None of the identified resources in the Alabama Register of Landmarks and Heritage web map have direct line of sight to Wilson Dam. The nearest identified resource, the c. 1870 Norfolk-Southern Railroad Bridge, is located approximately 2.69 miles west-southwest of Wilson Dam, and does not have a direct line of sight. NRHP data available through the National Park Service indicates the only historic property within 1.25 miles of Wilson Dam is Florence Wagon Works Site listed in the NRHP by TVA in 1996. The site is not within direct line of sight. TVA records indicate additional NRHP-eligible resources associated with TVA's Muscle Shoals Reservation including, but not limited to the Power Service Building and CCC Pavilion are also not located within direct line of sight. Thus, TVA finds that the only historic property within the APE is the Wilson Dam NHL.

Any concrete or paint applied textural finishes would be matched to Wilson Dam's current appearance. Furthermore as the plans specify, the contractor would take special care to protect any parts of the structure that are not to be removed specifically, and the contractor is not allowed to use a hydraulic ram on a backhoe, mini excavator, or other equipment for concrete removal on portions of the structure to remain in service.

Given that the original project and expanded scope (handrails, epoxy overlay, and expansion joints) is keeping with the *Secretary of the Interior's Standards for Rehabilitation*, it is unlikely that the additional actions related to the rehabilitation of the fly-over portion of the bridge at Wilson Dam will diminish the integrity of the c. 1918-1926 NHL. Thus, TVA finds that the proposed project will have no adverse effect to historic properties.

Pursuant to 36 CFR 800.5(b), we are seeking your concurrence with TVA's finding that there will be no adverse effect to historic properties as a result of the proposed undertaking.

Ms. Lee Anne Wofford Page 3 April 22, 2019

Should you have any questions or comments, please contact Hallie Hearnes in Knoxville by email, <u>hahearnes@tva.gov</u> or by phone, (865) 632-3463.

Sincerely,

Edward W. Welle

Edward W. Wells on Behalf of Clinton E. Jones Manager Cultural Compliance


HAH:ABM Enclosures

REFERENCES CITED

Rettig, Polly M. and Horace J. Sheely, Jr.

1976 Wilson Dam, National Register of Historic Places Inventory – Nomination Form, United States Department of the Interior, National Park Service, Washington, D.C. INTERNAL COPIES NOT TO BE INCLUDED WITH OUTGOING LETTER:

Lana D. Bean, WT 10 C-K David L. Bowling, WT 11B-K Benjamin E. Byard, BR 1C-C Jon Day, PSC 1F-M Michael C. Easley, BR 4A-C Patricia B. Ezzell, WT 7C-K David B. Forster, WT 11A-K Hallie A. Hearnes, WT 11-B Susan R. Jacks, WT 11-B Susan R. Jacks, WT 11C-K Paul J. Pearman, MR 4G-C Ashley A. Pilakowski, WT 11-B M. Susan Smelley, BR 4A-C Elizabeth Smith, WT 11B-K Lori A. Whitehorse, WT 11-B ECM, WT CA-K



Wilson Dam Rehabilitation

Source: TVA, ESRI, NPS, USGS

Author: Jacob Wall, TVA 4/18/2019

Figure 1. Aerial image and topographic quadrangle showing the APE and Wilson Dam NHL.




Figure 2. Overview of Wilson Dam highlighting for fly-over portion of the bridge (shoalstrac.com).



Figure 3. Overview of deterioration of epoxy overlay and the coatings on the handrails (werunracephotos.com).