


Groundwater Monitoring: Colbert Fossil Plant

Ensuring the protection of water resources

Why We Monitor

As part of our commitment to environmental stewardship and in compliance with state and federal regulations, TVA continues to monitor the groundwater quality at the site to ensure water resources are not impacted by our coal ash management units. This fact sheet summarizes TVA's robust monitoring network program and provides the most recent monitoring results reported under federal regulations.



How We Monitor

We maintain a robust network of monitoring wells that we sample regularly for groundwater quality. Many of the constituents in coal ash are naturally occurring in rocks and soil, which makes it important to understand groundwater quality before it reaches the site. That's why we typically install monitoring wells both before and after groundwater reaches the site. We proactively report the results to regulators and post the results on the TVA website.





Image shown is a rendering, well locations are approximate.



2022

Selenium

Thallium

0.05

0.002

Results of Assessment Monitoring for 2022*

2022		GROUNDWATER QUALITY MONITORING WELL LOCATIONS											
		Background Wells			CCR Monitoring Wells								
Constituent	GWPS mg/L	CA5	CA6	COF- 116BR	COF- 102	COF- 104	COF- 105	COF- 108	COF- 111	MC4	MC5A	CA17B	CA30B
Antimony	0.006			•	•	•	•	•	•			•	•
Arsenic	0.01	•		•	•	•		•	•			•	•
Barium	2	•	•	•	•	•	•	•	•	•	•	•	•
Beryllium	0.004	•	•	•	•	•		•	•	•	•	•	•
Cadmium	0.005	•	•	•	•		•	•	•	•	•	•	•
Chromium	0.1	•	•	•	•	•		•	•	•	•	•	•
Cobalt	0.006	•	•	•	•	•		•	•	•	•	•	•
Fluoride	4	•	•	•	•	•	•	•	•	•	•	•	•
Lead	0.015	•	•	•	•		•	•	•	•	•	•	•
Lithium	0.04	•	•	•	•	•		•		•		•	•
Mercury	0.002	•	•	•	•		•	•		•		•	•
Molybdenum	0.1	•	•	•	•		•	•	•	•	•	•	•
Rad226+228	5 pCi/L	•	•	•	•	•		•		•			•
Selenium	0.05	•	•	•	•	•		•	•	•	•	•	•
Thallium	0.002	•	•	•	•	•		•	•	•		•	•

2022	CCR Monitoring Wells									
Constituent	GWPS mg/L	MC1	MC5C	COF- 111BR	COF- 112BR	COF- 113BR	COF- 114BR			
Antimony	0.006						•			
Arsenic	0.01		•				•			
Barium	2		•				•			
Beryllium	0.004	•	•	•	•	•	•			
Cadmium	0.005		•				•			
Chromium	0.1	•	•				•			
Cobalt	0.006	•	•				•			
Fluoride	4	•	•	•		•	•			
Lead	0.015	•	•			•	•			
Lithium	0.0696	•	•				•			
Mercury	0.002	•	•	•	•	•	•			
Molybdenum	0.1	•	•		•		•			
Rad226+228	5 pCi/L	•		•		•	•			
		_					_			

GROUNDWATER QUALITY MONITORING WELL LOCATIONS


Color Coding Key

- Monitoring data results are below groundwater protection standards (GWPS)
- Monitoring data results exceed GWPS (TVA completed assessment of corrective measures report)
- * The results shown here are representative of the results in the Semiannual Report submitted on January 13, 2023 and the Annual Groundwater Monitoring and Corrective Action Report submitted on January 31, 2023 and may not be the most recent documented result.



Monitoring and Remedy Process Under Federal Regulations

Below are the steps that TVA takes to understand groundwater conditions and resolve any issues that are detected as a part of our robust monitoring.



Should action be required to address an issue, the public is notified and corrective measures are taken. As the issue is resolved, monitoring continues. This is a cycle that continues as part of our robust monitoring program.

Next Steps

TVA will continue to monitor and assess groundwater testing results and take the steps necessary to preserve and protect the quality of the environment and surrounding community.

TVA will not waver from our commitment to protecting water resources.